



REPUBLIC OF THE PHILIPPINES

NATIONAL DISASTER COORDINATING COUNCIL

National Disaster Management Center, Camp Gen. Emilio Aguinaldo, Quezon City, Philippines

NDCC UPDATE

Initial Report on Landslide and Flashflood Incident at Koronadal City and South Cotabato

Releasing Officer

for: Ramos

BENITO T RAMOS
Administrator, OCD and
Executive Officer, NDCC

DATE : September 11, 2010

Source: CDCC Koronadal City, PDCC South Cotabato and OCDRC XII

I. SITUATION OVERVIEW

- ❖ On September 10, 2010 at around 6:00 PM a landslide and flashflood incident occurred due to heavy rainfall at Sitio Acub, Brgy. San Isidro and Brgy. Carpenter Hill, Koronadal City and Purok 9-A, Purok 1 Brgy. Poblacion and Sitio Tucalabong Crossing Rubber of Tupi, South Cotabato.
- ❖ Casualties/Damages of the said incident were identified as follows:

Incident	Area	Families	Persons	Casualties	Houses Damaged
Landslide	Sito, Acub Brgy. San Isidro, Koronadal City			(1)dead (6)injured (4) missing	
Flashflood	Purok 9-A and Purok 1, Brgy. Poblacion, Tupi South Cotabato	2	10	(1) injured	(2) partially
Flashflood	Sitio Tucalabong, Crossing Rubber, Tupi South Cotabato	40	200		(4) Totally
TOTAL		42	210	(1) dead, (7) injured and (4) missing	(2) partially (4) Totally

II. ACTIONS TAKEN

- ❖ Immediate response was done by PDRRMC South Cotabato and CDRRMC Koronadal in transporting injured victims.
- ❖ PDRRMC South Cotabato and CDRRMC Koronadal conducted immediate search, rescue and retrieval operation for missing individuals.

- ❖ OCD XII, PDRPMC South Cotabato and CDRPMC Koronadal immediately conducted ocular inspection at the flashflood and landslide area.
- ❖ PDRPMC South Cotabato provided medical services and hot meals to all injured victims.
- ❖ Rescue and retrieval operations are on going by PDRPMC South Cotabato and CDRPMC Koronadal with SAR Team.
- ❖ CDO Dorado, Chief, Operations, OCD XII conducted ocular survey of the affected areas.
- ❖ Duty OCD personnel coordinated to OCDRC XII regarding on the specific names of the casualties mentioned above for proper identification. Progress report to follow.