



REPUBLIC OF THE PHILIPPINES
NATIONAL DISASTER RISK REDUCTION AND MANAGEMENT COUNCIL

National Disaster Risk Reduction and Management Center, Camp Aguinaldo, Quezon City, Philippines

NDRRMC UPDATE

Incident Monitored Covering the Period of
091700H – 100800H February 2016

Releasing Officer:

amb
USEC ALEXANDER P PAMA
Executive Director, NDRRMC and
Administrator, OCD

DATE : 10 February 2016

Source: OCDRO IV-B (MIMAROPA)

1. Initial Report re Flooding Incident in Oriental Mindoro (Region IV-B)

A. Situation Overview:

1. Around 4:30 PM, 9 February 2016, a flooding incident transpired in five (5) barangays in Baco and thirteen (13) barangays in Naujan both in Oriental Mindoro due to the continuous rain experienced in the province.

B. Effects:

1. A total of 23 families / 72 persons from Brgy Masagana, Naujan, Oriental Mindoro evacuated to higher grounds in the same barangay.
2. Flooded areas are as follows:

Province/ Municipality	Flooded Areas	Remarks
Baco, Oriental Mindoro	Brgy. Mangangani	approximately 2ft
	Brgy. Bayanan	approximately 2ft
	Brgy. Baras	approximately 2ft
	Brgy. Catuwiran	approximately 3ft
	Brgy. Malapad	approximately 3ft
Naujan, Oriental Mindoro	Brgy. Metolza	approximately 2ft
	Brgy. Arangin	approximately 1.5ft
	Brgy. Masagana	approximately 3ft
	Brgy. Evangelista	approximately 2.5ft
	Brgy. Gen. Esco	approximately 1.5ft
	Brgy. San Luis	approximately 2.5ft
	Brgy. Mahabang Parang	approximately 3ft
	Brgy. Tagumpay	approximately 3ft
	Brgy. San Andres	approximately 3ft
	Brgy. Malvar	approximately 3ft
	Brgy. Balite	approximately 2ft
	Brgy. San Nicolas	approximately 2ft
	Brgy. Inarawan	approximately 2ft

3. The following roads were rendered not passable:

Municipality/ Province	Roads	Remarks
Baco, Oriental Mindoro	Dalig Road (Brgy. Tagumpay – Brgy. Bangkatan	Not passable to light vehicles
	Brgy. Malapad Road	Not passable to light vehicles
	Brgy. Catuwiran I Road	Not passable to light vehicles
Naujan, Oriental Mindoro	Brgy. Metolza Road	Not passable to light vehicles
	Brgy. Arangin Road	Not passable to light vehicles
	Brgy. Masagana Road	Not passable to light vehicles
	Brgy. Evangelista Road (Aurora-Evangelista)	Not passable to all types of vehicles
	Brgy. Gen. Esco Road	Not passable to all types of vehicles due to washed out spillway
	Brgy. San Luis Road	Not passable to light vehicles due to washed out spillway
	Brgy. Mahabang Parang Road	Not passable to all types of vehicles
	Brgy. Tagumpay Road	Not passable to all types of vehicles
	Brgy. San Andres Road	Not passable to all types of vehicles
	Brgy. Malvar Road	Not passable to all types of vehicles
	Brgy. Balite Road	Not passable to all types of vehicles
	Brgy. Inarawan Road	Not passable to light vehicles

C. Actions Taken:

1. MDRRMC Baco, Oriental Mindoro coordinated the evacuation efforts and monitored the flooding incidents in its AOR.
2. MDRRMC Naujan, Oriental Mindoro coordinated the evacuation efforts and monitored the flooding incidents in its AOR and distributed relief goods to the affected population.
3. OCD MIMAROPA coordinated with PDRRMC Oriental Mindoro regarding the incident.