




## **NDRRMC UPDATE**

**Incident Monitored Covering the Period of**  
**180800H – 181700H September 2016**

**Releasing Officer:**

  
**USEC RICARDO B. JALAD**  
Executive Director, NDRRMC and  
Administrator, OCD

**DATE : 18 September 2016, 8:00 AM**

*Sources: OCDRO X*

### **1. Progress/Final Report re Landslide Incurred by Blasting (Road Widening) at Sitio Damay, Brgy. San Vicente, Sumilao, Bukidnon**

#### **A. Situation Overview:**

- At around 5:30 PM on September 17, 2016, a landslide induced by blasting occurred in the National Highway along Bukidnon-Davao Route, Sitio Damay, Brgy. San Vicente, Sumilao, Bukidnon.

#### **B. Effects:**

- Debris covered an estimated 80 meters length/portion of the National Highway
- Damage portion of the Bukidnon-Davao Route (National Highway) is not passable to any vehicles of this report.
- Vehicles coming from and going to Davao are temporarily stranded due to traffic obstruction in the affected area
- No report of casualty.

#### **C. Actions Taken:**

- Ongoing cleaning operations by the DPWH 1st District Engineering Office.
- Engr. Virgie nayve, Chief Construction Division immediately instructed the contractor Equiparco to clear the road pavement of slides using their equipment which are on standby at the project site.