



REPUBLIC OF THE PHILIPPINES
NATIONAL DISASTER RISK REDUCTION AND MANAGEMENT COUNCIL

National Disaster Risk Reduction and Management Center, Camp Aguinaldo, Quezon City, Philippines

National Disaster Risk Reduction and Management Council

INCIDENTS MONITORED

Progress Report No. 2 for the Effects of Southwest Monsoon in Davao Region (Region XI)

DATE OF INCIDENT	June 29, 2025
TIME OF INCIDENT	02:47 pm
DATE ISSUED	July 08, 2025
TIME ISSUED	10:30 am
OVERVIEW	<p>On or about 7:00pm, 28 June 2025, a flashflood occurred in Brgy. Katipunan, Nabunturan, Davao de Oro due to heavy rains caused by Southwest Monsoon affecting Davao Region.</p> <p>On or about 2:47pm, 29 June 2025, a landslide incident occurred in Sitio Tandik, Brgy. Katipunan, Maragusan, Davao de Oro. While on or about 5:00pm of the same date, a flashflood incident occurred in Barangays Panoraon and Mainit, Maco, Davao de Oro due to moderate to heavy rains caused still caused by Southwest Monsoon.</p> <p>On 1 and 2 July 2025, landslides occurred in Barangays Tubaon and Cabagayan, respectively, due to several days of occasional heavy rainfall brought by the Southwest Monsoon affecting Tarragona, Davao Oriental.</p> <p>On or about 3:30 AM on 6 July 2025, flooding was reported in Barangays Nangan and Pundaguitan, Governor Generoso, Davao Oriental. On the same day, at 5:00 am, a mudslide incident occurred in Brangay Saladoc, Don Marcelino, Davao Occidental caused by moderate to heavy rains associated with the Southwest Monsoon.</p>

RELATED INCIDENTS

The following incidents were reported in some areas of DAVAO DE ORO, DAVAO OCCIDENTAL.

PROVINCE	Flooded Areas			Tornado/Destructive Winds/Strong Winds	Fallen Debris
	Flooded	Subsided	Receding		
Total	0	4	0	1	1
DAVAO DE ORO	0	3	0	0	0
DAVAO OCCIDENTAL	0	1	0	1	1

AFFECTED POPULATION

A total of 538 families or 2,131 persons were affected. Of which, 0 families or 0 persons were served inside 0 ECs and 0 families or 0 persons were served outside ECs:

Affected Provinces	AFFECTED			INSIDE ECs			OUTSIDE ECs	
	Brgy	Families	Persons	No. of ECs	Families	Persons	Families	Persons
TOTAL	7	538	2,131	0	0	0	0	0
DAVAO DE ORO	2	264	774	0	0	0	0	0
DAVAO ORIENTAL	5	274	1,357	0	0	0	0	0

ROADS AND BRIDGES

A total of 7 road sections and 0 bridges were affected. Below is the current status of affected road sections and bridges:

	NOT PASSABLE		PASSABLE (previously reported as not passable and/or one lane passable)	
	ROADS	BRIDGES	ROADS	BRIDGES
GRAND TOTAL	0	0	7	0
DAVAO DE ORO	0	0	5	0
DAVAO OCCIDENTAL	0	0	2	0

POWER

A total of 1 cities/municipalities were affected. Below is the current status of power supply:

PROVINCE	NO. OF CITIES/ MUNICIPALITIES	
	INTERRUPTED	RESTORED
GRAND TOTAL	0	1
DAVAO OCCIDENTAL	0	1

WATER SUPPLY

A total of 1 cities/municipalities were affected. Below is the current status of water supply:

PROVINCE	NO. OF CITIES/ MUNICIPALITIES	
	INTERRUPTED	RESTORED
GRAND TOTAL	1	0
DAVAO DE ORO	1	0

DAMAGE TO INFRASTRUCTURE

The estimated cost of damage to infrastructure amounting to Php 0 was reported in DAVAO ORIENTAL.

PROVINCE	NUMBER OF DAMAGED INFRASTRUCTURE	COST OF DAMAGE (PHP)
GRAND TOTAL	1	0

DAVAO ORIENTAL	1	0
----------------	---	---

Related Incidents

REGION PROVINCE CITY/ MUNICIPALITY BARANGAY		TYPE OF INCIDENT	DATE OF OCCURENCE	TIME OF OCCURENCE	DESCRIPTION	ACTIONS TAKEN	REMARKS	STATUS (for flooded areas)
GRAND TOTAL	6							
REGION 11	6							
DAVAO DE ORO	3							
Nabunturan	1							
Katipunan		Flooded Areas	28 June 2025	07:00 pm	-Eroded culvert at Purok 3 Sitio Apogon particularly in the Pacatang Area -Eroded culvert at Purok 3 Katipunan particularly at Baranda area and an unsafe road at Purok 6 to 3 due to its roughness.	Conducted ocular inspection.	For repair	Subsided
Maco	2							
Mainit		Flooded Areas	29 June 2025	05:30 pm	River flood	Close monitoring to the incident and conducted debris clearing operations in coordination with APEX Mining		Subsided
Panoraon		Flooded Areas	29 June 2025	05:30 pm	River flood	Close monitoring to the incident and conducted debris clearing operations by ASIAN ALLIANCE and PEO		Subsided
DAVAO OCCIDENTAL	3							
Don Marcelino	3							
Kinanga		Flooded Areas	28 June 2025	10:00 pm	Floodwaters had entered the houses causing significant damage to their properties and personal belongings.			Subsided
Mabuhay		Tornado/Destructive Winds/Strong Winds	28 June 2025	10:00 pm	Due to strong winds and heavy rains, their house was damaged—the roof and the walls of the house were destroyed.		Ongoing validation on the damaged house.	
Kinanga		Fallen Debris	28 June 2025	10:00 pm	Two (2) households reported partially damaged part of the house due to a fallen coconut tree.		Ongoing validation on the damaged house.	

REGION PROVINCE CITY/ MUNICIPALITY BARANGAY		TYPE OF INCIDENT	DATE OF OCCURENCE	TIME OF OCCURENCE	DESCRIPTION	ACTIONS TAKEN	REMARKS	STATUS (for flooded areas)
---	--	------------------	-------------------	-------------------	-------------	---------------	---------	----------------------------

Affected Population

REGION PROVINCE CITY/ MUNICIPALITY BARANGAY		NO. OF AFFECTED			No. of ECs		Inside Evacuation Centers				Outside Evacuation Centers				TOTAL SERVED			
															(Inside + Outside)			
		Brgys.	Families	Persons			Families		Persons		Families		Persons		Families		Persons	
					CUM	NOW	CUM	NOW	CUM	NOW	CUM	NOW	CUM	NOW	CUM	NOW		
GRAND TOTAL	7	7	538	2,131	0	0	0	0	0	0	0	0	0	0	0	0	0	0
REGION 11	7	7	538	2,131	0	0	0	0	0	0	0	0	0	0	0	0	0	0
DAVAO DE ORO	2	2	264	774	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Maco	2	2	264	774	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Mainit		1	2	8	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Panoraon		1	262	766	0	0	0	0	0	0	0	0	0	0	0	0	0	0
DAVAO ORIENTAL	5	5	274	1,357	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Tarragona	2	2	140	700	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Tubaon		1	129	645	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Cabagayan		1	11	55	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Governor Generoso	3	3	134	657	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Pundaguitan		1	118	590	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Surop		1	15	62	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Luzon		1	1	5	0	0	0	0	0	0	0	0	0	0	0	0	0	0

Roads and Bridges

REGION PROVINCE CITY /MUNICIPALITY BARANGAY		TYPE	CLASSIFICATION	ROAD SECTION/BRIDGE	STATUS	DATE REPORTED (passable)	TIME REPORTED (passable)	DATE REPORTED (not passable)	TIME REPORTED (not passable)	REMARKS
GRAND TOTAL	7									
REGION 11	7									
DAVAO DE ORO	5									
Maco	3									
Mainit		Road	Provincial		PATV - PASSABLE ALL TYPES VEHICLES	29 June 2025	09:00 pm	29 June 2025	05:30 pm	

REGION PROVINCE CITY /MUNICIPALITY BARANGAY		TYPE	CLASSIFICATION	ROAD SECTION/BRIDGE	STATUS	DATE REPORTED (passable)	TIME REPORTED (passable)	DATE REPORTED (not passable)	TIME REPORTED (not passable)	REMARKS
Panoraon		Road	Provincial		PATV - PASSABLE ALL TYPES VEHICLES	29 June 2025	09:00 pm	29 June 2025	05:30 pm	
Tagabaros		Road	Provincial		PATV - PASSABLE ALL TYPES VEHICLES	29 June 2025		29 June 2025	05:30 pm	-Due to landslide -Clearing operation conducted by LGU Maco and PEO
Nabunturan	1									
Katipunan		Road	Barangay		PATV - PASSABLE ALL TYPES VEHICLES	30 June 2025	11:09 am	28 June 2025	07:00 pm	-Needs further clearing operations
Maragusan (San Mariano)	1									
Katipunan		Road	National (primary)		PATV - PASSABLE ALL TYPES VEHICLES	30 June 2025		29 June 2025	02:47 pm	-Due to landslide
DAVAO OCCIDENTAL	2									
Malita	1									
Ticulon		Road	National (primary)	Sitio Mayapot, Brgy. Ticulon, Malita, Davao Occidental K1654+400 to K1654+420 Latitude - 6.304818° Longitude - 125.596298°	OLP - ONE LANE PASSABLE	02 July 2025	12:00 pm			
Don Marcelino	1									
Talaguton		Road	National (primary)	Sitio Pamungot, Brgy. Talaguton, Don Marcelino, Davao Occidental K1652+500 - K1652+600 Latitude - 6.297778° Longitude - 125.655278°	PATV - PASSABLE ALL TYPES VEHICLES	07 July 2025	12:00 pm	30 June 2025		-Previously reported as One lane passable last June 30, 2025 due to mudslide -2 lanes passable out of 2 lanes as of July 7, 2025, 12:00NN -Installed warning signs and traffic -Continuous monitoring of affected infrastructure

Power

REGION PROVINCE CITY /MUNICIPALITY BARANGAY		TYPE	SERVICE PROVIDER	DATE OF INTERRUPTION/ OUTAGE	TIME OF INTERRUPTION/ OUTAGE	DATE RESTORED	TIME RESTORED	REMARKS
GRAND TOTAL	1							
REGION 11	1							
DAVAO OCCIDENTAL	1							
Don Marcelino	1							
		Outage	DASURECO	29 June 2025	04:00	29 June 2025	10:00	

Water Supply

REGION PROVINCE CITY /MUNICIPALITY BARANGAY		TYPE	SERVICE PROVIDER	DATE OF INTERRUPTION/ OUTAGE	TIME OF INTERRUPTION/ OUTAGE	DATE RESTORED	TIME RESTORED	REMARKS
GRAND TOTAL	1							
REGION 11	1							
DAVAO DE ORO	1							
Maco	1							
Panoraon		Public		29 June 2025	05:00 pm			-Natural Flow; -Some of the hoses were damaged and need for replacement.
Mainit		Public		29 June 2025	05:00 pm			-Natural Flow; -Some of the hoses were damaged and need for replacement.

Damage to Infrastructure

REGION PROVINCE CITY /MUNICIPALITY BARANGAY		TYPE	CLASSIFICATION	INFRASTRUCTURE	NUMBER OF DAMAGED	UNIT	QUANTITY	STATUS	COST(PHP)	REMARKS
GRAND TOTAL	1				1		0		0	
REGION 11	1				1		0		0	
DAVAO ORIENTAL	1				1		0		0	
Governor Generoso	1				1		0		0	

REGION PROVINCE CITY /MUNICIPALITY BARANGAY		TYPE	CLASSIFICATION	INFRASTRUCTURE	NUMBER OF DAMAGED	UNIT	QUANTITY	STATUS	COST(PHP)	REMARKS
Nangan		Flood control	Local	Embankment	1		0		0	

Progress Report No. 2 for the Effects of Southwest Monsoon in Davao Region (Region XI)

ACTIONS TAKEN

Region 11

OCD XI

- Continuous monitoring of AOR in coordination with P/C/MDRRMCs and concerned RDRRMC XI member-agencies;
- Continuous dissemination of EAWMs thru Social Media, SMS, and E-mail; and
- Continuous coordination with affected LGUs for possible provision of NFI and Rice Assistance.

DSWD XI DROMIC

- Maintained close coordination with the affected LGUs;
- Coordinated with OCD XI re significant information related to the Southwest Monsoon; and
- Maintains adequate supply of stockpile ready for augmentation.

DPWH XI

- Continuous monitoring of affected infrastructure;
- Installed warning signs and traffic; and
- Conducted clearing operation

Don Marcelino MDRRMO

- Continuous monitoring of the AOR;
- MDRRMO personnel were deployed for response and monitoring of the incident area;
- Assisted the stranded pedestrian in Barangay Saladoc;- MEO and DPWH conducted clearing and temporary stabilization of affected roads;
- Traffic control and signage were installed in the hazardous locations;
- Power outage and restoration were coordinated with the local electric cooperative;
- Public advisories disseminated through official channels and social media;
- The LGU provided housing materials to families with partially damaged houses;
- Distributed food packs to affected families;
- Coordinated with the CIU-Davao Occidental to assist families with damaged homes;
- Coordinated with DASURECO to help restore electricity in the Municipality;
- Continuous dissemination of weather and road updates, along with safety reminders, through their official social media accounts; and
- Ongoing assessment of damaged houses, crops and roads.

Davao Oriental PDRRMO

- Conducted monitoring of the AOR;
- Continuous dissemination of weather advisories;
- Prepositioned response personnel and equipment if needs arises; and
- Conducted close coordination with their respective MDRRMOs,

Davao De Oro P/MDRRMCs

- Davao de Oro PDRRMO on continuous monitoring of AOR in coordination with MDRRMCs and concerned PDRRMC member-agencies/offices;
- Coordinated with Provincial Engineering Office for the conduct of clearing operations in the landslide affected areas;
- Continuous dissemination of EAWMs thru Social Media, Radio Communication and SMS;
- Continuous coordination with affected LGUs for possible augmentation of assistance

- Maco, Maragusan and Nabunturan on continuous monitoring of respective AOR in coordination with BDRRMCs;
- Maco, Maragusan and Nabunturan conducted clearing operations of their respective AORs affected by flashflood and landslide incidents; and
- Conducted clearing operation in Barangay Anitapan, Pantukan.

Governor Generoso MDRRMO

- Provided relief operation conducted by MSWDO;
- Conducted evacuation of affected residents;
- Conducted clearing operation;
- Constant monitoring and coordination with BDRRMCs.

Tarragona MDRRMO

- Conducted assessment re damage caused by the incident;
- Close monitoring with BDRRMC;
- Evacuated affected families; and
- Coordinated with DPWH re affected roads.