



NDRRMC ADVISORY

TO : Chairperson, RDRRMCs XI and XII

FROM : Executive Director, NDRRMC and Administrator, OCD

SUBJECT : Flood Advisory No. **02 (Final)** for Buayan-Malungon River Basin

Date : 23 August 2020, 7:00 AM

Source: PAGASA-DOST

DATE AND TIME OF ISSUANCE	23 August 2020, 7:00 AM	
FACTORS OF RAINFALL	Localized Thunderstorms	
CURRENT SITUATION OF RIVER WATER LEVEL	As of 6:00 AM today, the main Buayan River and its major tributaries remained way below their respective alert levels (yellow). Slight increase is possible until later today but will remain below their respective alert levels (yellow).	
AVERAGE BASIN RAINFALL	DATE & TIME	23 August 2020, 6:00 AM
	PAST 24-HR	0.70 mm
	FORECAST 24- HR	Isolated rainshowers and thunderstorms
AREAS OF CONCERN (WATERWAYS LIKELY TO BE AFFECTED)	Buayan - Malungon rivers and major tributaries within the basin boundary. Area coverage within river basin are Malalag of Davao del Sur Province; Malita and Santa Maria of Davao Occidental Province; Malungon and Alabel of Sarangani Province; Tupi and Tampakan of South Cotabato Province and General Santos City.	
AWARENESS INFORMATION/ ADVISORY	Generally light rains and chances of thunderstorm activities are likely to occur over the Buayan - Malungon River Basin (BMRB) during the forecast period;	
	Less likelihood of flash floods and landslides at mountainside in upstream areas particularly in Municipalities of Tupi, Tampakan, Malita, Malalag, Santa Maria and Malungon;	
	Possible accumulation / ponding of rainwater at low – lying areas and those with poor drainage system and slight flooding of coastal areas affected by tides in downstream areas particularly in municipality of Alabel and General Santos City;	
	The Local Disaster Risk Reduction and Management Councils (LDRRMCs) within the basin are still advised to maintain their alertness and take appropriate precautionary measures to mitigate the adverse impacts of possible flashfloods and river floods and to continue monitoring for updates of thunderstorm advisories issued	

by Mindanao PAGASA Regional Services
Division (MPRSD).

With this event and unless significant developments of weather condition within the basin occurs, this is the final flood advisory for Buayan – Malungon River Basin.

You are directed to monitor the situation and undertake precautionary measures in your area of responsibility (AOR). Likewise, the public and the DRRMCs are advised to take appropriate actions, as necessary.


In order to better inform/warn communities, you are reminded to disseminate these through local/community leaders and through your local media, including community radio stations. Conduct press briefings as often as needed. This local effort will complement and reinforce efforts at the national level. Emphasis should be on proactive actions – evacuation rather than rescue.

Moreover, you are hereby directed to reiterate the guidelines on personal protection and hygiene such as respiratory etiquette and hand hygiene, social distancing, environmental, and food safety measures.

Let's untiringly aim for zero casualty.

Submit report on actions taken.

BY AUTHORITY OF THE CHAIRPERSON, NDRRMC:


UNDERSECRETARY RICARDO B JALAD
Executive Director, NDRRMC and
Administrator, OCD