




## NDRRMC UPDATE

### FLOOD ADVISORY NO. **02 (Final)** BUAYAN-MALUNGON RIVER BASIN

Releasing Officer:

  
**UNDERSECRETARY RICARDO B JALAD**  
Executive Director, NDRRMC and  
Administrator, OCD

**DATE : 23 August 2020, 7:00 AM**

Source: PAGASA-DOST issued on 23 August 2020, 7:00 AM

<b>DATE AND TIME OF ISSUANCE</b>	<b>23 August 2020, 7:00 AM</b>
<b>FACTORS OF RAINFALL</b>	<b>Localized Thunderstorms</b>
<b>CURRENT SITUATION OF RIVER WATER LEVEL</b>	As of 6:00 AM today, <b>the main Buayan River and its major tributaries remained way below their respective alert levels (yellow). Slight increase is possible until later today but will remain below their respective alert levels (yellow).</b>
<b>AVERAGE BASIN RAINFALL</b>	DATE & TIME <b>23 August 2020, 6:00 AM</b>
	PAST 24-HR <b>0.70 mm</b>
	FORECAST 24- HR <b>Isolated rainshowers and thunderstorms</b>
<b>AREAS OF CONCERN (WATERWAYS LIKELY TO BE AFFECTED)</b>	Buayan - Malungon rivers and major tributaries within the basin boundary. Area coverage within river basin are Malalag of Davao del Sur Province; Malita and Santa Maria of Davao Occidental Province; Malungon and Alabel of Sarangani Province; Tupi and Tampakan of South Cotabato Province and General Santos City.
<b>AWARENESS INFORMATION/ ADVISORY</b>	<b>Generally light rains and chances of thunderstorm activities are likely to occur over the Buayan - Malungon River Basin (BMRB) during the forecast period;</b>
	<b>Less likelihood of flash floods and landslides</b> at mountainside in upstream areas particularly in Municipalities of Tupi, Tampakan, Malita, Malalag, Santa Maria and Malungon;  <b>Possible accumulation / ponding of rainwater at low – lying areas and those with poor drainage system and slight flooding of coastal areas affected by tides in downstream areas particularly in municipality of Alabel and General Santos City;</b>  <b>The Local Disaster Risk Reduction and Management</b>

	<p>Councils (LDRRMCs) within the basin are still advised to maintain their alertness and take appropriate precautionary measures to mitigate the adverse impacts of possible flashfloods and river floods and to continue monitoring for updates of thunderstorm advisories issued by Mindanao PAGASA Regional Services Division (MPRSD).</p> <p>With this event and unless significant developments of weather condition within the basin occurs, this is the final flood advisory for Buayan – Malungon River Basin.</p>
--	--

**ACTION/S TAKEN:**

**NDRRMC Flood Advisory No. 02 (Final) for Buayan - Malungon River Basin** was cascaded to **OCD Regional Offices XI and XII** through email, SMS, and website for further dissemination to respective LDRRMCs from the provincial down to the municipal levels.

---