



REPUBLIC OF THE PHILIPPINES
NATIONAL DISASTER RISK REDUCTION AND MANAGEMENT COUNCIL

National Disaster Risk Reduction and Management Center, Camp Aguinaldo, Quezon City, Philippines

National Disaster Risk Reduction and Management Council

INCIDENTS MONITORED

Initial Report for the Vehicular Accident in Tarlac SCTEX Exit Toll Plaza, Brgy Bantog, Tarlac City (REGION III)

DATE OF INCIDENT	May 01, 2025
TIME OF INCIDENT	12:18 pm
DATE ISSUED	May 01, 2025
TIME ISSUED	11:00 pm
OVERVIEW	On 01 May 2025, at about 12:18 PM, a multiple vehicular collision occurred at SCTEX Tarlac Exit Toll Plaza (Northbound). According to the investigation of the Tarlac City Police Station, all involved vehicles were travelling towards north direction wherein the four (4) vehicles (V1, V2, V3, and V4) stopped upon reaching the queuing area of SCTEX Tarlac Toll Plaza. While approaching the said queuing area, V5 suddenly collided behind the V4 pushing it to collide with other vehicles in front (V1, V2, V3). Further investigation is ongoing.

CASUALTIES (2)

A total of 10 dead, 37 injured, and 0 missing persons were reported:

REGION	VALIDATED			FOR VALIDATION			TOTAL REPORTED		
	dead	injured	missing	dead	injured	missing	dead	injured	missing
TOTAL	0	0	0	10	37	0	10	37	0
TARLAC	0	0	0	10	37	0	10	37	0

Four (4) unidentified dead in V4 and 34 unidentified injured in V5. Further investigation is ongoing.

OTHER DAMAGED ASSETS

The estimated cost of damage to other assets amounting to Php 0 was reported in TARLAC.

PROVINCE	CLASSIFICATION	COST OF DAMAGE (PHP)
GRAND TOTAL		0
TARLAC	Vehicles	0

Casualties (2)

PROVINCE CITY /MUNICIPALITY BARANGAY	QTY	SURNAME	FIRST NAME	MIDDLE NAME	AGE	SEX	ADDRESS	CAUSE	REMARKS	SOURCE OF DATA	VALIDATED
--	-----	---------	------------	-------------	-----	-----	---------	-------	---------	----------------	-----------

Four (4) unidentified dead in V4 and 34 unidentified injured in V5. Further investigation is ongoing.

Other Damaged Assets

REGION PROVINCE CITY /MUNICIPALITY BARANGAY		CLASSIFICATION	PARTICULARS/ NAME OF ASSET	UNIT	QUANTITY	COST(PHP)	REMARKS
GRAND TOTAL	5				5	0	
REGION 3	5				5	0	
TARLAC	5				5	0	
Tarlac City	5				5	0	
Brgy Bantog		Vehicles	SUV - Toyota Veloz	unit	1	0	Partially Damaged
Brgy Bantog		Vehicles	SUV - Kia Sonet	unit	1	0	Totally Damaged
Brgy Bantog		Vehicles	SUV - Urvan	unit	1	0	Totally Damaged
Brgy Bantog		Vehicles	FAO Tractor Head	unit	1	0	Partially Damaged
Brgy Bantog		Vehicles	Solid North Bus	unit	1	0	Partially Damaged

**Initial Report for the Vehicular Accident in Tarlac SCTEX Exit Toll Plaza, Brgy Bantog, Tarlac
City (REGION III)
ACTIONS TAKEN**

Region 3

OCD III

-Continuous coordination with Tarlac PDRRMO, SCTEX, Tarlac City DRRMO, PNP Tarlac and Philippine Red Cross

SCTEX

-Responded to the incident site, provided medical assistance and regulated traffic congestion

TARLAC CITY POLICE STATION

-Responded to the incident site and regulated traffic congestion
-Investigated the incident, gathered evidence and interviewed witnesses to determine the cause and sequence of events

Tarlac PDRRMO

-Responded to the incident site, provided medical assistance and transported injured passengers to nearest hospital.

TARLAC CITY DRRMO

-Responded to the incident site, provided medical assistance and transported injured passengers to nearest hospital.