



REPUBLIC OF THE PHILIPPINES

NATIONAL DISASTER RISK REDUCTION AND MANAGEMENT COUNCIL

National Disaster Risk Reduction and Management Center, Camp Aguinaldo, Quezon City, Philippines

National Disaster Risk Reduction and Management Council

INCIDENTS MONITORED

Progress Report No. 1 for the Magnitude 5.8 Earthquake in San Francisco, Southern Leyte (REGION VIII)

DATE OF INCIDENT	January 23, 2025
TIME OF INCIDENT	07:39 am
DATE ISSUED	January 24, 2025
TIME ISSUED	04:00 pm
OVERVIEW	On 23 January 2025, 7:39 AM, a magnitude 5.8 earthquake was reported in San Francisco, Southern Leyte with 011km depth of focus and tectonic in origin. Aftershocks and damage are expected.

AFFECTED POPULATION

A total of 337 families or 1,207 persons were affected. Of which, 0 families or 0 persons were served inside 0 ECs and 0 families or 0 persons were served outside ECs:

Affected Provinces	AFFECTED			INSIDE ECs			OUTSIDE ECs	
	Brgy	Families	Persons	No. of ECs	Families	Persons	Families	Persons
TOTAL	30	337	1,207	0	0	0	0	0
SOUTHERN LEYTE	30	337	1,207	0	0	0	0	0

CASUALTIES (2)

A total of 0 dead, 31 injured, and 0 missing persons were reported:

REGION	VALIDATED			FOR VALIDATION			TOTAL REPORTED		
	dead	injured	missing	dead	injured	missing	dead	injured	missing
TOTAL	0	0	0	0	31	0	0	31	0
SOUTHERN LEYTE	0	0	0	0	31	0	0	31	0

ROADS AND BRIDGES

A total of 2 road sections and 2 bridges were affected. Below is the current status of affected road sections and bridges:

	NOT PASSABLE		PASSABLE (previously reported as not passable and/or one lane passable)	
	ROADS	BRIDGES	ROADS	BRIDGES
GRAND TOTAL	0	0	2	2
SOUTHERN LEYTE	0	0	2	2

DAMAGED HOUSES

A total of 348 damaged houses are reported in SOUTHERN LEYTE.

REGION	PARTIALLY	TOTALLY	TOTAL	AMOUNT (PHP)
GRAND TOTAL	342	6	348	0
SOUTHERN LEYTE	342	6	348	0

DAMAGE TO INFRASTRUCTURE

The estimated cost of damage to infrastructure amounting to Php 0 was reported in SOUTHERN LEYTE.

PROVINCE	NUMBER OF DAMAGED INFRASTRUCTURE	COST OF DAMAGE (PHP)
GRAND TOTAL	63	0
SOUTHERN LEYTE	63	0

Affected Population

REGION PROVINCE CITY/ MUNICIPALITY BARANGAY		NO. OF AFFECTED			No. of ECs		Inside Evacuation Centers				Outside Evacuation Centers				TOTAL SERVED					
		Brgys.	Families	Persons	CUM	NOW	Families		Persons		Families		Persons		(Inside + Outside)		Families		Persons	
							CUM	NOW	CUM	NOW	CUM	NOW	CUM	NOW	CUM	NOW	CUM	NOW		
GRAND TOTAL	5	30	337	1,207	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
REGION 8	5	30	337	1,207	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
SOUTHERN LEYTE	5	30	337	1,207	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Liloan	1	3	43	155	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
		3	43	155	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Padre Burgos	1	4	10	50	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
		4	10	50	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Pintuyan	1	11	157	628	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
		11	157	628	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Saint Bernard	1	3	10	39	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
		3	10	39	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
San Francisco	1	9	117	335	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
		9	117	335	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0

Casualties (2)

PROVINCE CITY /MUNICIPALITY BARANGAY	QTY	SURNAME	FIRST NAME	MIDDLE NAME	AGE	SEX	ADDRESS	CAUSE	REMARKS	SOURCE OF DATA	VALIDATED
---	-----	---------	------------	-------------	-----	-----	---------	-------	---------	-------------------	-----------

Roads and Bridges

REGION PROVINCE CITY /MUNICIPALITY BARANGAY		TYPE	CLASSIFICATION	ROAD SECTION/BRIDGE	STATUS	DATE REPORTED (passable)	TIME REPORTED (passable)	DATE REPORTED (not passable)	TIME REPORTED (not passable)	REMARKS
GRAND TOTAL	4									
REGION 8	4									
SOUTHERN LEYTE	4									
Liloan	4									
		Bridge		Liloan Bridge	PTLV - PASSABLE TO LIGHT VEHICLES	23 January 2025	09:00 am			Space gap of the Steel Expansion Joint -Ongoing assessment

REGION PROVINCE CITY /MUNICIPALITY BARANGAY		TYPE	CLASSIFICATION	ROAD SECTION/BRIDGE	STATUS	DATE REPORTED (passable)	TIME REPORTED (passable)	DATE REPORTED (not passable)	TIME REPORTED (not passable)	REMARKS
		Road		Daang Maharlika Road	OLP - ONE LANE PASSABLE	23 January 2025	09:00 am			Slab cracking at Left Lane and Inner Right Lane -Ongoing assessment
Brgy Amaga		Road		Along Maharlika Highway	OLP - ONE LANE PASSABLE	23 January 2025	09:00 am			Left lane is Blocked due to Rockfall -Ongoing assessment
		Bridge	National (primary)	LILOAN BRIDGE K1054+580 RL	OLP - ONE LANE PASSABLE	23 January 2024		23 January 2024		Detachment of Cross Bracing

Damaged Houses

REGION PROVINCE CITY/ MUNICIPALITY BARANGAY	NO. OF DAMAGED HOUSES			AMOUNT (PHP)	REMARKS
	TOTALLY	PARTIALLY	GRAND TOTAL		
GRAND TOTAL	6	342	348	0	
REGION 8	6	342	348	0	
SOUTHERN LEYTE	6	342	348	0	
Pintuyan	0	154	154	0	
	0	154	154	0	
Padre Burgos	0	10	10	0	
	0	10	10	0	
Saint Bernard	0	9	9	0	
	0	9	9	0	
Hinundayan	0	1	1	0	
	0	1	1	0	
San Francisco	6	146	152	0	
	6	146	152	0	ongoing assessment
Liloan	0	22	22	0	
	0	22	22	0	

Damage to Infrastructure

REGION PROVINCE CITY /MUNICIPALITY BARANGAY		TYPE	CLASSIFICATION	INFRASTRUCTURE	NUMBER OF DAMAGED	UNIT	QUANTITY	STATUS	COST(PHP)	REMARKS
GRAND TOTAL	63				63		383.905		0	
REGION 8	63				63		383.905		0	
SOUTHERN LEYTE	63				63		383.905		0	
San Francisco	12				12		181.405		0	
Portion of Brgy. Habay Highway, Sta Paz Norte Highway and Brgy Road of Gabi		Roads	Local	Brgy Roads	1		0		0	slight cracks
		Government Facilities	Local	Sanguniang Bayan Building	1		0		0	minor cracks
		Government Facilities	Local	Municipal Gym	1		0		0	minor cracks
		Schools	Local	Sta. Paz Elementary School	1		0		0	minor cracks
		Schools	Local	Sta. Paz National High School	1		0		0	minor cracks
		Schools	Local	Marayag National High School	1		0		0	minor cracks
Sudmon		Roads	National	Liloan-San Ricardo Road K 1060+820 RS Brgy. Sudmon, San Francisco, Southern Leyte	1	Meter	100	PATV	0	Landslide incident along Lilian-San Ricardo Road
Sudmon		Roads	National	Liloan-San Ricardo Road K 1060+850 BL RS Brgy. Sudmon, San Francisco, Southern Leyte	1	Meter	18.09	PATV	0	Slab Cracking along Liloan-San Ricardo Road
Sitio Cawi		Roads	National	Liloan-San Ricardo Road K 1062+650 BL Sitio Cawi, San Francisco, Southern Leyte	1	Meter	18.09	PATV	0	Transverse along Liloan-San Ricardo Road
Sitio Cawi		Roads	National	Liloan-San Ricardo Road K 1062+750 BL Sitio Cawi, San Francisco, Southern Leyte	1	Meter	18.09	PATV	0	Transverse along Liloan-San Ricardo Road
Sitio Cawi		Roads	National	Liloan-San Ricardo Road K 1062+850 LL Sitio Cawi, San Francisco, Southern Leyte	1	Meter	9.045	PATV	0	Transverse along Liloan-San Ricardo Road

REGION PROVINCE CITY /MUNICIPALITY BARANGAY		TYPE	CLASSIFICATION	INFRASTRUCTURE	NUMBER OF DAMAGED	UNIT	QUANTITY	STATUS	COST(PHP)	REMARKS
Habay		Roads	National	Liloan-San Ricardo Road K 1066+380 BL Brgy. Habay, San Francisco, Southern Leyte	1	Meter	18.09	PATV	0	Slab Cracking along Liloan-San Ricardo Road
Limasawa	8				8		0		0	
		Government Facilities	Local	New Municipal Building; 3rd Floor Conference	1		0		0	minor cracks
		Government Facilities	Local	New Municipal Building; 2nd Floor Conference	1		0		0	minor cracks
		Government Facilities	Local	New Municipal Building; Municipal Accountant Office 2	1		0		0	minor cracks
		Government Facilities	Local	Municipal Treasurer's Office 2	1		0		0	minor cracks
		Government Facilities	Local	MSWD Office 1	1		0		0	minor cracks
		Government Facilities	Local	Agriculture Office 1	1		0		0	minor cracks
		Government Facilities	Local	EOC Building	1		0		0	minor cracks
		Schools	Local	Limasawa National High School	1		0		0	minor cracks
Liloan	7				7		172.25		0	
		Bridges	National	Liloan Bridge	1		0		0	minor cracks
Himay-angan		Roads	National	Daang Maharlika K1049+300 Brgy. Himay-angan, Liloan, Southern Leyte	1	Meter	49.72	PATV	0	Slab Cracking in Daang Maharlika
Himay-angan		Roads	National	Daang Maharlika K1049+350 BL Brgy. Himay-angan, Liloan, Southern Leyte	1	Meter	49.72	PATV	0	Slab Cracking in Daang Maharlika
Himay-angan		Roads	National	Daang Maharlika K1049+370 Brgy. Himay-angan, Liloan, Southern Leyte	1	Meter	49.72	PATV	0	Slab Cracking in Daang Maharlika

REGION PROVINCE CITY /MUNICIPALITY BARANGAY		TYPE	CLASSIFICATION	INFRASTRUCTURE	NUMBER OF DAMAGED	UNIT	QUANTITY	STATUS	COST(PHP)	REMARKS
Amaga		Roads	National	Daang Maharlika K1051+450 (LS) Brgy. Amaga, Liloan, Southern Leyte	1	Meter	5	PATV	0	Rockfall incident along Daang Maharlika
Amaga		Roads	National	Daang Maharlika K1052+090 BL Brgy. Amaga, Liloan, Southern Leyte	1	Meter	18.09	PATV	0	Traverse Crack over Daang Maharlika
San Isidro		Roads	National	K1059+099 San Isidro Bridge (B00115LT) Brgy. San Isidro, Lilaon, Southern Leyte	1		0	PATV	0	Collapsed Abutment Slope Protection
Pintuyan	9				9		0		0	
		Government Facilities	Local	Municipal Government Building	1		0		0	minor cracks
		Government Facilities	Local	Barangay Hall (Nueva Estrella Norte and Son-of 2	1		0		0	minor cracks
		Others: Chapel	Local	Chapel	1		0		0	minor cracks
		Health facilities	Local	Pintuyan District Hospital	1		0		0	minor cracks
		Schools	Local	Nueva Estrella Elementary School	1		0		0	minor cracks
		Schools	Local	Catbawan Elementary School	1		0		0	minor cracks
		Schools	Local	Pintuyan National Vocational High School	1		0		0	minor cracks
		Schools	Local	Cogon Elementary School	1		0		0	minor cracks
		Bridges	Local	Brgy. Bridge	1		0		0	damaged bridge abutment
Tomas Oppus	1				1		0		0	
Maslug		Government Facilities	Local	Barangay Hall and Minor crack in their Kalahi Project	1		0		0	minor cracks
Padre Burgos	5				5		0		0	
		Schools	Local	Dinahugan Elem, School	1		0		0	minor cracks
		Schools	Local	Lungsodaan Elem School	1		0		0	minor cracks

REGION PROVINCE CITY /MUNICIPALITY BARANGAY		TYPE	CLASSIFICATION	INFRASTRUCTURE	NUMBER OF DAMAGED	UNIT	QUANTITY	STATUS	COST(PHP)	REMARKS
		Schools	Local	Tangkaas Elem School	1		0		0	minor cracks
		Schools	Local	Cantutang Elem, School	1		0		0	minor cracks
		Schools	Local	Sto. Rosario Elem School	1		0		0	minor cracks
Macrohon	1				1		0		0	
		Schools	Local	Macrohon Elementary School Building	1		0		0	minor cracks
Libagon	9				9		0		0	
		Schools	Local	Kawayan Elem School	1		0		0	minor cracks
		Schools	Local	Magkasag Elem School	1		0		0	minor cracks
		Schools	Local	Otikon Elem School	1		0		0	minor cracks
		Schools	Local	Nahulid elem, School	1		0		0	minor cracks
		Schools	Local	RMSMNNHS	1		0		0	minor cracks
		Schools	Local	LNHS	1		0		0	minor cracks
		Schools	Local	Gakat Elem School	1		0		0	minor cracks
		Government Facilities	Local	Covered Court	1		0		0	minor cracks
		Government Facilities	Local	Municipal Building	1		0		0	Visible cracks
Maasin City	2				2		0		0	
		Schools	Local	Elementary and Secondary Schools	1		0		0	minor cracks
		Others: Church	Local	Our Lady of the Assumption Parish Church/Cathedral	1		0		0	for verification
Malitbog	1				1		0		0	
		Schools	Local	Elementary and Secondary Schools	1		0		0	minor cracks
Saint Bernard	1				1		0		0	
		Schools	Local	Elementary and Secondary Schools	1		0		0	minor cracks
Hinundayan	3				3		0		0	

REGION PROVINCE CITY /MUNICIPALITY BARANGAY		TYPE	CLASSIFICATION	INFRASTRUCTURE	NUMBER OF DAMAGED	UNIT	QUANTITY	STATUS	COST(PHP)	REMARKS
		Schools	Local	Hinundayan Catholic Schools	1		0		0	minor cracks
Brgy. District 1		Government Facilities	Local	Barangay Hall	1		0		0	minor cracks
		Government Facilities	Local	Municipal Building, Municipal Gym and legislative Building	1		0		0	minor cracks
Silago	1				1		0		0	
		Schools	Local	Elementary School	1		0		0	Several classrooms were found to have new minor cracks, and the size of some pre-existing minor cracks had increased
Sogod	2				2		0.25		0	
		Schools	Local	Elementary School and College University	1		0		0	minor cracks
Pancho Villa		Roads	National	Daang Maharlika K1015+600 LL Brgy. Pancho Villa, Sogod, Southern Leyte	1	Meter	0.25	PATV	0	Minor Rockfall in Daang Maharlika
Bontoc	1				1		30		0	
Bunga		Roads	National	Buenavista, Bontoc - Asuncion Maasin City Road (S00232LT) K1124+ 092 - K1134+000	1	Meter	30	PATV	0	Road Slip

**Progress Report No. 1 for the Magnitude 5.8 Earthquake in San Francisco, Southern Leyte
(REGION VIII)
ACTIONS TAKEN**

Region 8

OCD VIII

- Conducted Structural Assessment on some of the damages ICOW Effects of the recent Magnitude 5.9 Earthquake in San Francisco, Southern Leyte
- Ceremonial Turnover of NFIs to affected population of the recent Magnitude 5.9 Earthquake in San Francisco, Southern Leyte at San Francisco Municipal Gymnasium
- Conducted Aerial Assessment together with concerned agencies for the recent Magnitude 5.9 Earthquake in San Francisco, Southern Leyte
- Initial Situation Briefing of the current updates re Mag 5.9 Earthquake in Southern Leyte by Phivolcs Supervising Research Specialist Dr. Jeff Perez and Congressman Christopher Yap, 2nd District of Southern Leyte
- Facilitate Air mission Briefing for the Aerial Assessment in the Province of Southern Leyte
- Facilitate Media Briefing ICOW effects of the recent Magnitude 5.8 Earthquake in San Francisco, Southern Leyte @ HTOG8 Airbase, San Jose, Tacloban City together with PHIVOLCS Supervising Science Research Specialist DR. Jeffrey Perez, Southern Leyte 2nd District Congressman Christopherson Yap and TOG8 Acting Deputy Group Commander LTC Leopoldo Bacierra, Jr. II
- Hauling of Non-Food Items for the families affected by the Mag 5.9 EQ in San Francisco Southern Leyte
- Deployment of Quick Response Team on 24 Jan 2025 to conduct damage assessment in Southern Leyte, to be led by Dr. Jeffrey Perez of Phivolcs together with the OCD8 Personnel
- Sent letter request to NDRRMOC for assistance on the requested availability of Air Asset for the conduct of Aerial assessment.

MDRRMO San Francisco

- Dissemination of weather advisory to BDRRMCs and MDRRMC members through group chat
 - Submitted Situational Report to the PDRRMC Southern Leyte
- Close monitoring of barangay with reported landslide
- Conducted RDANA

Department of Science and Technology - PHIVOLCS

- Deployed Quick Response Team to join the conduct of Aerial Assessment initiated by the Office of Civil Defense RO8

Tactical Operations Group 8

- Facilitated the request of OCD8 for the availability of Air Asset for the Aerial Assessment in the areas affected by the Magnitude 5.9 Earthquake in San Francisco, Southern Leyte