



REPUBLIC OF THE PHILIPPINES  
**NATIONAL DISASTER RISK REDUCTION AND MANAGEMENT COUNCIL**

National Disaster Risk Reduction and Management Center, Camp Aguinaldo, Quezon City, Philippines

## NDRRMC UPDATE

### SitRep No. 13 re Magnitude 6.1 Earthquake in Castillejos, Zambales

Releasing Officer:

  
**UNDERSECRETARY RICARDO B JALAD**  
Executive Director, NDRRMC and  
Administrator, OCD

**DATE: 01 May 2019, 6:00 AM**

Sources: DOST-PHIVOLCS, DOE, DPWH, DSWD, DILG, DOH, BFP, AFP, NGCP, NEA, NPC, MMDA, BFP, DepEd, OCD ROs I, III, CALABARZON, CAR and NCR

#### **I. SITUATION OVERVIEW**

- An earthquake with a Magnitude of 6.1 occurred in **Castillejos, Zambales**. Further details below:

Date/Time	22 Apr 2019 - 5:11:09 PM
Location	15.02°N, 120.34°E - 018 km N 58° E of Castillejos (Zambales)
Depth of Focus (Km)	010
Origin	TECTONIC
Magnitude	Ms 6.1
Expecting Damage	YES
Expecting Aftershocks	YES
Issued on	23 Apr 2019 – 2:27 PM
Reported Intensities	<p><b>Intensity VII</b> – Lubao, Pampanga</p> <p><b>Intensity VI</b> - San Marcelino, and Subic, Zambales; Floridablanca, and Porac, Pampanga; Angeles City; Olongapo City</p> <p><b>Intensity V</b> - Castillejos, Iba and San Felipe, Zambales; Magalang, Mexico, and San Fernando, Pampanga; Abucay, Balanga, and Mariveles, Bataan; Malolos, Calumpit and Obando, Bulacan; Indang, Cavite; Sto. Domingo, Nueva Ecija; Lipa City; Makati City; Mandaluyong City; Manila City; Quezon City; Pasay City; San Juan City; Taguig City; Valenzuela City</p> <p><b>Intensity IV</b> - Meycauayan, Plaridel, and San Jose Del Monte, Bulacan; San Rafael, Tarlac; Rosales and Villasis, Pangasinan; Itogon, and La Trinidad, Benguet; Kasibu, Nueva Vizcaya; Gabaldon, Nueva Ecija; San Mateo and Rodriguez, Rizal; Bacoar, Imus, and Maragondon, Cavite; Nasugbu, Batangas; Antipolo City; Baguio City; Caloocan City; Las Piñas City; Marikina City; Pasig City; Tagaytay City</p> <p><b>Intensity III</b> - Marilao, Bulacan; Santo Domingo, and Talavera, Nueva Ecija; Maddela, Quirino; Dingalan, Aurora; Lucban, Quezon; Santa Cruz, Laguna; Carmona, Dasmariñas, General Trias, and Silang, Cavite; Lemery, San Nicolas and Talisay, Batangas; Cabanatuan City; Calamba City; Gapan City; Muntinlupa City; Palayan City</p>

	<b>Intensity II - Baler, Aurora</b>  <b>Instrumental Intensities:</b> <b>Intensity VII – Guagua, Pampanga</b>  <b>Intensity V – Magalang, Pampanga; Malolos City, Malabon City</b>  <b>Intensity IV - San Ildefonso, Bulacan; Cabanatuan City; Gapan City; Muntinlupa City; Pasig City; Quezon City; San Juan City; Las Piñas City; Marikina City; Caloocan City; Tagaytay City</b>  <b>Intensity III - Mauban, Quezon; Talisay, Batangas; Olongapo City</b>  <b>Intensity II - Dolores and Lucban, Quezon; Daet, Camarines Norte; Dagupan City; Lucena City</b>  <b>Intensity I - Guinayangan, Quezon; Calatagan, Batangas; Sinait, Ilocos Sur; Baguio City</b>
--	---

- As of **5:00 AM, 1 May 2019**, a total of **1,049 aftershocks were recorded**. Of which, **127 were plotted** and **16 were felt**, ranging from **1.4 to 2.5 Magnitude** and Intensity of I to III.

## II. EFFECTS

### A. CASUALTIES (TAB A)

- A total of **eighteen (18) dead, 256 injured, and three (3) missing** persons were reported in Regions III and NCR. Of which, **177 injured persons were validated by DOH**.

Region	Dead	Injured		Missing
		Reported	Validated	
III	18	255	176	3
NCR	-	1	1	-
Total	18	256	177	3

Source: OCD Region III and OCD NCR  
Note: Subject to verification and validation

### B. AFFECTED POPULATION

- A total of **3,630 families / 17,410 persons** were affected in **41 Barangays** in Region III.
- Of which, a total of **696 families / 2,979 persons** are being served inside **3 ECs** and **951 families / 4,756 persons** outside ECs.

REGION / PROVINCE / CITY / MUNICIPALITY	NO. OF AFFECTED		No. of ECs	SERVED POPULATION			
				INSIDE ECs		OUTSIDE ECs	
	Families	Persons		Families	Persons	Families	Persons
<b>GRAND TOTAL</b>	<b>3,630</b>	<b>17,410</b>	<b>3</b>	<b>696</b>	<b>2,979</b>	<b>951</b>	<b>4,756</b>
<b>REGION III</b>	<b>3,630</b>	<b>17,410</b>	<b>3</b>	<b>696</b>	<b>2,979</b>	<b>951</b>	<b>4,756</b>
<b>Pampanga</b>	<b>3,124</b>	<b>14,860</b>	<b>3</b>	<b>696</b>	<b>2,979</b>	<b>951</b>	<b>4,756</b>
Angeles City	1	6	-	-	-	-	-
Bacolor	18	81	1	10	46	-	-
Floridablanca	686	2,257	2	686	2,933	-	-
Guagua	56	318	-	-	-	-	-
Lubao	68	340	-	-	-	-	-
Mexico	1	6	-	-	-	-	-
Porac	2,034	10,170	-	-	-	951	4,756
City of San Fernando (capital)	10	60	-	-	-	-	-
Sasmuan (Sexmoan)	250	1622	-	-	-	-	-
<b>Zambales</b>	<b>392</b>	<b>1,988</b>	<b>-</b>	<b>-</b>	<b>-</b>	<b>-</b>	<b>-</b>
San Marcelino	288	1,468	-	-	-	-	-
Subic	104	520	-	-	-	-	-



REGION / PROVINCE / CITY / MUNICIPALITY	NO. OF AFFECTED		No.of ECs	SERVED POPULATION			
				INSIDE ECs		OUTSIDE ECs	
	Families	Persons		Families	Persons	Families	Persons
<b>Bataan</b>	<b>114</b>	<b>562</b>	-	-	-	-	-
Abucay	4	13	-	-	-	-	-
Bagac	1	4	-	-	-	-	-
Hermosa	107	535	-	-	-	-	-
Orani	2	10	-	-	-	-	-

Source: *DSWD DROMIC Report No. 13 as of 30 April 2019, 7:00 PM*

## C. DAMAGES

### 1. DAMAGED HOUSES

A total of **3,616 damaged houses** (925 – totally and 2,691 partially) were reported in Bataan, Pampanga, and Zambales (Region III):

REGION / PROVINCE / MUNICIPALITY	NO. OF DAMAGED HOUSES	
	TOTALLY	PARTIALLY
<b>GRAND TOTAL</b>	<b>925</b>	<b>2,691</b>
<b>Bataan</b>	<b>1</b>	<b>113</b>
Abucay	1	3
Bagac	-	1
Hermosa	-	107
Orani	-	2
<b>Pampanga</b>	<b>923</b>	<b>2,524</b>
Floridablanca	419	1,448
Bacolor	25	14
Guagua	-	46
Lubao	-	-
Mexcio	-	1
Porac	472	1,005
City of San Fernando (capital)	1	10
Sasmuan (Sexmoan)	-	-
<b>Zambales</b>	<b>1</b>	<b>54</b>
Subic	1	54

Source: *DSWD DROMIC Report No. 13 as of 30 April 2019, 7:00 PM*

### 2. DAMAGED INFRASTRUCTURES (TAB B)

A total of **741 structures/buildings** sustained damages due to earthquake in Regions I, III, NCR, and CALABARZON. **Of which, 214 schools was validated by DepEd and 74 health facilities validated by DOH..**

Sources: *DILG, DOH, DepEd, DPWH, OCDROs III and NCR*



Chuzon Supermarket in Porac, Pampanga



### 3. COST OF DAMAGES

An estimated worth of **₱539,000,000.00** damage to schools and damage to roads and bridges was reported in Regions I, III, CALABARZON, and NCR.

REGION	Cost of Damages to Schools	Cost of Damages to Roads and Bridges
NCR	17,000,000.00	-
I	41,500,000.00	-
III	210,500,000.00	200,000,000.00
CALABARZON	70,000,000.00	-
<b>TOTAL</b>	<b>₱339,000,000.00</b>	<b>₱200,000,000.00</b>

Source: DepEd and DPWH

Note: Decrease in the amount of damages in Region III was due to on-going validation of DepEd.

### D. INCIDENTS MONITORED

1. An **earthquake-induced landslide** was reported in Mt. Bimmukel, Sitio Lomibao, Brgy. San Rafael, San Marcelino, Zambales. Approximately **120** families were evacuated and provided with relief packs.

### E. STATUS OF LIFELINES

#### 1. Power Supply

- A total of **4 Provinces** in Regions I and III experienced power interruption due to earthquake.

REGION / PROVINCE	CITY/ MUNICIPALITY	DATE AND TIME OF INTERRUPTION	REMARKS
<b>REGION I</b>			
Pangasinan	Province-wide	22 April 2019	Restored
La Union	Province-wide	22 April 2019	Restored
<b>Region III</b>			
Pampanga	Province-wide	22 April 2019	Restored except in Brgy. Cangatba, Porac
Bataan	Province-wide	22 April 2019	Restored

Source: DOE as of 22 April 2019, 7:00 PM

#### 2. Roads and Bridges

- A total of one (1) dike, one (1) bridge, and one (1) road in Pampanga (Region III) were rendered not passable to vehicles. On 29 April 2019, Floridablanca Consuelo Bridge and Sasmuan-Lubao Road were reported passable to all types of vehicles.

AFFECTED AREAS	ROAD SECTION / BRIDGE		STATUS	REMARKS
REGION III				
Pampanga	Pampanga 1 <sup>st</sup> DEO	East Lateral Mega Dike, Maiwalo/Dolores, Bacolor	Not passable as of 23 April 2019, 9:26 AM	Lateral and vertical movement of dike causing cracks and opening of concrete slope protection and settlements  <b>Passable to light vehicles only</b> as of 26 April 2019, 8:00 AM  Alternate Route 1: Manila North Road going to Angeles  Alternate Route 2: Angeles - Porac - Floridablanca Road and Guagua - Sta. Rita Arterial Road (Florida - Porac - Angeles) going to Angeles

AFFECTED AREAS	ROAD SECTION / BRIDGE		STATUS	REMARKS
	Pampanga 2 <sup>nd</sup> DEO	Floridablanca Consuelo Bridge, B01528LZ	Not passable as of 23 April 2019, 9:26 AM	Slab deck cracks and depression on approach "A"  <b>Passable to light vehicles only</b> as of 26 April 2019, 8:00 AM  Alternate Route: Jose Abad Santos Avenue Rd.  <b>Passable to all types of vehicles as of 29 April 2019, 8:00AM.</b>
		Sasmuan-Lubao Road, K0076+380 - K0076+480, San Nicolas 1st, Lubao, Pampanga	Not passable as of 23 April 2019, 9:26 AM	Collapsed slope protection and half of the carriageway and embankment was scoured  <b>One Lane Passable to light vehicles only</b> as of 26 April 2019, 8:00 AM  <b>Passable to all types of vehicles as of 29 April 2019, 8:00AM.</b>

Source: DPWH as of 29 April 2019, 8:00 AM

### 3. Cancelled Flights (TAB C)

- **67 International flights and 154 domestic flights** were cancelled in Clark International Airport Corporation (CIAC) on 22 - 24 April 2019. Of which, ALL flights have already resumed.

### F. SUSPENSION OF CLASSES AND WORK

1. A total of **1,653 schools** in Regions III, CALABARZON, CAR, and NCR have suspended classes due to the incident. Of which, only three (3) schools in NCR and Region III have not resumed classes (**TAB D**).

Source: DEPED and OCD Regions

2. Government work was suspended on 23 April 2019 in Metro Manila and in the Provinces of Zambales, Nueva Ecija, and Pampanga to facilitate the inspection of all structure damages.

### G. Declaration of State of Calamity:

- The entire Municipality of Porac, Pampanga was declared under State of Calamity on 22 April 2019 with Resolution No. 25, series of 2019.

## III. DISASTER RESPONSE (TAB E)

1. **Response assets and 1,548 Personnel** from National/Regional Government Agencies, Local Government Units, and Private Sectors were deployed to conduct response operations in Region III (**TAB F**).

### 1. National Disaster Risk Reduction and Management Operations Center (NDRRMOC)

- a. The alert status was raised to BLUE at the NDRRMOC effective 22 April 2019, 7:00 PM.
- b. Issued NDRRMC Memorandum on 22 April 2019, to all concerned Chairpersons, RDRRMCs/OCD Regional Directors, directing them to raise their respective Operations Centers alert status to continuously monitor their respective Areas of Responsibility (AOR). Likewise, NDRRMC member agencies were directed to render duty at NDRRMOC to ensure continuous coordination.



- c. Immediately disseminated Earthquake Information Nos. 1, 2, 3, and 4 to OCD Regional Offices concerned and other stakeholders through facsimile, SMS, website and twitter account for further dissemination to their respective local DRRMCs. Moreover, advised them to undertake precautionary measures and monitor the situation for any possible effects of said earthquake particularly in areas with reported intensities.
- d. Prepared the Emergency Alert and Warning Message (EAWM) for dissemination by Telecommunications Companies (TELCOs) to the affected areas.
- e. President Rodrigo Roa Duterte, together with Usec. Ricardo Jalad and House Speaker Gloria Macapagal-Arroyo, visited the affected areas in Pampanga on 23 April 2019.
- f. A briefing for the President was conducted at the Provincial Capitol of Pampanga on 23 April 2019, 6:00 PM.
- g. Response Cluster Meeting was conducted on 24 April 2019, 2:00 PM at the NDRRMC Operations Center.

#### A. Cost of Assistance

- A. A total of **₱2,423,695.52** worth of assistance from OCD, DSWD, and LGUs were provided for Region III.

RECIPIENT	OCD	DSWD	LGU	NGO	Total
<b>TOTAL</b>	<b><u>52,944.29</u></b>	<b><u>2,015,677.23</u></b>	<b><u>242,574.00</u></b>	<b><u>112,500.00</u></b>	<b><u>2,423,695.52</u></b>
PEMRU HEMS	3,463.60				3,463.60
BFP	8,542.58				8,542.58
Philippine Army	40,938.11	-	-	-	40,938.11
<b>Pampanga</b>	-	<b>1,916,392.23</b>	<b>242,574.00</b>	<b>112,500.00</b>	<b>2,271,466.23</b>
Angeles City	-	5,000.00	-	-	5,000.00
Floridablanca	-	580,552.35	-	-	580,552.35
Guagua	-	20,742.70	-	-	20,742.70
Lubao	-	145,000.00	-	-	145,000.00
Mexico	-	10,000.00	-	-	10,000.00
Porac	-	1,155,097.18	242,574.00	112,500.00	1,510,171.18
<b>Zambales</b>	-	<b>99,285.00</b>	-	-	<b>99,285.00</b>
San Marcelino	-	99,285.00	-	-	99,285.00

Source: DSWD DROMIC Report No. 13 as of 30 April 2019, 7:00 PM and OCD Region III Situation Report.

**Effects of Magnitude 6.1 Earthquake in Castillejos, Zambales**  
**CASUALTIES**  
**As of 6:00 AM, 01 May 2019**

AREA		LAST NAME	FIRST NAME	MIDDLE NAME	AGE	GENDER	ADDRESS	REMARKS
<b>INJURED</b>	<b>177</b>							
<b>NCR</b>	<b>1</b>							
<b>Valenzuela City</b>	<b>1</b>							
	1	Rotulo	Jayson	Maglente	33	M	Maysa, Valenzuela City	Fracture close bilateral comminuted calcaneus
<b>REGION III</b>	<b>176</b>							
<b>Pampanga</b>	<b>176</b>							
<b>Angeles City</b>	1	Briquillo	Allan		48	M	Angeles, Pampanga	Laceration Right Foot
	1	Binasing	Norma		62	F	Cutcut, Angeles City	Trauma Secondary to Falling Object
	1	Miranda	Raymart	P.	26	M	Angeles, Pampanga	Ankle Sprain Right, R/O Fracture
	1	Hermohinez	Precorpio		49	M	Sitio Tangot, Sapang Bato	Physical Injury secondary to Earthquake
	1	Cerbito	Ronalyn		38	F	P. Maragul, Angeles	Multiple Injuries Secondary to Earthquake
	1	Gabriel	Jimuel		18	M	P. Bulu, Angeles	MPI secondary to Falling Debris
	1	David	Maricar		25	F	Pandar, Angeles City	Left Ankle Sprain to rule out Fracture
	1	Lajum	Marjin		16	F	San Jose, Angeles	Bimalleolar Fracture Open, Left Foot
	1	Rodriguez	Jim		31	M	F. Ship, Angeles	Sprained Ankle, Right, R
	1	Guira	Denmart		11	M	Malabanias, Angeles	Mild TBI Secondary to Fall
	1	Morcio	Teresa		41	F	Balibago, Angeles	PI secondary to Fall
	1	Cuison	Kyle	N.	18	M	Marisol, Angeles	Punctured Wound
	1	Santos	Kremlin	F.	39	M	Mansfield, Angeles	Punctured Wound
	1	Tomas	John Leonard	C.	28	M	Maoaque, Angeles	SA/VA
	1	Masangcay	Amador	D.	61	M	Virgen Delos Remedios	SA/Fall
	1	Llaguno	John Raymond		17	M	Purok 1, Amsic	Animal Bite CAT III
	1	Moania	Jirovary		11	M	Balibago, Angeles	Lacerated Wound, Right Parietal Region
	1	Guevarra	Analisa		19	F	Cutcut, Angeles City	Right Shoulder Dislocation
	1	Aladin	Carmelito		67	M	Manibaug, Angeles	T/C Hip Dislocation, R/O Left Femoral Fracture
	1	Sanchez	Sandro	B.	22	M	LNW, Angeles City	Anxiety Attack
	1	Escobar	Alfonso		22	M	Angeles, Pampanga	Lacerated Wound, Right Hand
	1	Arigao	Shayne		7	F	Brgy. Limin	VA Secondary to Earthquake
	1	Le Clanel	Jorena		40	M	Malabanias, Angeles	Physical Injuries Secondary to Earthquake
	1	Guria	Reynaldo		18	M	Angeles, Pampanga	Physical Injuries Secondary to Earthquake
	1	Yap	Rogelio		58	M	Balibago, Angeles	Physical Injuries Secondary to Earthquake
	1	Mueco	Jasper		18	M	Cerayan, Angeles	Lacerated Wound, Left Foot
	1	Corpus	Christine Joy		30	F	Cutcut, Angeles City	Soft Tissue Injury
	1	Salamat	Mark Gerald	D.C.	36	M	Anuras	Self Accident related to Earthquake
<b>Apalit</b>	1	Reyes	Eduardo	T	50	M	Apalit, Pampanga	Physical Injury secondary to Earthquake
<b>Floridablanca</b>	1	Apang	Misty		34	F	P1, Nabuclod, Floridablanca, Pampanga	Lacerated wound scalp left periorbital
	1	Balenton	Nelia	B	38	F	Sitio Tagak, Nabuclod, Floridablanca, Pampanga	Ankle sprain left r/o fracture positive abrasion and swelling left ankle
	1	Bequilla	Rowena	D	42	M	P4 Paguiran, Floridablanca, Pampanga	Head injury
	1	Cabrera	Benedicto	A	67	F	Mabical, Floridablanca, Pampanga	Lacerated wound frontal area right
	1	Danan	Emmanuel	D	14	M	Anon, Floridablanca, Pampanga	Multiple Abrasion
	1	Danan	Vilma		25	F	Anon, Floridablanca, Pampanga	Abrasion
	1	De Hitta	Margie	S	51	F	Fortuna, Floridablanca, Pampanga	Lacerated wound frontal area
	1	De Vera	Rona Mae	S	21	F	Canlas, Floridablanc, Pampanga	Hematoma right parietal, abrasion left shoulder
	1	Guanlao	Loures	M	31	F	San Antonio, Floridablanca, Pampanga	Lacerated wound
	1	Kabiling	Jennifer	D	25	F	P5 Paguiran, Floridablanca, Pampanga	Knee spasm left
	1	Liwanag	Milia		62	F	P1, Nabuclod, Floridablanca, Pampanga	R/O pelvic fracture, skeletal spasm lumbosacral
	1	Mayuyu	Lolita	D	63	F	Nabuclod, Floridablanca, Pampanga	Lacerated wound right parietal area
	1	Muli	Alex	N	53	M	San Jose, Floridablanca, Pampanga	Lacerated wound right forearm
	1	Papasing	May	T	11	F	Nabuclod, Floridablanca, Pampanga	Abrasion left buttock secondary to landslide
	1	Papasing	Perlas	T	5	F	Nabuclod, Floridablanca, Pampanga	Abrasion Facial Area
	1	Papasing	Lovely	T	10	F	Nabuclod, Floridablanca, Pampanga	No Physical Injury Noted
	1	Papasing	Myrna	T	2	M	Nabuclod, Floridablanca, Pampanga	Back pain secondary to landslide r/o pelvic fracture
	1	Papasing	Romel	T	3	M	Nabuclod, Floridablanca, Pampanga	Avulsed wound face, open fracture left clavicle
	1	Pinlac	Jolina Rose	L	17	F	#22 Fortuna, Floridablanca, Pampanga	Puncture Wound
	1	Quiambao	Isnaria	N	41	F	Purok I San Jose, Floridablanca	Lacerated Wound Left Leg
	1	Ramirez	Grace	I	16	F	Nabuclod, Floridablanca, Pampanga	Avulsion 2nd Finger Left Contusion right parietal area
	1	Ramos	Enriquez	D	43	M	Mabical, Floridablanca, Pampanga	Left Shoulder Pain
	1	Reyes	Qallen	V	40	M	Lambingan St. Dampe, Floridablanca, Pampanga	Lacerated wound forehead
	1	Romualdo	Jerico	S	20	M	Nabuclod, Floridablanca, Pampanga	Abrasion left frontal with swelling
	1	Santos	Efroclan	M	77	M	P5 Bodega, Floridablanca, Pampanga	Femoral neck fracture, left
	1	Serrano	Roman	A	34	M	Nabuclod, Floridablanca, Pampanga	Crushing injury secondary to falling debris
	1	Soria	Jenny	T	5	F	Nabuclod, Floridablanca, Pampanga	R/O Pelvic structure
	1	Soria	Emily	T	48	F	Nabuclod, Floridablanca, Pampanga	Lacerated wound occipital area
	1	Tamtam	Rogelio		65	M	Nabuclod, Floridablanca, Pampanga	Abrasion right leg secondary to land slide, abrasion right leg
	1	Tamtam	Ariel		18	M	Nabuclod, Floridablanca, Pampanga	No Physical Findings
	1	Tamtam	Teresita	S	76	F	Sitio Tagak, Nabuclod, Floridablanca, Pampanga	T/C Radio Ulnar Fracture Right Lacerated wound right hand
	1	Ticsay	Karen Mae	C	26	F	San Jose, Floridablanca, Pampanga	Right ankle sprain
	1	Valerio	Elsie	B	45	F	Apalit, Floridablance	Abrasion right wrist, right hand
	1	Yusi	Liezel	R	42	F	Blk 26 Lot 40 Model Comm. Pio, Porac, Pampanga	Puncture Wound
<b>Guagua</b>	1	Villafuente	Nenita	G	49	F	Becuran, Guagua, Pampanga	Mpi 2° To Earthquake Related Injury
<b>Lubao</b>	1	Manacmul	Kheyael	M	7	F	San Francisco, Lubao, Pampanga	Lacerated wound forehead
<b>Mabalacat</b>	1	Ramos	Renier	F	28	M	Sta. Rita, Lubao, Pampanga	Lacerated Wound Left Hand
	1	San Agustin	Kaycee		51	M	Mabalacat	Rule out Fracture
	1	Dela Cruz	Precious Marie		19	F	Mabalacat, Pampanga	Physical Injuries Secondary to Earthquake
<b>Mexico</b>	1	Lopez	Jimboy	V	28	M	Mabalacat	Physical Injury secondary to Earthquake
	1	Borja	Arcel		33	F		Anterior Shoulder Dislocation
	1	Manangan	Jun Jose		30	M		Abrasion Anterior Left Leg Secondary To Industrial Injury
<b>Porac</b>	1	Abuque	Josabel	C	25	F	Camias, Porac, Pampanga	1st Degree Burn Abdominal Area
	1	Aladin	Carmelito		65	M	P6. M. Libutad, Porac, Pampanga	Hip dislocation, R/O Left Femoral Fracture; Lacerated wound left finger
	1	Loreta		L	65	F	P6. M. Libutad, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Alvaro	Arceli	G	44	F	Pio, Porac, Pampanga	Contusion left parietal area
	1	Ambrocio	Junior Payo		35	M	Porac, Pampanga	Abrasion ankle right secondary to crushing injury
	1	Ambrocio	Jade Adrian		23	M	Porac, Pampanga	Abrasion forearm, hand right, occipital area secondary to crushing injury
	1	Ambrocio	Adrian Jade	E	13	F	B. Sacan, Porac, Pampanga	Mpi 2° To Earthquake Related Injury

AREA		LAST NAME	FIRST NAME	MIDDLE NAME	AGE	GENDER	ADDRESS	REMARKS
Porac	1	Ambrocio	Junior	P	25	M	B. Sacan, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Ambrosio	Marilou		35	F	Porac, Pampanga	Spinal cord injury due to burst fracture T12 due to crushing
	1	Ampatria	Michelle	B	4	F	Tokwing Pio, Porac, Pampanga	T/C Cerebral Concussion
	1	Ayson	Gina	B	34	F	Palat, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Ayson	Maxima		74	F	Poblacion, Porac, Pampanga	Cerebral Concusion
	1	Balicwas	Jonie		22	M		Traumatic Brain Injury, Mild; Mild Cerebral Concussion; Multiple Abrasion sec to Crushing Injury
	1	Basanta	Jonalyn		12	F	Mitla, Porac, Pampanga	Contusion Ha 2° To Earthquake Related Injury
	1	Bengco	Bhea Berlin	A	24	F	M.Pasig, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Bernardo	Mariel		4	F	Mexico, Pampanga	Traumatic Brain Injury Severe, Epidural Fronto-tempoparietal Convexity Left with Linear Skull Fracture Frontotempoparietal sec to fall
	1	Bulatao	Maritess	K	36	F	Inararo, Porac, Pampanga	Lumbar And Back Pain
	1	Canicosa	Ellein Grace	C	35	F	S. Bulaon, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Canicosa	Margaux	G	4	F	B. Sacan, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Corpuz	Rhealyn		22	F	Porac, Pampanga	Traumatic brain injury mild, cerebral concussion, fracture closed complete displaced distal clavicle right due to crushing
	1	Cortez	Josephine	Q	28	F	Planas, Porac, Pampanga	Multiple Abrasion
	1	Cunan	Rosita	M	50	F	P. Santol, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	David	Manulito	B	47	M	S. Bulaon, Porac, Pampanga	Acute Abdomen
	1	David	John Kevin	M	24	M	B. Pangulo, Porac, Pampanga	Avulsion Sole Right
	1	De Guzman	Winet		19	F	Cangatba, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Dela Cruz	Kaizer Lee	E	3	M	Planas, Porac, Pampanga	Lacerated wound head
	1	Delmundo	Andrea	S	17	F	Planas, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Delmundo	Jinky	S	44	F	Planas, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Dulu	Hermie	D	5	M	Cangatba, Porac, Pampanga	Lacerated Wound Parietal Area
	1	Ecallir	Elvin	M	52	M	Sta. Cruz, Porac, Pampanga	Laceration Calf Area Right
	1	Enriquez	Magliely	P	34	M	San Carlos City, Pangasinan	Hyperventilation Syndrome
	1	Enriquez	Melvin	I	27	M	Tarlac	Mpi 2° To Earthquake Related Injury
	1	Evangelista	Rowena		33	F	Porac, Pampanga	Abrasion on the middle aspect of left thigh, parietal area right secondary to crushing injury
	1	Evangelista	Camille Faith	M	5	F	B. Sacan, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Facun	Desiree		23	F	Moncada, Tarlac	Gangrenous, Right Lower Extremity; Multiple Abrasions sec to Crushing Injury
	1	Facunla	Jean Rhea	C	20	F	Guimba, Nueva Ecija	Mpi 2° To Earthquake Related Injury
	1	Flores	Reynaldo	E	85	M	Pmc, Porac, Pampanga	Abrasion Right Leg
	1	Gabriel	Winlove	G	23	F	B. Pangulo, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Gajol	Sharon Allana		37	F		Fracture Closed Complete Transverse Displaced 3rd Metatarsal Left; Fracture Closed Complete segmental Displaced 3rd Metatarsal Left; Fracture Closed Complete Oblique Displaced 4th Metatarsal Left Sec to Fall
	1	Galang	Janell	R	13	F	Palat, Porac, Pampanga	Crushing Injury Right Hand
	1	Galang	Janelle		5	F	Porac, Pampanga	Mangled 4th and 5th finger, hand right due to crushing injury
	1	Galay	Ellen Grace	C	35	F	S. Bulaon, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Gambo	Almira	D	21	F	B. Pangulo, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Garcia	Jenny		22	F	Pangasinan	Mpi 2° To Earthquake Related Injury
	1	Garung	Estrellita	B	71	F	Pio, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Guanlao	Belinda	G	51	F	Pio, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Guiao	Donnalyn	S	40	F	Pmc, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Igos	Jerwin	M	22	M	Cangatba, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Landicho	Angeline	C	14	F	Cangatba, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Lansang	Puricacion		71	F	Porac, Pampanga	Intertrochanteric fracture left secondary to fall
	1	Lansangan	Caren	M	28	F	Villa Maria, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Lozano	Jefferson	D	20	M	Lamorito, Neuva Ecija	Mpi 2° To Earthquake Related Injury
	1	Lusung	Princess Emjay	C	5	F	S. Bulaon, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Magisno	Zyanne	C	2	F	Planas, Porac, Pampanga	Multiple Abrasion
	1	Magisno	Geraldine	C	29	F	Planas, Porac, Pampanga	Pregnancy Uterine 26 and 4/7 weeks AOG G3P2
	1	Malit	Marivic	B	34	F	Palat, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Manalastas	Juanita		74	F	Mexico, Pampanga	Traumatic Brain Injury Severe, Subarachnoid Hemorrhage, Contusion Hematoma Frontal Lobe Left sec to Crushing Injury
	1	Manalili	Nelissa	F	56	F	B. Sacan, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Manuel	Gian Rose	C				Soft Tissue Swelling R/O Fracture Foot
	1	Manuel	Maine	G	2	F	Palat, Porac, Pampanga	Soft Tissue Swelling R/O Fracture Foot
	1	Manuel	Isabella	Q	2	F	Palat, Porac, Pampanga	Abrasion Fall Left
	1	Mariano	Maria Jesusa		24	F	Poblacion, Porac, Pampanga	T/C Soft Tissue Injury Right Foot R/O Fracture
	1	Mariano	Michael	M	35	M	Poblacion, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Marquez	Cresencia			F	Balubad, Porac, Pampanga	Abrasion Leg Right, Soft Tissue Swelling Knee Right
	1	Marquez	Lolita			F	Balubad, Porac, Pampanga	Abrasion Knee Left
	1	Martin	Lourdes		25	F	Concepcion, Tarlac	Hypovolemic Shock sec to Acute Blood Loss sec to Amputated Right thigh sec to Crushing Injury
	1	Melchor	Grace		31	F	Lubao, Pampanga	Traumatic brain injury
	1	Nacu	Jay-V	S	34	M	Planas, Porac, Pampanga	Lacerated wound head
	1	Orsino	Olive		24	F	Tarlac	Fall Due To Earthquake
	1	Palad	Ejeerah Shayne	L	17	F	S. Bulaon, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Pallasique	Marlo		32	M	Tarlac	Mpi 2° To Earthquake Related Injury
	1	Palo	Liza	P	16	F	S. Uwak, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Panzuelo	Rommel	B	20	M	Cangatba, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Pascual	Adrian	P	20	M	Gimba, Nueva Ecija	Mpi 2° To Earthquake Related Injury
	1	Peco	Samantha Nicole	A	8	F	B. Sacan, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Popatco	Leonor	B	70	F	S. Bulaon, Porac, Pampanga	Syncope
	1	Quiambao	Norma	M	64	F	Cangatba, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Quizon	Marielle	P	23	F	Dila-Dila, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Ramos	Mark Anthony	C	31	M	Cangatba, Porac, Pampanga	T/C Anxiety Rxn
	1	Romualdo	Marites		36	F	Porac, Pampanga	Traumatic Brain Injury Mild, Cerebral Concussion, Multiple Abrasion sec to Crushing Injury
	1	Rosillo	Kaycee		31	M		Fracture Closed Complete Displaced Right Calcaneus Sec To Fall
	1	Sadaran	Joselita Mae	D	32	F	M. Pasig, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Santos	Ana May	M	27	F	Planas, Porac, Pampanga	Contusion right frontal area
	1	Santos	Margie	G	13	F	Porac, Pampanga	Fracture open complete displaced proximal phalanx ring finger, fracture open complete displaced distal phalanx small finger secondary to crushing injury
	1	Santos	Jackielou	P	33	F	H. Dolores, Porac, Pampanga	Dizziness
	1	Santos	Roann Cabiel	T	11 Mo.	F	Poblacion, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Santos	Viner	R	11	M	Pias, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Sebalos	Jordan	G	32	M	B. Sacan, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Serrano	Roann Marie	D	22	F	P. Santol, Porac, Pampanga	Tension Headache
	1	Sula	Sonny	F	37	M	B. Sacan, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Tan	Jelly	C	29	M	Cangatba, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Tating	Yvon		21	F	Aurora	Traumatic Brain Injury Mild, Abrasions Left Upper Quadrant, Multiple Abrasions Thigh Right sec to Crushing Injury
	1	Toledo	Anita	M	66	F	Poblacion, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
	1	Tua	Matilda		90	F	Porac, Pampanga	Pelvic fracture, Superior rami
	1	Valencia	Lagrimas		80	F		Intertrochanteric Fracture Femur Left
	1	Manaloto	Melchor		39	M	Porac, Pampanga	Fracture Closed Complete Spiral Displaced mid to distal third femur left sec to fall
	1	Gotis	Roselyn	S.	28	f	Dolores, Porac Pampanga	Mpi 2° To Earthquake Related Injury
	1	Abalgan	John Edward	21	M		Tarlac	MPI 2° To Earthquake Related Injury
	1	Socco	Irene		32	F	Porac, Pampanga	Left Ankle Sprain to rule out Fracture
	1	Laynes	Solita		46	F	Porac, Pampanga	Soft Tissue Inflammation. Riht Foot, R/O Fracture
	1	Hobello	Yhussuf Ali		7	M	Porac, Pampanga	Closed, Complete, Non-Displaced Fracture of the Distal Phalange of 2nd Digit, Right Foot
	1	Sigua	Precy		42	F	Porac, Pampanga	Lacerated Wound, Wrist
	1	Guinto	Patricia Ann		19	F	Balubad, Porac, Pampanga	Mpi 2° To Earthquake Related Injury
San Fernando	1	Timbol	Camille		21	F		Fracture Closed Complete, Basicervical Femoral Neck Right
San Luis	1	Soliman	Marita		74	F	San Nicolas, San Luis, Pampanga	Fracture dislocation humeral head right, fracture closed displaced distal radius right secondary to fall

Sources: DOH-HEMB as of 29 April 2019



## Effects of Magnitude 6.1 Earthquake in Castillejos (Zambales)

**DAMAGED STRUCTURES**

As of 1 May 2019, 6:00 AM

REGION/PROVINCE/CITY	LOCATION	STRUCTURE	REMARKS
<b>REGION I</b>			
<b>Pagasinan</b>	Dagupan	Sabangan ES	5 classrooms with major damages
		West CES II	6 classrooms totally damaged 6 classrooms with minor damage
	Bayambang	Bayambang CS	Cracks along the walls and floorings
		Balaybuaya ES	Cracks along the walls 2 classrooms with major damage
	Binalonan	SDO Office	Visible cracks on walls and Ceilings
	Bani	Bogtong ES	Cracks along the walls and floorings 3 classrooms with minor damage
		Abunciang ES	Cracks along the walls 2 classrooms with major damage
		Arwas ES	along the walls and floorings and pathways
		Centro Toma ES	Cracks along the walls and floorings
		Dacap Norte ES	Cracks along the walls 1 classroom with major damage
		Dacap Sur ES	3 classrooms with major damage
		Quinaoayanan ES	Cracks along the walls 4 Classrooms with major damages
		Ranom Iloco ES	Cracks along the walls 4 Classrooms with major damages
		Tugui Grande ES	Major Structural damage/ Walls 2 Totally Damaged Classrooms 3 classrooms with major damage
	Bolinao	Yabyaban ES	Cracks along the walls 1 room with major damage
		Catuday NHS	Cracks along the walls 5 classrooms with major damages
	Lingayen	Baybay ES	Wall cracks 3 classrooms with major damage
		San Jose ES	Cracks in Wall and floorings 13 classrooms with major damage
		Macaleeng ES	Cracks in Wall and floorings 2 classrooms with major damage
		Macaleeng NHS	Cracks along the walls 4 classrooms with minor damage
		ToriTori ES	Cracks along the walls 1 classroom with minor damage
		Arnedo ES	Cracks along the walls, broken glass
		Lokeb Este	Cracks along the walls
		Linmansangan ES	Cracks along the walls
		Estanza NHS	damage along the walls and Ceilings of SHS building 5 classrooms with major damages
	Manaoag	Cabanbanan NHS	Visible cracks on walls and slabs 1 classroom with major damage
	Mangatarem	Dorongan ES	3 rooms with major damages
		Tococ-Bariker ES	Cracks along the walls 2 rooms with minor damage
	San Carlos City	Baldog ES	2 classrooms totally damaged
		Central II ES	3 classrooms with minor damage
	Umingan	Prado NHS	Visible cracks on walls and slabs 1 Room with Major damage
<b>REGION III</b>			
<b>Bataan</b>	Bataan	San Jose Elementary School	Collapsed Perimeter Fence - 60 meters
	Abucay	Salian ES	3 rooms with minor damage
		Jose Abejar MES	4 rooms with minor damage
	Bagac	Banawang ES	2 rooms with minor damage
		Saysain NHS	1 room with minor damage
			1 room with major damage 1 room totally damaged
	Balanga City	Bataan People's Center Capitol Compound Balanga Center	Minor Cracks at Provincial Cooperative Development Office (PCEDO) Bataan wall
		Bataan-Pampanga Boundary Ark	Totally damage, cleared debris as of 7:32PM through consolidated efforts of DPWH, PEO, MBDA, Lubao DRRMO and PNP for fast and effective management
		Malabia Water Tank Balanga City	Minor leaks
		Robinson's Mall Balanga	Minor cracks in the wall
		Vista Mall Bataan	Minor cracks in the wall
		St.Joseph Hospital	Minor Cracks in the wall. Balanga CDRMO and safety officers conducted damage assessment to the building

REGION/PROVINCE/CITY	LOCATION	STRUCTURE	REMARKS
Bataan		Bataan General Hospital	· Minor Cracks in the wall. PEO conducted damage assement to the building
	Hermosa	Hermosa ES	· Collapsed perimeter fence about 60 meters
		Almacen ES	1 room with minor damage
		Bacong ES	2 rooms with minor damage
		Bamban ES	3 rooms with minor damage
		Casupanan ES	2 rooms with minor damage
	Mariveles	Cabcaben ES	2 rooms with minor damage
		Mariveles NHS Cab. Annex - New Alion	3 rooms with minor damage
		Mariveles NHS Malaya	7 rooms with minor damage
		Mariveles NHS Pob. Annex-Sisiman	1 room with minor damage 1 room totally damaged
		Mariveles District Hospital	· Minor Cracks in the wall. PEO conducted damage assement to the building
	Orani	Dona ES	2 rooms with minor damage
		Orani North ES	· Collapsed perimeter fence about 60 meters · 1 room with minor damage
		Orani South ES	2 rooms with minor damage
		Pag-Asa ES	Collapsed Perimter Fence 2 rooms with minor damage
		Pantalan Luma ES	Damaged Perimeter Fence 1 room with minor damage 1 room totally damaged
		Pulo ES	6 rooms with minor damage
		Sibul ES	1 room with minor damage 1 room totally damaged
		Orani District Hospital I	· Minor Cracks in the wall. PEO conducted damage assement to the building
	Orion	Calungusan ES	1 room totally damaged
		Daan Pare ES	4 rooms with minor damage 4 rooms totally damaged
		Justice E.A. Gancayco MHS	2 rooms with minor damage
		Sta. Elena ES	3 rooms with minor damage
		Sto. Domingo ES	3 rooms with minor damage
	Dinalupihan	Pagalanggang Bridge, Angeles – Porac Floridablanca – Dinalupihan Road	· Cracks on railings and wingwall, chipped off clustering. Cracking on deck expansion joint
		Angeles – Porac Floridablanca – Dinalupihan Road	· Dropped shoulder
		Luacan National High School	· Collapsed perimeter fence about 40 meters
		San Jose Elementary School	· Collapsed perimeter fence about 60 meters
		JC Payumo Memorial Hospital	· Minor hairline cracks on wall
		JC Payumo ES	Damaged Perimeter Fence
		Maligaya ES	1 room with minor damage
		Payangan ES	1 room with minor damage
		Pentor ES	2 rooms with minor damage
		Colo Elementary School	· Collapsed fence 1 room totally damaged
		Happy Valley ES	1 room with minor damage
		Pita ES	1 room with minor damage
		Sta. Lucia HS	4 rooms with major damage
		Our Lady of Lourdes (Brgy Colo)	· Cracks on wall, ceilings and beams
		Pagalanggang Dam	· Liquefaction
		Residential Fence Brgy. Sto. Niño	· Collapsed
		3-storey Residential Building	· Collapsed
		Residential house at Brgy. Dalao	· Collapsed
		Residential fence at Brgy. Kataasan	· Collapsed
	Pilar	Pilar Municipal Building	· Minor wall cracks
		Pilar Parish Church	· Minor wall cracks were noted. Small parts of the glass window were broken
		Municipal Evacuation Center	· Minor wall cracks
		Josefaville Water Tank at Barangay	· Detached brace bar of the water tank
		Electrical Post at Barangay Rizal	· Reclined electrical post
	Morong	Morong NHS	2 rooms with minor damage
		Morong NHS Annex (Mabayo)	2 rooms with minor damage
		Sampaloc ES	2 rooms with minor damage
		Morong Municipal Building	· Minor hairline cracks on wall
	Samal	Samal North ES	3 rooms with minor damage
		Samal National High School	· Minor hairline cracks on wall 6 rooms with minor damage
Bulacan		Angat HS (Binagbag NHS - Taboc NHS)	4 rooms with minor damage



REGION/PROVINCE/CITY	LOCATION	STRUCTURE	REMARKS
Bulacan	Angat	Don Pablo Amisola MS	5 rooms with minor damage 5 rooms totally damaged
		O.M. Esteban ES (Pulong Yantok ES)	2 rooms with major damage
	Balagtas (Bigaa)	Balagtas Heights ES	2 rooms with major damage
		Northville VI ES	2 rooms with minor damage
	Baliuag	Mariano Ponce NHS	8 rooms with minor damage
		Virgen Delas Flores HS	4 rooms with minor damage
	Bulacan	Bagumbayan PS	2 rooms with minor damage
		Talipit National High School	2 rooms with minor damage
		Tibig PS	1 room with minor damage
	Bustos	Tibagan ES	2 rooms totally damaged
	Calumpit	Frances NHS	2 rooms with minor damage
		Linagit PS	1 room with major damage
	Dofia Remedios Trinidad	Pulong Sampaloc ES	1 room with minor damage
	Hagonoy	Ramona S. Trillana HS (Mayor Ramon Trillana Mem. HS (Iba NHS))	1 room with minor damage
		San Pedro NHS	1 room with minor damage
		Sta. Monica ES	3 rooms with minor damage
	Marilao	Marilao CS	2 rooms with major damage
	Norzagaray	North Hills Village HS	2 rooms with minor damage
	Obando	Salambao ES	1 room with major damage
		SHS in Obando, Bulacan	1 room with minor damage
	Pandi	Bunsuran NHS	6 rooms with minor damage 3 rooms with major damage
	Pulilan	Dampol 2nd NHS	4 rooms with minor damage
	San Ildefonso	Gabihan ES	2 rooms with major damage
	San Jose del Monte	Citrus NHS	Slight damage on walls
		Gaya-gaya ES	Damage ceilings in the 4
		Lawang Pare BBC ES	Slight damage on walls
		Marangal ES	Damage on walls and columns
		Paradise Farms NHS	Crack on walls and ceiling
		San Martin BBC ES	Damage on ceiling and walls
		Caniogan Elementary School	With reported cracks
		Tibig Elementary School	1 Minor damaged comfort room; Minor cracks on building
		San Miguel NHS	Cracks on walls; Damaged ceilings
		Bagong Buhay F ES	Minor Crack on ceiling
		Francisco Homes ES	Minor cracks on stairs
		Benito Nieto ES	Minor cracks on floors and walls
		S. Palay Proper ES	Minor cracks on walls and ceiling
		Paradise Farm Community School	1 room with major damage
		San Jose Del Monte ES	Minor cracks on exterior wall and roof beam
		Sta. Cruz ES	Minor cracks on walls
		San Jose Del Monte NHS	Cracks on stairs and flooring
		San Jose Del Monte National Trade School	Detached ceiling and roof gutter
		Sapang Palay NHS	Minor cracks on walls and ceiling
		City of San Jose Del Monte NHS	Minor cracks on exterior column
		Sto. Cristo NHS	Minor cracks on floors and walls
		Kaypian NHS	cracked walls
		San Jose Del Monte Heights HS	Cracks on stairs
	San Miguel	Balaong ES	2 rooms with major damage
		Calumpang ES	2 rooms with major damage
		Partida HS (San Miguel NHS)	6 rooms with minor damage 10 rooms with major damage 10 rooms totally damaged
			Pinambaran ES
	San Rafael	Talacsan ES	2 rooms with major damage
	Santa Maria	Bagong Barrio ES (Balasing PS Annex)	2 rooms with major damage
		Cornelia M. De Jesus Memorial Central School	2 rooms with minor damage 2 rooms totally damaged
		Mag-asawang Sapa ES	2 rooms with major damage
		Manggahan ES	2 rooms with major damage
		San Vicente ES	1 room with major damage
		Tabing Bakod ES	2 rooms with major damage
	Malolos City	Malolos City High School - Bungahan	With slight cracks
		Santisima High School	With slight cracks
		Canalate Elementary School	With slight cracks
		President Corazon Cojuangco Aquino	With reported cracks
Nueva Ecija	Talugtug	Talugtug National High School	Damaged pathway; visible gap between room post and
		Caalimbangan Integrated School	Minor Cracks and damage on septic
		Calikid Norte Elementary School	Minor wall cracks
		Macatbong Elementary School	Minor cracks on the windows and door knobs of the DepEd Bldg.
		Samon Elementary School	Minor Floor cracks
		Valdefuente	Minor Ceiling Cracks
		Lazaro Francisco IS	Minor wall and flooring cracks; Minor ceiling damages; Old cracks worsen
		San Josef NHS	Minor wall and flooring cracks; Minor ceiling damages; Old cracks worsen

REGION/PROVINCE/CITY	LOCATION	STRUCTURE	REMARKS
Nueva Ecija		Samon Elementary School	Minor wall and flooring cracks; Minor ceiling damages; Old cracks worsen
		Caalibangbangan ES	Minor wall and flooring cracks; Minor ceiling damages; Old cracks worsen, 1 room with minor damage
		Macatbong Elementary School	Minor wall and flooring cracks; Minor ceiling damages; Old cracks worsen
		Calikid Norte ES	Minor wall and flooring cracks; Minor ceiling damages; Old cracks worsen
		Mayapyap NHS	Minor wall and flooring cracks; Minor ceiling damages;
		Valdefuente ES	Minor wall and flooring cracks; Minor ceiling old cracks worsen
		Balite Integrated School	Minor wall and flooring cracks; Minor ceiling old cracks worsen
		Cesar E. Vergara Memorial HS	Minor wall and flooring cracks; Minor ceiling old cracks worsen; 7 rooms with minor damage
		HCPSMSHS	Minor wall and flooring cracks; Minor ceiling old cracks worsen
		Sumacab ES	Minor wall and flooring cracks; Minor ceiling old cracks worsen
		Cabu Elementary School	Minor wall and flooring cracks; Minor ceiling old cracks worsen
		Sapang Elementary School	Minor wall and flooring cracks; Minor ceiling old cracks worsen
		San Isidro Integrated School	4 rooms with minor damage, 4 rooms totally damaged
	Gapan City	Gapan East Central School	3 rooms with minor damage
		Gapan North Central School	Minor wall cracks
		Juan R. Liwag Memorial High School	Minor cracks on the wall; 2 rooms with minor damage
		Puting Tubig Elementary School	Cracks on the wall and floor
		Mabuga ES	1 room with minor damage
		Punot ES	2 rooms with minor damage
	Science City of Muñoz	Bical ES	3 rooms with minor damage; 1 room with major damage; 4 rooms totally damaged
		Catalanacan Elementary School	cracks in the second floor
		Franza ES	3 rooms with minor damage
		Linglingay Elementary School	Minor cracks on the floor; Hairline cracks on the wall of New 2-storey building; 4 rooms with minor damage
		Maligaya ES	2 rooms with minor damage
		Mapangpang ES	2 rooms with major damage
		Munoz National HS - Main	1 room with minor damage
		Palusapis IS	2 rooms with major damage
		Ricardo Viola Adriano ES	2 rooms with major damage
		Villa Nati Elementary School	Minor cracks on walls; 3 rooms with major damage
	Nueva Ecija	Cabileo Elementary School, Cuyapo East	Minor cracks on walls
	Nueva Ecija	Caputican Elementary School, Talavera South	Cracks found on the walls
Zambales	Botolan	Botolan NHS	3 rooms with minor damage
		Danacbunga ES	3 rooms with minor damage
		Dojoc Balite IS	3 rooms with minor damage
		Panan NHS	Cracks on walls and flooring; 3 rooms with minor damage
		San Juan IS	1 totally damaged room
	Cabangan	Apo-apo ES	Cracks on walls; 4 rooms with minor damage
		Casa Tondo ES	Minor cracks
		Cabangan ES	Cracks on walls and flooring
		Cabangan National High school	Cracks on walls; 4 rooms with minor damage
	Castillejos	Hanjin Integrated School	1 room with minor damage
		San Agustin High School	Cracks on walls; Damaged ceiling; 4 rooms with minor damage
		Sta. Maria ES	6 temporary learning spaces needed; 2 rooms with minor damage; 3 rooms with major damage.
		Villaflor ES	2 rooms with minor damage
		Kanaynayan Elementary School	Cracks on walls and flooring; Broken windows
	San Marcelino	Creek Canal along Purok 3 Brgy. Burgos	Sustained minor damage
		Chiang Chio Te Mem. Aeta School (Ibad PS)	1 room with minor damage
		Judd Hendricks Mem. Aeta School	Collapsed ceiling; Broken Jalousie Blades; Cracks on walls and flooring; 3 rooms with minor damage.



REGION/PROVINCE/CITY	LOCATION	STRUCTURE	REMARKS
Zambales		Aglao ES	Collapsed perimeter fence; Cracked wall, ceiling, pathway, flooring, and school stage; and 2 damaged tanks of rain water
	San Narciso	Beddeng-Mabangcal ES	Cracks on walls; Damaged ceilings; 3 rooms with minor damage
		La Paz NHS	4 rooms with minor damage.
	Santa Cruz	Sta. Cruz North Central School	3 rooms with major damages
	Subic	Aningway-Sacatihan ES - Annex	3 temporary learning spaces needed; 3 rooms with minor damage; 7 rooms with major damage.
		Batiawan Integrated School Annex	1 room with minor damage
		Mapanao ES	2 rooms with minor damage; 1 room with major damage
		Ilwas ES	1 room with minor damage
		Subic NHS	cracks on wall and ground floor slab; Damaged ceiling joists and boards; 4 rooms with minor damage
		Subic NHS - Annex VI - Aningway-Sacatihan HS	2 temporary learning spaces needed; 2 rooms with minor damage; 2 rooms with major damage
		Subic NHS - Annex V - Ilwas HS	4 rooms with minor damage
		Subic Central School	Minor cracks on the ceiling and wall
		Subic Central Elementary School	Damaged pathways
		Pili Elementary School	Minor cracks on building walls used as kitchen and stock room; Collapsed perimeter fence
		San Miguel National High School	Major cracks/damages on walls and ceilings
		Santiago Elementary School	Visible cracks on the wall
		Sto. Tomas National High School	Minor cracks on the ceiling and wall
		Jesus F. Magsaysay Technical Vocational High School	Cracks on walls; Broken jalouise blades
		San Isidro ES	Cracks on walls
		Namatacan National High School	Cracks on walls
		San Jose - Patrocinio ES	Cracks on walls
		Arew Elementary School	Cracks on walls
		Longos ES	Cracks on walls and flooring
		Bangan-Capayawan IS	Cracks on walls
		Zambales NHS	Cracks on walls and flooring
		San Salvador HS	Cracks on walls and flooring
		Sta. Cruz South HS	Cracks on walls and flooring; Damaged ceiling
Pampanga	Angeles City	Pawnshop in Baragay San Nicolas	Collapsed
		Marquee Mall	Glass shattered
		Sunset School and a residential building at Dama de Noche St. Brgy Cutcut	Collapsed fence
		Northville 15 Integrated School	1 room with minor damage
		Apung Guidang Nepomuceno ES	Collapsed fence
		M Nepomuceno ES	Collapsed fence
		Virgen Delos Remedios ES	Minor fence cracks
		Gov. Rafael L. Lazatin IS	Minor cracks
		Amsic IS	Visible cracks on walls and ceilings 2 classrooms with minor damages
		Angeles City National Trade School	Minor wall and floor cracks
		Edilberto M. Ganzon Elementary School	visible cracks (for inspection)
		Gueco Balibago Elementary School	on the Walls of the 2
		Jose P. Dizon Elementary School	Minor wall cracks
		Marisol Bliss Elementary School	Minor wall cracks
		Pineda Gutierrez Elementary School	Minor wall cracks
		Sapangbato National High School	Minor wall cracks
		Sto. Domingo Integrated School	Minor wall and floor cracks 2 rooms ith minor damage
		Sto. Rosario Elementary	Major wall cracks in the faculty room of 2 storey Marcos Type Modified Bldg. 2 rooms totally damaged
		Angeles City Science HS-SHS	Minor wall cracks
		Angeles City Senior HS	2 classrooms with minor damage
		Bonifacio V. Romero HS	Damaged ceiling at PAGCOR Building
		Bonifacio V. Romero HS-SHS	Damaged gutter
		Cutud Elementary School	Detatched tiles on school name signage 1 classroom with major damage
		Lourdes Northwest ES	Raised flooring outside classroom
		Angeles Elementary School	Damaged waiting shed; Collapsed fence
		Claro M. Recto ICT HS	Minor wall cracks
	Apalit	E.D Lim Hospital	Cracked walls
		St. Peter the Apostle Church	Cracked walls
		Pampanga Premier Medical Center	Cracked walls
		Fausto Gonzales Sioco MS	6 rooms with minor damage
		Sto. Rosario ES	6 rooms with minor damage

REGION/PROVINCE/CITY	LOCATION	STRUCTURE	REMARKS
Pampanga	Arayat	Gatiawin ES	4 rooms with minor damage
		Lacmit ES	4 rooms with minor damage
	Bacolor	Megadike Access Roads	Closed from Dolores to Calibutbut / Maliwalo
		Municipal Hall	· Cracked walls
		Brgy. Potrero Chapel	· Cracked
		Cabalantian ES Town Proper	3 rooms with minor damage; 3 rooms totally damaged.
	Candaba	Municipal Hall	· Multiple cracked walls
	Clark	Clark International Airport	· Ceiling collapsed
			· As of 7:40 PM, 22 April 2019, flights were suspended
	Floridablanca	Consuelo Bridge along Floridablanca (2kms away from Basa Air Base)	· Damaged/Collapsed
			· Not passable to all types of vehicles
		Diosdado Macapagal Memorial High School	1 room with minor damage
		Floridablanca National Agr'l School	1 room with minor damage
		San Jose HS	2 rooms with minor damage; 5 rooms with major damage; 1 room totally damaged
	Guagua	Betis NHS	5 rooms with minor damage 5 rooms totally damaged
		Siran ES	7 rooms with minor damage
		Guagua Elementary School	· Concrete fence was partially damaged
		St. Claire Monastery	· Collapsed concrete fence
	Lubao	St. Augustine Parish Church	· Portion of the Tower or Dome collapsed
			· Authorities on-site assessing the damage
		Sto. Niño Arch	· Collapsed
		Sasmuan-Lubao Road. San Nicolas 1st, Lubao, Pampanga	Collapsed slope protection and half of the carriageway and embankment was scoured
		Bridge at San Jose Gumil	· Collapsed
		Baruya NHS	1 room with minor damage
		San Vicente ES	2 rooms with major damage; 3 rooms totally damaged
		Sta. Cruz High Integrated School	4 rooms with minor damage
		Sta. Tereza 2nd ES	2 rooms with major damage, 3 rooms with minor damage
		Sta Teresa II Integ. School	3 rooms with minor damage
		Bataan-Pampanga Boundary Arch	· Totally damage · Cleared debris
	Mabalacat	Air Force City HS	2 rooms with minor damage
		Dungan PS	2 rooms with minor damage
		Mabiga Elementary School	Collapsed perimeter fence : 5-8 meters
		Mabalacat Technical Vocational HS	Minor wall, ceiling, and window edges crack, 16 rooms with minor damage, 16 rooms totally damaged
		Mabalacat National SHS	Minor wall, ceiling, and window edges crack
		Santos Ventura High School	Minor wall, ceiling, and window edges crack
		Calumpang Elementary School	Minor wall and ceiling cracks
		Sapang Biabas Elementary School	Minor wall and ceiling cracks; 5 rooms with minor damage
		Santos Ventura Elementary School	Minor wall, ceiling, and window edges crack; 2 rooms with minor damage
		Monicayo Elementary School	Minor wall, ceiling, and window edges crack, 10 rooms with minor damage; 10 rooms totally damaged
		San Jaoquin Covered Court	· Cracked walls
		Mabalacat Elementary School	· Collapsed concrete fence
		Atlu Bola Elementary School	· Collapsed concrete fence
		Northville Elementary School	· Cracked
		Camachiles Elementary School	Minor wall, ceiling, and window edges crack
		Atlu Bola Chapel	· Cracked
		Residential house in Samsonville, Dau	· Collapsed concrete wall
		Barangay Hall in Mangalit	· Collapsed concrete wall
	Macabebe	Castuli ES	2 rooms with minor damage; 2 rooms totally damaged
		San Esteban NHS	4 rooms with minor damage
		San Gabriel ES	1 room with minor damage
		Sta. Maria CS	9 rooms with minor damage, 9 rooms totally damaged
		Tacasan ES	2 rooms with minor damage
		Telacsan NHS	2 rooms with minor damage
	Magalang	Bell tower of San Bartolome Catholic Church	· Cracked
		Brgy. Hall of Turu	· Cracked walls
		Ayala High School	· Cracked walls



REGION/PROVINCE/CITY	LOCATION	STRUCTURE	REMARKS
	Masantol	Puregold Supermarket	· Cracked walls
		Best Budget, Sta. Lucia Anac	· Cracked
		Evacuation Center in Bebe Anac	· Cracked floors
		Evacuation Center in Sagrada	· Cracked floors
	Mexico	Water tank in Brgy. San Roque	· Collapsed
		Diosdado Macapagal High School	· Collapsed
		Mexico CS	1 room with minor damage
		San Juan ES	2 temporary learning spaces needed, 2 rooms with major damage. 2 rooms totally damaged
		San Juan NHS	4 rooms with minor damage
		Brgy. Hall of San Carlos	· Cracked walls
		Sta. Monica Parish Church	· Cracked
	Minalin	Chuzon Supermarket	· Collapsed
	Porac	Megadike going to Porac	· Sink Hole
		Pio Elementary School	Collapsed Walls
		Camias ES	5 temporary learning spaces needed, 4 rooms with minor damage, 1 room with major damage, 5 totally damaged rooms
		Camias High School	· Collapsed perimeter fence 5 temporary learning spaces needed, 4 rooms with minor damage, 1 room with major damage, 5 totally damaged rooms
		Planas HS	5 temporary learning spaces needed, 5 rooms with minor damage, 5 room with major damage, 10 totally damaged rooms
		Porac Model Comm. HS (Resettlement School)	4 rooms with minor damages
		Sepung Bulaun ES	2 rooms with minor damage, 2 rooms with major damage.
	Sasmuan	Malusac Elementary School	· Collapsed wall
		Sebitanan Public Elementary School	· Collapsed wall
		Malusac High School	· Cracked beams and walls; 1 room with major damage
	Santa Ana	Fulgencio Elementary School	· Collapsed concrete wall
		San Agustin ES	5 rooms with minor damage
	Santa Rita	San Isidro ES	2 rooms with minor damage; 2 rooms with major damage
	Santo Tomas	Sapa ES	2 rooms with minor damage
	San Fernando City	Water tank in Covelandia Homes, Del Carmen	· Collapsed
		Exit of SM City	· Damaged
		Water tank of Prime at Brgy. Maimpis	· Damaged
		San Agustin School	· Collapsed wall
		Ceiling of the covered court at Northville	· Collapsed
		Sindalan Elementary School	· Damaged corridors
		San Nicolas Integrated School	· Damaged fence
		Bulaon ES	· Damaged fence
		Sto. Nino ES	· Damaged fence
		St. Vincent of Quebiawan Integrated	· Damaged fence
		Malpitic IS (Main and Annex)	· Damaged fence
		City of San Fernando West Integrated	cracks on the wall were
		ICT High School	cracks on the canteen
		Magliman Integrated School	With visible cracks (for inspection)
		Maimpis Integrated School (K-12 and	With visible cracks (for inspection)
		Malino Elementary School	With visible cracks (for inspection)
		Northville High School	With visible cracks (for inspection)
		Nuestra Senora Del Pilat Integrated	With visible cracks (for inspection)
		Pampanga High School	Cracks on the wall and floor
		Panipuan High School	With visible cracks (for inspection)
		Calulut Integrated School	With visible cracks (for inspection)
		San Fernando Elementary School	Damaged walls
		San Isidro Intergrated School	With visible cracks (for inspection)
		San Juan South Elementary School	With visible cracks (for inspection)
	San Luis	San Isidro ES	6 rooms with minor damage
		San Jose ES	1 room totally damaged
		San Jose Proper ES	5 temporary learning spaces needed; 4 rooms with major damages; 3 totally damaged rooms
		San Juan - San Luis NHS Annex (San Carlos)	1 room with minor damage
	San Simon	Dela Paz ES	1 room with minor damage; 1 room totally damaged
		San Simon HS	5 rooms with minor damage
Olongapo City	New Asinan	Firewall in Lindayag Street	· Nearly collapsed
	Kalaklan	Wall near Central Luzon College of	· Cracked
Olongapo City	New Kalalake	Wall along Jones Street	· Cracked
	Pag-asa	Walls at SM City Olongapo	· Visible cracks
	West Bajac Bajac	Wall along 24th Street near BPI Rizal	· Collapsed Wall
	West Tapinac	Wall along 14th Street	· Nearly collapsed
		Dapdap High School	Slight damage on walls;

REGION/PROVINCE/CITY	LOCATION	STRUCTURE	REMARKS
Tarlac	Bamban	San Roque National High School	Three buildings are visible for spotted cracks; 3 rooms with
		San Rafael Elementary School	Visible for spotted cracks; 1 room with minor damage
	Camiling	Malacampa ES - Main	2 temporary learning spaces needed; 2 rooms with major damage; 2 rooms totally damaged rooms
		Tambugan ES	3 rooms with minor damage
	Capas	Talaga ES	3 rooms totally damaged
	Mayantoc	Mamonit ES	2 rooms with minor damage; 2 rooms with major damage; 4 rooms totally damaged
		San Bartolome ES	6 rooms with minor damage
	Moncada	San Julian - Sta. Maria NHS	3 rooms with minor damage
		Sta. Lucia ES	9 rooms with minor damage
	Paniqui	Balaoang NHS	6 rooms with minor damage; 6 rooms totally damaged
		Burgos ES	6 rooms with major damage
	San Jose	Lawacamulag ES	1 room with minor damage; 1 room totally damaged
	Santa Ignacia	Timmaguab ES	3 rooms totally damaged
		Buenavista Elementary School	Cracks on walls of Bagong Lipunan
		Canamongan National High School	found on walls of 2x2 SHS
		Capas High School	School (24 Rooms) 4
		Cayaon Elementary School	on the wall and beam
		Eduardo Cojuangco National Vocational School	cracks found on the
		Gerona Western National High School	Cracks on walls and floor
		Matapitap Elementary School	Minor wall racks
CALABARZON			
Batangas	Batangas City	Batangas Province HS for Culture and Arts	1 room with major damage
	Calaca	Lumbang na Bata ES	2 rooms totally damaged
	Cuenca	Fermin La Rosa NHS	5 rooms with major damage; 6 totally damaged rooms
	San Nicolas	San Nicolas NHS	1 room with major damage
	Taal	Aguedo Lota Asinas Memorial ES	1 room totally damaged
		SHS within Taal Central School	2 rooms totally damaged
Rizal	Antipolo City	Cupang National HS	Cracks seen from 2nd floor to 4th floor in the building
		Antipolo NHS	2 rooms with minor damage
		Mambugan NHS	5 rooms with minor damage
		Muntindilaw ES	1 room with minor damage
		San Juan NHS	1 room with minor damage
		San Luis ES	1 room with minor damage
	Cainta	Saint Gregory ES	2 rooms with minor damage
	Rodriguez (Montalban)	Kasiglahan Village ES Unit I	3 rooms with minor damage
		Mascap ES - Magalipit Elem.	1 totally damaged room
		Tagumpay NHS	1 room with minor damage
	Tanay	Marciana P. Catolos Mem. Es	6 rooms with minor damage
	Teresa	Quiterio San Jose ES - Sitio Ibabaw Annex	1 room with minor damage
Quezon	Catnanauan	Don Abadilla ES	2 temporary learning spaces needed; 2 rooms with major damage; 4 rooms totally damaged.
	General Nakar	Gen. Nakar Central School	2 rooms with major rooms
	Lopez	Villageda ES	1 totally damaged room
	Mauban	Mauban South CES II	2 temporary learning spaces needed; 2 rooms with major damage; 4 totally damaged rooms
	Sairaya	Gov. Anacleto C. Alcala NHS	4 rooms with minor damage
Cavite	Bacoor City	Ligas II ES	7 rooms with major damage; 5 rooms totally damaged
	Amadeo	Dagatan ES	1 temporary learning spaces needed; 6 rooms with minor damage; 2 rooms with major damage
	Gen. Mariano Alvarez	Francisco De Castro ES	6 rooms with minor damage
	Naic	Naic NHS	7 rooms with major damage; 5 rooms totally damaged
	Silang	Bukal ES	1 temporary learning spaces needed; 6 rooms with minor damage; 2 rooms with major damage
	Tanza	Sta. Cruz (Bucal) ES	1 room with major damage
	Trece Martires City	Aliang ES	1 temporary learning spaces needed; 6 rooms with minor damage; 2 rooms with major damage
	Cavite City	Dalahican ES	11 rooms with minor damage
	Dasmarinas City	Paliparan II NHS	1 room with minor damage
		Sabang ES	1 room with minor damage
		San Pedro CES	Cracks on the stairs
	Bay	Maitim ES	1 room with minor damage
	Calamba City	Palo Alto ES	1 room with minor damage

REGION/PROVINCE/CITY	LOCATION	STRUCTURE	REMARKS	
Laguna	Los Baños	Bayog ES	1 room with minor damage; 1 room with major damage; 1 room totally damaged	
		Lopez Elem	1 room with minor damage; 1 room totally damaged	
	Pagsanjan	Jose A. Gallardo, Sr. ES (Magdapio ES)	1 room with minor damage	
	Pakil	Banilan ES	3 rooms with major damages	
	Santa Maria	Santa Maria ES	2 rooms with minor damage	
		Santa Maria NHS - J. Santiago Annex	2 rooms with minor damage	
		Sta. Maria NHS	5 rooms with minor damage	
		Sta. Maria NHS - Calangay Annex	1 room with minor damage	
	San Pablo City	San Cristobal NHS	1 room with minor damage	
San Marcos ES		7 temporary learning spaces needed; 2 room with minor damage; 6 rooms with major damages; 7 totally damaged rooms		
NCR				
Caloocan		Amparo ES	Reported to have seen cracks	
		Kasarinlan ES	Reported to have seen cracks 10 classrooms with minor damage	
		Kaunlaran ES	Reported to have seen cracks/ 1 room with minor damage	
		Llano ES	Reported to have seen cracks 1 Class room with minor damage	
		Bagbaguin ES	minor damage to 1 classroom	
		Caloocan National Science and Technology HS	8 classrooms with minor damage	
		Lerma ES	2 classrooms with major damage	
		Juan Felipe Helath Center	Numerous Cracks on the facilities	
		Brgy. 12 Health Center	Numerous Cracks on the facilities	
		Bagong Barrio Lying-In Clinic	Numerous Cracks on the facilities	
		Baesa Health Center	Numerous Cracks on the facilities	
		Bagong Silang Ph 8 Health Center	Numerous Cracks on the facilities	
		Amparo Health Center	Numerous Cracks on the facilities	
		Tala Health Center	Numerous Cracks on the facilities	
	Sabalo Satellite Health Center	Numerous Cracks on the facilities		
Manila	San Marcelino, UN	Emilio Aguinaldo College (EAC)	Detached façade and damaged building	
	Binondo, Sta. Cruz	Anchorage Hotel	Water Tank Spilled	
	Binondo, Sta. Cruz	Sun Tower Building	Partially collapsed	
	Ongping cor.	Anchor Land Sky Suites	Damaged	
	Ina Homes, Brgy.	Electrical Post	Leaning Posts	
		Atande Health Center	Partially damaged	
		Corazon Aquino Lying-In Clinic	Partially damaged	
		Bo Fugoso Health Center	minor cracks	
		Aurora Health Center	minor cracks	
		Lanuzza Health Center	Minor cracks	
		Tondo Foreshore Health Center	minor cracks	
		Ospital ng Sampaloc	Cracks on walls	
		Sta. Ana ES	minor damage	
		Margarita Roxas de Ayala ES	minor damage	
		NMDEO Main Building	cracks on walls	
		Senate building	cracks on walls	
		GSIS Building	cracks on walls	
	Paco	Carlos P. Garcia HS	1 classroom with major damage	
	Pandacan	Bagong Barangay ES	1 classroom with major damage 1 Classroom totally damaged	
	Sampaloc	Esteban Abada HS	5 partially damaged classrooms (Minor)	
	Santa Ana	I. Villamor HS	1 classroom with major damage	
		Mariano Marcos Memorial HS	6 classrooms with minor damage	
	Tondo	M. Roxas de Ayala ES	1 classroom with minor damage	
		P. Burgos ES	1 classroom with minor damage	
		Tondo HS	5 new building rooms with major damage, 5 old bldg rooms with minor damage	
	Malabon		Malabon ES	3 rooms with minor damage M. Blas Bldg. : For condemnation Oreta bldg: For retrofitting of gap between slab and beam
			Tañong ES I	1 totally damaged room
			Tinejeros Bridge	minor damage
		Tanza Bridge	minor cracks at railings	
		Potrero NHS	minor crack damage	
		Tinajeros ES	minor damage	
Malabon		Guillermo S. Sanchez ES	minor crack on pathway linked to bridge	
	Barangay Miramig, EDSA, Mandaluyong	GA Tower	Several fallen decorative bricks reported outside the building.	



REGION/PROVINCE/CITY	LOCATION	STRUCTURE	REMARKS
Mandaluyong		Malamig Health Center	Partially damaged
		Pleasant Hills Health Center	cracks seen on walls
		City Hall Compound	Councilor's Bldg - Cracks on edge of column, major cracks on wall and beams.
		Old Municipal Bldg.	Exterior: minor cracks on columns and walls DILG Office: Minor cracks on walls and cracks on tiles
		Barangay Operations Center	Exterior: with visible cracks; Ground Floor: minor cracks on walls
		Existing PNP, BFP, and BJMP Bldg.	minor crack failure on 2nd floor
		Project Teach building	Ground flr: Visible cracks on walls (CR Area) 2nd floor: Minor cracks on columns near window and stairs 3rd floor: visible cracks on ceiling
		Old building / Lingap	Visible cracks on walls on the ground floor
		on going construction of Mandaluyong City Medical Center	minor cracks/ hairline cracks on stairs
		Mandaluyong High School	Cracks on columns at the ground floor of Gonzales Bldg.
		Barangka Ilaya ES	cracks on 1st, 2nd and 3rd floors.
		Mandaluyong Science High School	Cracks on walls, windows, corner wall and ceiling cracks
		Hulo Elementary School	cracks on columns, beams and walls. and stiffener columns.
		Filemon Javier ES	cracks on beams, walls, stairs, column and beams and stiffener columns
		Renato Lopez ES	Cracks on the stairs, beam, and on the ceiling.
		Isaac Lopez Integrated School	Visible cracks on the walls, columns, ceiling, beams, and covered court.
		Pedro P. Cruz ES	visible cracks
		Mataas na Paaralan ng NAG	cracks on columns
		Nuebe de Pebrero ES	cracks on columns
		Ilaya Barangka	cracks on floors
		Jose Fabella ES	cracks on walls
		Mandaluyong Science High School (Senior High School Bldg.)	cracks on walls, corner walls and ceiling cracks.
		Hulo Elementary School	cracks on columns, beams and walls. and stiffener columns.
		Mandaluyong Addition Hills ES	cracks at slab, visible cracks in stair landing, cracks near classroom 410, 411, 408
		Andres Bonifacio Integrated HS	cracks on ceiling
Makati		Comembo ES	visible crack
		Guadalupe Viejo ES	Visible cracks
		Makati West HS (Makati Science HS)	Visible cracks
		Pembo ES	Cracks at plant box and CHB
		Rizal ES	Uneven level (seismic gap), visible cracks
		General Pio Del Pilar Elementary School	Cracks on the walls and patients CR
Navotas		Tanza Lying-In Clinic	Crack on the walls and patients CR
		Tanza Health Center	Partially damaged
		Tangos Health Center	Crack on the and ceiling
		NBBN Health Center	Partially damaged
		Kaunlaran Health Center	Cracks on the wall on first to fourth floor; Metal steel frame stairway ceiling on 2nd and 3rd floor are exposed; Flooring cracks on the 4th floor
		Tumana Health Center	Displaced ceiling; cracks on wall of TB DOTS
		Navotas Wellness	Major cracks on the wall especially on sanitation room
		Navotas City Hall	Minor damages on interior finishes only such as broken toilet tiles and vanity mirrors and hairline cracks on interior partition
		Navotas Annex Building	Minor cracks
		Barangay NBBS Brgy. Hall	Minor cracks on walls
		San Roque Elementary School	Cracks on flooring and PWD ramp/Electrical connection
		Daanghari elementary school	Minor cracks on walls
		Navotas polytechnic college	Cracks on 2 columns only
		Tanza elementary school	Cracks on wall and damage ceiling
		Tanza national high school	Minor damages on ceiling joints
Marikina City		Malanday NHS	Minor damage
		Marikina ES	cracks on walls
		Pamantasan ng Lungsod ng Marikina	cracks on walls
		Concepcion Integrated School	cracks on walls
		Bautista Elementary School	cracks on walls
Marikina City		Concepcion Integrated Elementary School	cracks on walls
		Parang Elementary School	cracks on walls

REGION/PROVINCE/CITY	LOCATION	STRUCTURE	REMARKS
		SSS Elementary School	cracks on beams
Muntinlupa City		Itaas Elementary School	Minor cracks (Biazon Building 2 (1st, 2nd and 4th floor), visible cracks in Biazon Building 3 (2nd Floor)
		Muntinlupa Business High School - Main	Visible surface cracks in walls
		Muntinlupa Business High School - Sucat Annex	Visible surface cracks in walls (Bonifacio Building 3rd Floor, Bonifacio Building Stairway)
		Pedro E. Diaz HS	15 classrooms with minor damages
		Sucat ES	Minor Cracks
		Muntinlupa National HS Main	Hairline cracks in CHB wall at ground floor, doors and window header.
		Poblacion Elementary School	Visible surface cracks (NHA bldg 3 room 201, 202) (New Biazon Bldg. 1, 301, 305
		Putatan Elementary School	Visible and major surface cracks (Biazon 4, 3rd flr; JRF bldg, PES covered court, Biazon 4, 4th flr)
		Laguerta health center	Cracks on dental room wall and ceiling on treatment room
		Tunasan Health center	Hairline cracks
		Putatan health center	Cracks on the side of bldg. (2 <sup>nd</sup> flr)
		Bayanan health center annex	Cracks on wall noted
		Muntinlupa City Hall	Audio visual room - Cracks noted on wall
		Annex building	Cracks on window; Procurement office - Cracks noted on wall
		Annex bldg. (5 <sup>th</sup> floor) outside EPNRO	Cracks noted
		Villa Carolina I multi-purpose hall	Hairline cracks(walls) column
		Villa Carolina I Senior citizen	Hairline cracks (wall, office)
		Villa Carolina II MPH	Hairline cracks (Walls)
		Tunasan covered court	Hairline cracks (Old)
		Muntinlupa Sport Complex	Minor cracks on walls and ceiling at bleachers
		Centennial ave (PNP)	Visible cracks due to earthquake, Major structure is damaged, repair is needed(Sidewalk
		Centennial ave (Museum)	Cracks are evident due to earthquake, repair is needed
		Plaza central	Hairline cracks at 2f wall , stairs landing area at 2F & 3F cracks at beam
		DSWD – Region 4 Calabarzon alabang	1st floor magiliw bldg. (Cracks on the wall), 2nd floor (Visible cracks on wall), 3rd floor (Visible cracks on wall near female comfort room)
		SAGIP Bldg / Red Cross Muntinlupa	Hallway and dormitory walls have notable cracks
		Bunyi compound MPH	Crack wall
		MNHS Main – Senior High School	Hairline cracks in CHB wall at ground floor, doors and window header.
		Alabang elementary School	Minor cracks on wall and beam
		Cupang Senior High school ( Pagcor Bldg	Cracks between intersection of wall – beam( newley build building)
		MNHS Senior High School	Crack on CHB headers between windows
		Sucat brgy hall	Entrance façade minor crack
		Sucat motor pool building	Rescue office minor crack above 2nd floor
		Sucat TMO	Mino crack south wall
		Sucat daycare center	Minor crack
Las Piñas		Las Piñas National High School (M Villar Bldg.)	Large Crack from 2nd floor to 3rd floor at corridor wall and flooring. Separation of wall from beam and column
		Las Piñas North High School (Deped Bldg)	Multiple major cracks at wall near stairs
		Ilaya Elementary Bagong Lipunan Bldg A	Minor cracks between two structure
		Pamplona Elementary School (PSIP Bldg.)	Minor cracks between two structure
		Pamplona Elementary School (Aquino Bldg.)	minor cracks on walls
		Pamplona Elementary School (Gen Luna Bldg.)	minor cracks on walls
		Pamplona Elementary School (Jose Rizal Bldg.)	minor cracks on walls
		Doña Manuela Elementary School (PLSB Bldg.)	minor cracks on walls
		Bernabe Health Center	minor crack
		Vergonville Elementary School	minor cracks on walls
Pasay		Doña Martha Lying-In Clinic	· Partially damaged
Pateros		Quintin de Borja Health Center	· Partially damaged
		Delfin Salonga Health Center	· Partially damaged
Paranaque City		F. Serrano Sr. ES	Visible cracks on walls
		Paranaque ES Central	Cracks in plastering wall, cracks in plastering of column
		Paranaque Science HS	Visible cracks on walls
		San Agustin ES	Cracks in plastering of wall, cracks in floor opening
		Baclaran ES - Unit 1	Cracks in plastering of wall
		Baclaran ES - Unit 2	Cracks in plastering of wall
		La Huerta ES	Cracks in plastering of wall
		Moonwalk NHS	Cracks in plastering of wall
		Paranaque ES Unit 2	Cracks in plastering of wall
		San Antonio High School	Minor cracks at Rms. 310, 305, 306, 401, 403 and the

REGION/PROVINCE/CITY	LOCATION	STRUCTURE	REMARKS
Paranaque City	Quirino Avenue, Parañaque	Out-Patient Department, Ultrasound Room, Ospital ng Parañaque (OSPAR)	Visible hairline cracks seen
		BF Health Center	Partially damaged
		Don Bosco Health Center	Partially damaged
		San Dionisio Health Center	Sustained cracks in wall s and ceiling
		Masville Health Center	Sustained cracks
		Electrical Posts Brgy San Antonio Ina Homes	Leaning posts
		BFP Parañaque Central Fire Station Building	Cracks reported
		BAHAY PAGASA/ BAHAY KALINGA	Cracks reported
		Parañaque City Jail	Visible cracks at eastside and southside façade of the building
		DFA ASEANA	Visible cracks at the ceiling of the 1st flr/ visible cracks at 2nd flr elevator area
		Sto. Niño Bridge	Damaged expansion joint, cracks on piers, weak slab, cracks on slabs
		RG Gatchalian Elementary Schools	Minor cracks, no significant structural damage
Pasig City		Dr Sixto Antonio ES	Minor cracks in the ceiling
		Nagpayong HS	Cracked floors, ceilings, walls, and beams
		De Castro ES	Cracks at ceiling and column near connector
		Eusebio HS	Cracked walls
		Oranbo ES	Minor Cracks on wall at ground floor
		Palatiw ES	BCE BLDG. w/ Minor cracks on 6 <sup>th</sup> floor
		RESPSCI	Cracked walls
		Rizal HS	Minor cracks at exterior wall VPE bldg.
		Rosario ES	Minor cracks on plastering and seismic gap
		Sagad ES	Cracked walls and floors
		San Joaquin ES	Cracked walls
		Santolan ES	Cracked beams and floors
		Santolan HS	Cracked windows
		Sta. Lucia HS	All bldgs. Are generally safe except for concrete topping. Cracks, dilapidated gutter and stair railings
		Maybunga Elementary School	Minor cracks @ 5 <sup>th</sup> Floor between column and wall
		Maybunga Elementary School – annex	Minor cracks on walls
		Decastro Elementary School	Cracks at ceiling and column near connector
		Bagong ilog Elementary School	Major and minor cracks along columns and girders
		Rosario High School	Minor cracks on plastering and seismic gap
		Caniogan Elementary School	Major cracks between beams, slab walls and columns
		Ugong high School	Minor cracks at wall and slab
		Dela paz high school	Wall cracks at 1 <sup>st</sup> -3 <sup>rd</sup> floor
		Ugong elementary school	Minor cracks between old and new bldg.
		Buting senior High School	Minor crack on walls
		Pasig city institute of science and technology	Structural members- okay. Minor cracks on plastering of CHB walls and FICEM ceiling
		Pasig Science High School	Minor cracks on wall
		Pasig City Children's Hospital	Cracks on flooring (dietary)
		Manggahan Super Health center	Minor cracks
		Santolan super health center	Minor cracks on wall
		Pasig City Hall	Bldg is safe with minor cracks
		Pasig Mega Market	Cracks found on some slab
		Pasig Mega Parking I	Minor crack under slab plaster
		Manggahan multi-purpose hall	Minor crack on walls
		Ismar Kalawaan Multipurpose hall	w/ existing cracks on plastering
		Fire Station	Existing major cracks increase at extension of 3F from slab to wall. Existing major cracks between extension and old fire station bldg. increased due to recent earthquake
		Toro building	Portion slab slightly sagged. Minor cracks at ceiling beams and connections
		Pasig Revolving Tower	Slight cracks on walls
Quezon City		Philippine Childrens Medical Center, Quezon ave. cor. Agham rd	Minor crack
		National Kidney & Transplant Inst. (NKTi) Annex Bldg. East Ave.	Minor crack; False beam outside with major crack
		National Kidney & Transplant Inst. (NKTi) Annex 2 Bldg. East Ave.	Minor crack
		National Kidney & Transplant Inst. (NKTi) Diagnostic Center, East Ave.	Cladding for further inspection
		National Children's Hospital Bldg. 1, E. Rodriguez Sr. Ave.	Hairline cracks on wall at ground floor
		National Children's Hospital Bldg. 2, E. Rodriguez Sr. Ave.	Minor cracks on slab at 6th flr.
		National Children's Hospital Bldg. 3, E. Rodriguez Sr. Ave.	Minor cracks on walls at 5th flr.



REGION/PROVINCE/CITY	LOCATION	STRUCTURE	REMARKS
Quezon City		National Children's Hospital Bldg. 4, E. Rodriguez Sr. Ave.	Minor cracks on walls at 4th, 5th and 6th flr. And exterior wall at 6th flr.
		QMMC Phase 1, 2,3,4,6,7 and 8 JP Rizal st. P-4	Visible cracks are observed
		QMMC Admin. Bldg. , JP Rizal st. P-4	Visible cracks are observed
		Lung Center NCPR Bldg., Quezon Ave.,	Minor cracks on bridgeway, for further inspection
		Lung Center B-2 Radion Therapy, Quezon Ave.,	Minor cracks
		Novaliches district Hospital	Hairline cracks on the walls at the OR/DR Complex, infirmary and pedia wards which are not remarkable
		National Electrification Administration, NIA rd., Brgy. Pinyahan	Glass wall crack at Penthouse was observed. Old horizontal wall cracks at Machine room was observed
		National Council for Disability Affairs, Doña Isidora st. Brgy. Holy Spirit	Column, Beams, stairs, and wall had minor cracks
		National Telecommunication Commision (Four storey) BIR rd. Brgy. Pinyahan	Minor cracks on slab and walls
		Sugar Regulatory Administration, North Ave. P-6	Minor cracks on column, stairs, and walls. Ceiling had minor sagging
		National Telecommunication Commision (Three storey with Basement) BIR rd. Brgy. Pinyahan	Minor cracks on column, beams and walls
		Land Registration Authority East Ave. cor NIA rd Brgy. Pinyaha	Minor cracks on connections (Ceiling to wall)
		DOJ/PAO/Parole Pardon, BIR rd. Brgy. Pinyahan	Minor cracks on column, slab, and walls. Ceiling had minor sagging
		Bureau of Internal Revenue (BIR) BIR compound, BIR rd	Walls had cracks
		Bureau of Internal Revenue (Revenue Computer Center) BIR compound, BIR rd	Walls had cracks
		House of Representative South Wing Bldg.,North Wing, IBP rd.	Interior walls, hairline cracks
		House of Representative Mitra Bldg., IBP rd.	Hairline crack interior wall 4th, 3rd and Grd.
		Department of Agriculture Agri-Business bldg., ITCAF bldg., Eliptical Rd.	Hairline crack
		Department of Agriculture New Bldg., Eliptical rd	Hairline crack
		Department of Agriculture Main (4 storey) Eliptical rd	Hairline crack
		Department of Agriculture FAPSO Bldg. (4 storey) Eliptical rd	Hairline crack at 3rd flr. Wall
		Department of Agriculture DARCO Bldg. (5 storey) Eliptical rd	Hairline crack at mid-span (2nd flr)
		Bureau of Jail Management and Penology, 144 Mindanao Ave., Bahay Toro	Beams (Existing cracks in beams hallway 3F), Slab (Tiles bulging at logistics BJMP NHQ 2F office)
		Office of Ombudsman, Agham rd. North Triangle, Diliman	Existing minor cracks on wall. During inspection
		Commission on Higher Education, HEDC. Bldg., C.P Garcia st. Diliman	Hairline cracks observed on Columns, slab tiles, stairs, and walls
		Commission on Human Rights, Saac Bldg., U.P Diliman Magsaysay Ave.	Perimeter walls and ground line at ground flr has gap approx. 10cm., hairline cracks observed on columns
		Metropolitan Waterworks and Sewerage Sytem, 489 Katipunan Rd., 1105 Balara	Hairline cracks on slab tiles
		Philippine Information Agency, P.I.A bldg., Visayas Ave. Diliman	Minor cracks on toppings of the column, minor cracks found on walls and topping of slab, major cracks was observed at some portion portion of beam, plywood ceiling at 2nd flr. Prone from falling
		Philippine Nuclear Research Institute, Central Ave., Diliman	Hairline cracks along window opening
		General luis bridge at rebisco	Damage sidewalk and railing
		Footbridge EVER Gotesco/ Holy Spirit drive, Commonwealth Ave.	Stairs have minor cracks on landing (southbound)
		Footbridge Near Riverside st.,	Stairs have cracks on landing (southbound)
		DEPEd Bldg. 2, E. Rodriguez Elementary School	Walls on 3rd flr. Have cracks
		Coseteng Bldg., Bagumbayan Elementary School	Zocall wall tilted supporting the railings
		Amlac / Bautista Bldg. Amlac Senior High School	Visible cracks on ceiling
		Balara ES	· 6 classrooms totally damaged · 5 classrooms with major damage
		Maharlika Elementary School	cracked concrete bin in one of the 3 storey bldg
		South Daang Hari Health Center	Damages and cracks

REGION/PROVINCE/CITY	LOCATION	STRUCTURE	REMARKS
Taguig		Lower Bicutan Health Center	Damages and cracks
		Upper Bicutan Health Center	Damages and cracks
		Paligong Health Center	Damages and cracks
		San Miguel Health Center	Damages and cracks
		Ibayo Health Center	Damages and cracks
		Napindan Health Center	Damages and cracks
City of San Juan		San Juan Government Center	Hairline cracks on columns at admin office, HR dept, and CSWD; Sagging of Mezanine Floor at Accounting Office
		San Juan City Bahay Pag-asa (Social Development Center)	cracks with minimum of 6mm gap from walls casusing the deformity of window frames openings at 3rd floor
		San Juan National High School (Zamora Bldg)	Visible hairline cracks on walls, beams and columns; minor cracks on stairs and floor tiles
		San Juan National High School (DEPED Bldg)	Hairline cracks on walls, beams, columns and floor cover
		San Juan National High School (JV Bldg)	Hairline cracks on walls, beams, columns and floor cover
		Kabayanan ES	Temperature cracks on the slab of second floor
		San Juan ES	Temperature cracks were located at the flooring of 2nd flr and post column at the ground floor
Valenzuela City		Arkong Bato National High School	Minor structural damage
		Polo National High School	Minor structural damage
		Polo NHS-Malanday Annex	Minor structural damage
		A. Fernando Elementary School	Minor structural damage
		Bago Lingunan NHS	Minor damage
		Bagbaguin NHS	5 classrooms with minor damages
		Bignay NHS	Minor damage
		Bitik Elementary School	Minor structural damage
		Dalandanan Elementary School	Minor structural damage
		Disiplina Village Bignay High School	Minor structural damage
		Valenzuela City Emergency Hospital	surfaced cracks
		Bignay Main Health Station	surfaced cracks
		Concepcion Health Station	surfaced cracks
		Duhad Health Station	surfaced cracks
		Northville 1 Health Station	surfaced cracks
		Sitio Cabahutan Health Station	surfaced cracks
		Linginan Health Station	surfaced cracks
		Lower Tibagan Ugong Health Station	surfaced cracks
		Karuhatan 3S Health Station	surfaced cracks
		Marulas Health Station 3S	surfaced cracks
		Bignay 3s Health Station	surfaced cracks
		GTDL 3S Health Station	surfaced cracks
		Polo Lying- In Clinic	surfaced cracks
		Balubaran Lying-In Clinic	surfaced cracks
		Marulas Lying- In Clinic	surfaced cracks

Note: Changes in figures is due to ongoing verification/validation

Sources: OCDROs III, NCR, DepEd, DOH, and DILG

## Effects of Magnitude 6.1 Earthquake in Castillejos (Zambales)

**CANCELLED FLIGHTS**

As of 1 May 2019, 6:00 AM

FLIGHT NO.	AIRLINE	ROUTE	DATE CANCELLED	DATE RESUMED	
Domestic Flights					
Z2902	AIR ASIA	CLARK-CEBU	22 April 2019	25 April 2019, 4:00 AM	
5J608 / 5J609	CEBU PACIFIC	CEBU-CLARK-CEBU		24 April 2019, 4:00 PM	
PR 2833 / PR 2834	PAL EXPRESS	CEBU-CLARK-CEBU		25 April 2019, 4:00 AM	
PR 2324	PAL EXPRESS	CAGAYAN-CLARK			
PR 2840	PAL EXPRESS	DAVAO-CLARK			
Z2901 / Z2902	AIR ASIA	CEBU-CLARK-CEBU	23 April 2019		25 April 2019, 4:00 AM
Z2 976 / Z2 975	AIR ASIA	CLARK-TACLOBAN-CLARK			
Z2922 / Z2921	AIR ASIA	CLARK-CATICLAN-CLARK			
Z2952 / Z2951	AIR ASIA	CLARK-PUERTO PRINSESA-CLARK			
Z2926 / Z2925	AIR ASIA	CLARK-CATICLAN-CLARK			
T6217 / T6210	AIR SWIFT	CLARK-EL NIDO-CLARK			
5J606 / 5J607	CEBU PACIFIC	CLARK-CEBU-CLARK		24 April 2019, 4:00 PM	
5J914 / 5J913	CEBU PACIFIC	CATICLAN-CLARK-CATICLAN		25 April 2019, 4:00 AM	
5J614 / 5J613	CEBU PACIFIC	CLARK-TAGBILARAN-CLARK			
5J986 / 5J985	CEBU PACIFIC	CLARK-DAVAO-CLARK		24 April 2019, 4:00 PM	
5J608 / 5J609	CEBU PACIFIC	CEBU-CLARK-CEBU			
PR 836 / PR 835	PAL	CLARK-CEBU-CLARK		25 April 2019, 4:00 AM	
PR 832 / PR 831	PAL	CLARK-DAVAO-CLARK			
PR 2206 / PR 2205	PAL EXPRESS	CLARK-ANTIQUE-CLARK			
PR 2685 / PR 2684	PAL EXPRESS	CLARK-BUSUANGA-CLARK			
PR 2332 / PR 2331	PAL EXPRESS	CLARK-BACOLOD-CLARK			
PR 2676 / PR 2675	PAL EXPRESS	CLARK-CATARMAN-CLARK			
PR 2697 / PR 2696	PAL EXPRESS	CLARK-BASCO-CLARK			
PR 2613 / PR 2612	PAL EXPRESS	CLARK-CUAYAN,ISABELA-CLARK			
PR 2352 / PR 2351	PAL EXPRESS	CLARK-CAGAYAN-CLARK			
PR 2679 / PR 2678	PAL EXPRESS	CLARK-BUSUANGA-CLARK			
PR 2699 / PR 2698	PAL EXPRESS	CLARK-BUSUANGA-CLARK			
PR 2689 / PR 2688	PAL EXPRESS	CLARK-BASCO-CLARK			
PR 2341 / PR 2340	PAL EXPRESS	CLARK-PUERTO PRINSESA-CLARK			
PR 2663 / PR 2662	PAL EXPRESS	CLARK-SAN VICENTE, PALAWAN-CLARK			
PR 2876 / PR 2875	PAL EXPRESS	CLARK-SIARGAO-CLARK			
PR 2872 / PR 2871	PAL EXPRESS	CLARK-TAGBILARAN-CLARK			
PR 2672 / PR 2671	PAL EXPRESS	CLARK-CALBAYOG-CLARK			
PR 2686 / PR 2687	PAL EXPRESS	CLARK-BUSUANGA-CLARK			
PR 2377 / PR 2376	PAL EXPRESS	CLARK-CATICLAN-CLARK			
PR 2692 / PR 2691	PAL EXPRESS	CLARK-BUSUANGA-CLARK			
PR 2878 / PR 2877	PAL EXPRESS	CLARK-SIARGAO-CLARK			
PR 2833 / PR 2834	PAL EXPRESS	CEBU-CLARK-CEBU	24 April 2019		24 April 2019, 4:00 PM
PR 2324 / PR 2323	PAL EXPRESS	CLARK-CAGAYAN-CLARK			
RW969 / RW968	ROYAL AIR	CATICLAN-CLARK-CATICLAN	24 April 2019	25 April 2019, 4:00 AM	
RW869 / RW868	ROYAL AIR	CLARK-PUERTO PRINSESA-CLARK			
Z2480 / Z2481	AIR ASIA	CLARK-DAVAO-CLARK			
Z2911 / Z2912	AIR ASIA	CAGAYAN-CLARK-CAGAYAN			
Z2922 / Z2921	AIR ASIA	CLARK-CATICLAN-CLARK			
Z2901 / Z2902	AIR ASIA	CEBU-CLARK-CEBU			
Z2932 / Z2931	AIR ASIA	CLARK-ILOILO-CLARK			
Z2926 / Z2925	AIR ASIA	CLARK-CATICLAN-CLARK			
T6215 / T6214	AIR SWIFT	CLARK-EL NIDO-CLARK			
T6217 / T6210	AIR SWIFT	CLARK-EL NIDO-CLARK			
5J606 / 5J607	CEBU PACIFIC	CLARK-CEBU-CLARK			
5J914 / 5J913	CEBU PACIFIC	CATICLAN-CLARK-CATICLAN			
5J614 / 5J613	CEBU PACIFIC	CLARK-TAGBILARAN-CLARK			
5J986 / 5J985	CEBU PACIFIC	CLARK-DAVAO-CLARK			
PR 836 / PR 835	PAL	CLARK-CEBU-CLARK			
PR 832 / PR 831	PAL	CLARK-DAVAO-CLARK			
PR 2936 / PR 2935	PAL EXPRESS	CLARK-VIRAC-CLARK			
PR 2685 / PR 2684	PAL EXPRESS	CLARK-BUSUANGA-CLARK			
PR 2332 / PR 2331	PAL EXPRESS	CLARK-BACOLOD-CLARK			
PR 2676 / PR 2675	PAL EXPRESS	CLARK-CATARMAN-CLARK			
PR 2697 / PR 2696	PAL EXPRESS	CLARK-BASCO-CLARK			



FLIGHT NO.	AIRLINE	ROUTE	DATE CANCELLED	DATE RESUMED
PR 2611 / PR 2610	PAL EXPRESS	CLARK-SAN JOSE, MINDORO-CLARK	24 April 2019	25 April 2019, 4:00 AM
PR 2352 / PR 2351	PAL EXPRESS	CLARK-CAGAYAN-CLARK		
PR 2679 / PR 2678	PAL EXPRESS	CLARK-BUSUANGA-CLARK		
PR 2699 / PR 2698	PAL EXPRESS	CLARK-BUSUANGA-CLARK		
PR 2689 / PR 2688	PAL EXPRESS	CLARK-BASCO-CLARK		
PR 2341 / PR 2340	PAL EXPRESS	CLARK-PUERTO PRINSESA-CLARK		
PR 2663 / PR 2662	PAL EXPRESS	CLARK-SAN VICENTE, PALAWAN-CLARK		
PR 2876 / PR 2875	PAL EXPRESS	CLARK-SIARGAO-CLARK		
PR 2615 / PR 2614	PAL EXPRESS	CLARK-TUGUEGARAO-CLARK		
PR 2872 / PR 2871	PAL EXPRESS	CLARK-TAGBILARAN-CLARK		
PR 2686 / PR 2687	PAL EXPRESS	CLARK-BUSUANGA-CLARK		
PR 2377 / PR 2376	PAL EXPRESS	CLARK-CATICLAN-CLARK		
PR 2966 / PR 2965	PAL EXPRESS	CLARK-NAGA-CLARK		
PR 2692 / PR 2691	PAL EXPRESS	CLARK-BUSUANGA-CLARK		
PR 2878 / PR 2877	PAL EXPRESS	CLARK-SIARGAO-CLARK		
PR 2833 / PR 2834	PAL EXPRESS	CEBU-CLARK-CEBU		
/ PR 2839	PAL EXPRESS	CRK-DVO-CRK		
RW969 / RW968	ROYAL AIR	CATICLAN-CLARK-CATICLAN		
RW869 / RW868	ROYAL AIR	CLARK-PUERTO PRINSESA-CLARK		
International Flights				
EK338 / EK338	CEBU PACIFIC	DUBAI-CLARK-DUBAI	22 April 2019 *diverted to Cebu*	24 April 2019, 4:00 PM
Z25127 / Z25126	AIR ASIA	CLARK-TAIPEI-CLARK	22 April 2019	24 April 2019, 4:00 PM
5J120	CEBU PACIFIC	CLARK-HONGKONG		24 April 2019, 4:00 PM
5J370	CEBU PACIFIC	CLARK-MACAU		24 April 2019, 4:00 PM
5J538	CEBU PACIFIC	CLARK-SINGAPORE		24 April 2019, 4:00 PM
3K775	JETSTAR	SINGAPORE-CLARK		24 April 2019, 4:00 PM
QR931	QATAR AIRWAYS	CLARK-DOHA		25 April 2019, 4:00 AM
TR387	SCOOT	CLARK-SINGAPORE		
Z25038	AIR ASIA	CLARK-INCHEON		
OZ707 / OZ708	ASIANA	INCHEON-CLARK-INCHEON	23 April 2019	24 April 2019, 4:00 PM
KA375 / KA376	CATHAY DRAGON	HONGKONG-CLARK-HONGKONG		
5J121 / 5J120	CEBU PACIFIC	HONGKONG-CLARK-HONGKONG		
5J371 / 5J370	CEBU PACIFIC	MACAU-CLARK-MACAU		
5J149 / 5J150	CEBU PACIFIC	CLARK-HONGKONG-CLARK		
5J538 / 5J537	CEBU PACIFIC	CLARK-SINGAPORE-CLARK		
MU5045 / MU5046	CHINA EASTERN	PUDONG-CLARK-PUDONG	23 April 2019	25 April 2019, 4:00 AM
EK338 / EK338	EMIRATES	DUBAI-CLARK-DUBAI		
7C4603 / 7C4604	JEJU AIR	INCHEON-CLARK-INCHEON		
3K776	JETSTAR	CLARK-SINGAPORE		
3K777 / 3K777	JETSTAR	SINGAPORE-CLARK-KANSAI		
3K 778 / 3K 778	JETSTAR	KANSAI-CLARK-SINGAPORE		
LJ023 / LJ024	JIN AIR	INCHEON-CLARK-INCHEON		
PR 493 / PR 492	PAL	INCHEON-CLARK-INCHEON		
QR930 / QR931	QATAR AIRWAYS	DOHA-CLARK-DOHA		
TR386 / TR387	SCOOT	SINGAPORE-CLARK-SINGAPORE		
Z25039	AIR ASIA	INCHEON-CLARK		
Z25126	AIR ASIA	CLARK-TAIPEI-CLARK		
OZ707 / OZ708	ASIANA	INCHEON-CLARK-INCHEON		
5J121 / 5J120	CEBU PACIFIC	HONGKONG-CLARK-HONGKONG		
5J371	CEBU PACIFIC	MACAU-CLARK-MACAU		
5J149 / 5J150	CEBU PACIFIC	CLARK-HONGKONG-CLARK		
5J537	CEBU PACIFIC	CLARK-SINGAPORE-SLARK		
MU5045 / MU5046	CHINA EASTERN	PUDONG-CLARK-PUDONG	24 April 2019	25 April 2019, 4:00 AM
EK338	EMIRATES	DUBAI-CLARK-DUBAI		
7C4603 / 7C4604	JEJU AIR	INCHEON-CLARK-INCHEON		
3K779 / 3K780	JETSTAR	SINGAPORE-CLARK-SINGAPORE		
LJ023 / LJ024	JIN AIR	INCHEON-CLARK-INCHEON		
PR 493 / PR 492	PAL	INCHEON-CLARK-INCHEON		
QR930 / QR931	QATAR AIRWAYS	DOHA-CLARK-DOHA		
TR386 / TR387	SCOOT	SINGAPORE-CLARK-SINGAPORE		

Source: Clark International Airport Corporation

## Effects of Magnitude 6.1 Earthquake in Castillejos (Zambales)

**SUSPENSION OF CLASSES**

As of 1 May 2019, 6:00 AM

PROVINCE / CITY / MUNICIPALITY	SCHOOLS	LEVELS	DATE OF SUSPENSION	DATE RESUMED	REMARKS
<b>REGION III</b>					
<b>Bataan</b>					
	Polytechnic University of the Philippines – Bataan		23 April 2019		
	Bataan Peninsula State University		23 April 2019	25 Apr 2019	
<b>Pampanga</b>	551 schools	All Levels	23 Apr 2019	24 Apr 2019	Public and Private Schools
Mabalacat City	55 schools	All Levels	23 April 2019	24 Apr 2019	Public and Private Schools
Angeles City	52 schools	All Levels	23 April 2019	24 Apr 2019	Public and Private Schools
<b>Zambales</b>	312 schools	All Levels	23 April 2019	24 Apr 2019	Public and Private Schools
Olongapo City	39 schools	All Levels	23 April 2019	24 Apr 2019	Public and Private Schools
<b>CALABARZON</b>					
<b>Laguna</b>	372 schools	All Levels	23 Apr 2019	24 Apr 2019	Public and Private Schools
Biñan City	37 schools	All Levels	23 Apr 2019	24 Apr 2019	Public and Private Schools
Cabuyao	28 schools	All Levels	23 April 2019	24 Apr 2019	Public and Private Schools
Calamba City	72 schools	All Levels	23 April 2019	24 Apr 2019	Public and Private Schools
San Pablo City	78 schools	All Levels	23 April 2019	24 Apr 2019	Public and Private Schools
Sta. Rosa City	28 schools	All Levels	23 April 2019	24 Apr 2019	Public and Private Schools
<b>CAR</b>					
<b>Baguio</b>					
	Saint Louis University		22 April 2019	23 April 2019	
<b>NCR</b>	All Public Schools	Elementary to Secondary	23 April 2019		Including regional office, and schools division offices.
Manila		All Levels	23 April 2019		Including all office work
	University of Santo Tomas		23 April 2019	24 Apr 2019	
	Ateneo Professional Schools		23 April 2019	24 Apr 2019	
	De La Salle University – Manila campus		23 April 2019	24 Apr 2019	
	Far Eastern University Manila		23 April 2019	24 Apr 2019	
	Far Eastern University Makati		23 April 2019	24 Apr 2019	
	Far Eastern University Diliman		23 April 2019	24 Apr 2019	
	Lyceum of the Philippines University		23 April 2019	24 Apr 2019	
	Mapua University – Makati Campus		23 April 2019	24 Apr 2019	
	Mapua University – Intramuros Campus		23 April 2019	24 Apr 2019	
	UP Diliman		23 April 2019	24 Apr 2019	
	iACADEMY		23 April 2019	24 Apr 2019	
	Roosevelt College		23 April 2019	24 Apr 2019	
	Ateneo de Manila University		23 April 2019	24 Apr 2019	
	Colegio de San Juan de Letran-Intramuros		23 April 2019	24 Apr 2019	
	College of the Holy Spirit Manila		23 April 2019	24 Apr 2019	
	Philippine Women's University		23 April 2019	24 Apr 2019	
	Polytechnic University of the Philippines All Campuses		23 April 2019	24 Apr 2019	
	MINT College Taguig		23 April 2019	24 Apr 2019	
	University of Makati		23 April 2019	24 Apr 2019	
	Unibersidad de Manila		23 April 2019		
	De La Salle University - Taguig Campus		23 April 2019	24 Apr 2019	
	University of the East - Manila		23 April 2019	24 Apr 2019	
	Emilio Aguinaldo College		23 April 2019		will resume on April 29, 2019
	University of the East - Caloocan		23 April 2019	24 Apr 2019	
Muntinlupa	Public and Private	All Levels	23 April 2019	24 Apr 2019	
Pasig City			23 April 2019	24 Apr 2019	

Sources: OCDROs CAR and NCR, #walangpasok, affected school's official social media accounts

Based on the earliest date of suspension or latest date of suspension or latest date of resumption per region

Suspension includes public schools with summer and/or make-up class, private schools and tertiary education

**Effects of Magnitude 6.1 Earthquake in Castillejos, Zambales****DISASTER RESPONSE****As of 01 May 2019, 6:00 AM****A. NATIONAL DISASTER RISK REDUCTION AND MANAGEMENT COUNCIL**

- Response assets and **1,548** Personnel from National/Regional Government Agencies, Local Government Units, and Private Sectors were deployed to conduct response operations in Region III (**TAB F**).

**1. National Disaster Risk Reduction and Management Operations Center (NDRRMOC)**

- a. The alert status was raised to BLUE at the NDRRMOC effective 22 April 2019, 7:00 PM.
- b. Issued NDRRMC Memorandum on 22 April 2019, to all concerned Chairpersons, RDRRMCs/OCD Regional Directors, directing them to raise their respective Operations Centers' alert status to continuously monitor their respective Areas of Responsibility (AOR). Likewise, NDRRMC member agencies were directed to render duty at NDRRMOC to ensure continuous coordination.
- c. Immediately disseminated Earthquake Information Nos. 1, 2, 3, and 4 to OCD Regional Offices concerned and other stakeholders through facsimile, SMS, website and twitter account for further dissemination to their respective local DRRMCs. Moreover, advised them to undertake precautionary measures and monitor the situation for any possible effects of said earthquake particularly in areas with reported intensities.
- d. Prepared the Emergency Alert and Warning Message (EAWM) for dissemination by Telecommunications Companies (TELCOs) to the affected areas.
- e. President Rodrigo Roa Duterte, together with Usec. Ricardo Jalad and House Speaker Gloria Macapagal-Arroyo, visited the affected areas in Pampanga on 23 April 2019.
- f. A briefing for the President was conducted at the Provincial Capitol of Pampanga on 23 April 2019, 6:00 PM.
- g. Response Cluster Meeting was conducted on 24 April 2019, 2:00 PM at the NDRRMC Operations Center.
- h. [Conducted Joint NDRRMC-RDRRMC III Meeting, Debriefing, Demobilization, and Recognition at Jose Songco Lapid Civil Center Gymnasium, Porac, Pampanga on 30 April 2019.](#)

**2. DOST-Philippine Institute of Volcanology and Seismology (PHIVOLCS)**

- a. Disseminated Earthquake Information Nos. 1, 2, 3, and 4.
- b. Deployed QRTs in Clark, Lubao, and Porac, Pampanga.
- c. Continuously monitoring significant earthquake activity/development.

**3. Department of Energy (DOE)**

- a. Activated Task Force on Energy Resiliency (TFER) to monitor the situation and coordinate with affected areas regarding the extent of the effects and damages to energy facilities.
- b. Ensures that all existing protocols / contingencies are carried-out by all TFER members.
- c. Implemented mitigating measures and regularly submit status of facilities/systems/areas and emerging problem that affect energy supply.



- d. Conducted emergency meeting on 23 April 2019, 10:00 AM.

#### 4. Department of Public Works and Highways (DPWH)

- a. Installed warning signs and deployed Post Disaster Assessment Team in Region III.

#### 5. Department of Interior and Local Government (DILG)

- Coordinated with Region III and NCR for report and monitoring on the situation on the ground.
- Advised all DILG offices concerned to damage assessment and structural integrity of DILG Offices and other public infrastructures.
- Advised all DILG field offices to the affected living in unengineered buildings or houses to prepare their emergency bags in view of the possible strong aftershocks within the next 24 hours.
- Linked with the Department of Energy and Municipality of Porac for immediate supply of generator sets;
- Coordinated with Department of Justice-National Bureau of Investigation and PNP Crime Laboratory for possible deployment of Disaster Victim Identification Team at the Municipality of Porac, Pampanga.

#### 6. Department of Social Welfare and Development (DSWD)

##### Status of Prepositioned Resources:

The DSWD Central Office (CO), Field Offices (FOs), and National Resource Operations Center (NROC) have stockpiles and standby funds amounting to **₱2,234,962,750.20** with breakdown as follows:

##### a. Stockpiles

A total of **357,588** Family Food Packs (FFPs) amounting to **₱143,019,742.18** and available Food and Non-food Items (FNIs) amounting to **₱760,144,532.61**.

##### b. Standby Funds

A total of **₱1,329,798,475.41** standby funds in the CO and FOs. Of the said amount, **₱1,287,360,840.16** is the available Quick Response Fund in the Central Office.

FIELD OFFICE	STANDBY FUNDS	STOCKPILES					Total STANDBY FUNDS & STOCKPILE
		Family Food Packs		Other Food Items	Non-Food Items	SUB-TOTAL (Food and NFIs)	
		Quantity	Total Cost	Total Cost	Total Cost		
TOTAL	1,329,798,475.41	357,588	143,019,742.18	169,170,597.25	590,973,935.36	760,144,532.61	2,232,962,750.20
Central Office	1,287,360,840.16	-	-	-	-	-	1,287,360,840.16
NRLMB - NROC	0.00	107,317	44,472,697.90	85,406,485.55	346,094,741.32	431,501,226.87	475,973,924.77
NRLMB - VDRC	0.00	10,100	3,636,000.00	18,463,035.38	8,382,582.50	26,845,617.88	30,481,617.88
I	3,000,752.75	7,354	2,713,497.56	2,725,567.60	42,345,070.52	45,070,638.12	50,784,888.43
II	2,477,816.92	12,046	3,904,435.44	3,657,302.00	349,519.59	4,006,821.59	10,389,073.95
III	2,484,557.00	23,363	9,056,855.66	1,123,719.70	259,588.00	1,383,307.70	12,924,720.36
CALABARZON	3,000,000.00	1,147	427,601.60	5,270,323.32	2,526,506.59	7,796,829.91	11,224,431.51
MIMAROPA	2,754,714.78	18,771	7,846,278.00	3,729,151.72	859,605.00	4,588,756.72	15,189,749.50
V	3,000,000.00	27,781	10,687,021.50	5,657,748.72	40,981,437.47	46,639,186.19	60,326,207.69
VI	400.00	14,067	5,069,056.32	7,918,784.00	4,759,451.50	12,678,235.50	17,747,691.82
VII	3,000,000.00	11,825	4,257,000.00	8,794,751.40	17,487,147.07	26,281,898.47	33,538,898.47
VIII	3,001,960.00	29,507	10,664,419.94	1,331,639.16	1,210,683.00	2,542,322.16	16,208,702.10
IX	1,395,021.35	19,789	7,124,040.00	2,425,410.00	3,793,242.65	6,218,652.65	14,737,714.00
X	3,000,000.00	23,763	15,019,960.42	5,888,133.00	98,037,638.60	103,925,771.60	121,945,732.02
XI	3,028,750.00	22,249	7,482,338.70	2,032,400.00	10,770,129.49	12,802,529.49	23,313,618.19
XII	3,000,433.00	3,254	1,304,854.00	2,103,532.67	851,017.26	2,954,549.93	7,259,836.93
CARAGA	3,000,000.00	11,585	4,224,707.70	2,664,901.30	6,355,495.95	9,020,397.25	16,245,104.95
NCR	3,292,543.50	1,147	396,537.34	3,065,438.33	928,770.00	3,994,208.33	7,683,289.17
CAR	3,000,685.95	12,523	4,732,440.10	6,912,273.40	4,981,308.85	11,893,582.25	19,626,708.30

\* Quick Response Fund (QRF) as of 25 April 2019

## **DSWD-DRMB**

- a. The Disaster Response Operations Monitoring and Information Center (DROMIC) of the DSWD-DRMB continues to closely coordinate with DSWD-FO III for significant reports on the status of affected families, assistance, and relief efforts.
- b. DSWD-RETT is on standby and ready for deployment with Emergency Communications Equipment.
- c. DSWD-CO QRT members is on standby and ready for deployment.
- d. Sent 10-Wheeler truck to Manila Water to haul 905 gallons of water going to Brgy. Camias, Porac, Pampanga.
- e. Coordinated with Philippine Disaster Relief Foundation (PDRF) to deliver 10,000 liters of water from Clark Water using Maynilad Water tanker.

## **7. Department of Health (DOH)**

- a. DOH-HEMB Operations Center coordinated with Centers for Health Development (CHD) III and NCR, Metro Manila, and Region III hospitals to gather initial reports of casualties and damaged health facilities.
- b. DOH-HEMB continuously coordinating with the ERTs deployed in Pampanga, CHD III, and NDRRMC for incident updates and any response needed.
- c. Evacuated patients to safe areas and returned as soon as it was declared safe.
- d. Deployed 1 Health Emergency Response Team (HERT) from Bataan General Hospital to do rapid assessment and provide needed medical assistance. Paulino J. Garcia Memorial Research and Medical Center is on standby to deploy additional team/s, if needed, while Jose B. Lingad Memorial General Hospital was alerted as referral hospital.
- e. Secretary Francisco T Duque III together with Director Gloria J Balboa attended the incident briefing presided by President Rodrigo R Duterte.
- f. Attended the response cluster meeting at NDRRMC on 24 April 2019.
- g. Augmented hygiene kits, jerry cans and assorted drugs and medicines worth ₱837,954.64 to CHD III on 25 April 2019.
- h. Prepositioned a total of ₱13,233,053.45 worth of logistics ready for augmentation at the CHD NCR warehouse in Pasig, Tala and Health Emergency Management Unit Office (HEMU).
- i. [Scheduled last batch of MHPSS interventions for Porac RHU personnel and Municipal Hall employees on 02 May 2019, 2:00 PM.](#)

## **8. Department of Education (DepEd)**

- a. DepEd officials and DRRMS Staff attended the situation briefing with the President in Pampanga.
- a. Disseminated memorandum for the submission of Rapid Assessment of Damaged Report (RADAR) 1 and 2.
- b. Conducted school inspection in NCR, Region III and CALABARZON.
- c. Mobilized DepEd DRRMS Staff to monitor the status of Areas of Responsibilities.
- d. Communicated with DRRM Coordinators of affected regions and division for detailed report for infrastructure and non-infrastructure damages (RADaR 1 and 2).
- e. Consolidated schools with damages.
- f. Tracked regions and divisions with class suspension.
- g. Conducted visits and damage assessment to affected schools in the Divisions of Pampanga and San Fernando City on 24 April 2019.

- h. Updated the consolidated Rapid Assessment of Damages Report (RADaR).

#### **9. BUREAU OF FIRE PROTECTION (BFP)**

- a. Conducted After Earthquake Damage Assessment to government buildings, school, and other establishments.
- b. Raised Heightened Alert and activated OPLAN PAGHALASA.
- c. Conducted Meetings with Fire Marshals to assess the damage of the earthquake.
- d. Deployed all available fire trucks, ambulances, and rescue vehicle to conduct assessment of all structures and buildings within AOR.
- e. Alerted all BFP Stations within the AOR for possible rescue and response operations.
- f. All duty personnel with their MFM conducted roving and monitoring within respective AOR.
- g. Tarlac BFP conducted fire truck visibility within AOR.

#### **10. Armed Forces of the Philippines (AFP)**

- a. Ongoing preparation of Tactical Operations Wing (TOW) Northern Luzon (NOL) to relieve PAF personnel at Porac, Pampanga.

#### **11. Metropolitan Manila Development Authority (MMDA)**

- a. Deployed 12-man team of Search and Rescue (SRR) with complete Collapsed Structure Search and Rescue (CSSR) in Region III.

#### **12. National Electrification Administration (NEA)**

- a. Advised concerned Electric Cooperatives to take the appropriate contingency measures in order to mitigate the impacts of the potential threats that may affect consumers.

#### **13. National Power Corporation (NPC)**

- a. Conducted inspection of San Roque and Angat Dams.

#### **14. National Grid Corporation of the Philippines (NGCP)**

- a. Activated 24/7 monitoring for the status of transmission facilities in Luzon.
- b. Ongoing restoration in affected transmission lines.

#### **15. Manila Electric Company (Meralco)**

- a. Dispatched 2 canter vehicles and 4 generator sets with 8 floodlights to Porac, Pampanga.

#### **16. Petron Corporation**

- a. Conducted protective tripping of some units at the refinery which resulted to eventual plant shutdown followed by the usual flaring of gases as required.

#### **17. Philippine National Railways**

- a. Dispatched explorer train (DEL 5009) with engineering personnel to inspect the tracks and bridges from Tutuban – Gov. Pascual – Calamba on 22 April 2019, 6:12 PM.
- b. Deployed trackmen to inspect structures and tracks between San Pedro-Calamba, Laguna.

- c. Resumed Train Operations on 22 April 2019, 11:00 PM, with corresponding sectional speed restriction for safe train passage.

#### **18. Philippine Red Cross**

- a. Mobilized an MHPSS Team to Porac, Pampanga. The team processed a total of thirteen (13) employees of the Chuzon Supermarket.

#### **B. Regional / Local Disaster Risk Reduction and Management Councils (R/LDRRMCs)**

**RDRRMC/OCDROs I, III, CALABARZON, CAR, and NCR** raised its alert status to closely monitor the situation and coordinate with concerned member-agencies and Local DRRMCs. Further, continuously disseminates advisories and updates to RDRRMC member-agencies, Provincial/Municipal/City DRRMCs, and local media (radio stations) through SMS and upload the same to social accounts to effectively ensure public safety.

#### **RDRRMC I**

##### **OCD I**

- a. Disseminated earthquake advisory and coordinated with Local DRRM Councils for any effects and actions taken.
- b. Raised RDRRMOC Alert Status into Blue Alert effective 22 April 2019, 7:00 PM.
- c. Quick Response Teams (QRTs) are on standby.
- d. Coordinated with NDRRMC and OCD Region III for possible augmentation.
- e. Continuous monitoring within the AOR.

#### **RDRRMC III**

##### **OCD III**

- a. Raised its alert status to BLUE effective 22 April 2019, 7:00 PM.
- b. Deployed Medical and CSSR Teams in the affected municipalities.
- c. Gathers information and validation on the effects and damages caused by 6.1 magnitude earthquake.
- d. Disseminated NDRRMC Advisories re Earthquake information to all Local Chief Executives, Local DRRM Officers, and Regional DRRMCs thru SMS, facsimile, and email for widest dissemination of information and warnings.
- e. Continuous coordination and monitoring with NDRRMC and PDRRMOs on the updates re Earthquake in Castillejos, Zambales.
- f. Conducted actual site inspection in Porac, Pampanga.
- g. Deployed Medical and CSSR Teams in the affected municipalities.
- h. Regional Director, OCD3 conducted actual site inspection at Porac, Pampanga.
- i. Established initial Regional Incident Management Team to assist in the Chuzon Supermarket Collapse incident.
- j. Regional Director, OCD III attended the situation briefing presided by President Rodrigo Roa Duterte on the effects of the Magnitude 6.1 Earthquake in Luzon at Pampanga Provincial Capitol.
- k. Coordinated with DSWD and released 700 family food packs to the affected community.
- l. Attended the IMT Operational Period Briefing on 24 April 2019.
- m. Regional Director, OCD III presided a meeting with IMT at Porac, Pampanga on 24 April 2019, 1:00 PM.
- n. Coordinated with PRO III regarding the request for transportation of family



- food packs and sleeping bags from DSWD to Porac, Pampanga.
- o. Provided fuel assistance to seven (7) vehicle units of Philippine Army.
  - p. Conducted Debris clearing operations as of 24 April 2018:
    - 525<sup>th</sup> PA (20) – 8 PM to 12 MN (25 April 2019)
    - Phelix Mining (15) – 8 PM to present
    - BFP III (20) – 12 MN (25 April 2019) 3:10 AM
    - BFP SRU (13) – 12 MN (25 April 2019) to 3:10 AM
    - PAF (30) – 3:10 AM to present
  - q. Prepositioned the following stockpiles:

Particulars	Unit	Quantity	Location
(5 Gal.) Jerry Cans	Pcs	4,000	NDRRMC-HRD Warehouse, Clark, Pampanga
Set Basin, Pail, and Dipper	Pcs	500	
Community Tent	Pcs	9	
Fold and Rest Bed	Pcs	140	
Sleeping Mat (King Size)	Pcs	500	
Blanket (double size)	Pcs	500	
Family Packs	Pcs	100	
Hygiene Kits	Pcs	50	
Disposable Masks	Pcs	200	
Chainsaw	Unit	40	
Generator Set	Unit	40	

- r. Continuous augmentation at Chuzon Supermarket, Porac, Pampanga.
- s. Conducted meeting on Debriefing/After-Action Review, and Recognition Ceremony in connection with the response operations.
- t. Conducted Leaders' Meeting in preparation for the Joint NDRRMC-RDRRMC Meeting, Debriefing, Demobilization, and Recognition.
- u. OCD III, together with Pampanga DRRMC, and MGB conducted an Aerial Inspection/Survey around the municipalities of Pampanga that have been affected by the earthquake.

### DSWD-FO III

- a. Deployed personnel on the ground to conduct validation and assessment on the current needs and possible assistance of the affected population.
- b. Continuous monitoring and coordination with the Municipal Action Team and MSWDO that were deployed in the affected areas.
- c. Established Crisis Intervention Unit in Porac, Pampanga and Child Friendly Space in affected areas.
- d. Conducted critical incidence stress debriefing / psychosocial support to 398 families of disaster victims.
- e. Deployed DRMD staff and four (4) Quick Response Team (QRT) to conduct validation to affected areas.
- f. Continues provision of medical assistance to reported injured persons in Porac and Lubao, Pampanga.
- g. Continuous validation of DRMD staff and DWSD Provincial Extension Office to affected areas in Brgys. Planas and Manibaug Pasig, Porac, Pampanga and Brgy. Nabuclod, Florida Blanca.
- h. Provided burial assistance to the fifteen (15) bereaved families amounting to ₱80,000.00.

### **DOH III**

- a. Deployed Mental Health and Psychosocial Support (MHPSS) Team composed of personnel from Mariveles Mental Hospital (MMH) and Center for Health Development (CHD) III to Porac, Pampanga. The team processed a total of fifty-three (53) employees of the Chuzon Supermarket.
- b. Activated Regional DRRM-H Emergency Operations Center.
- c. Deployed personnel to the Advance Command Post in Porac, Pampanga
- d. Mobilized ERTs from DOH-retained hospitals to aid in the response operations.
- e. Augmented 60 Cadaver Bags to the Advance Command Post in Porac.
- f. Conducted structural assessment in DOH-retained hospitals in Central Luzon.
- g. Conducted stress debriefing of demobilized responders from BFP, Army and Air Force.

### **PIA III**

- a. Disseminated timely, accurate and relevant information regarding the incident through Social Media and produced a total of eighty (82) situational reports.
- b. Provided assistance particularly media mobilization during the visit of Rodrigo R. Duterte in Porac and San Fernando City, Pampanga on 23 April 2019.

### **BFP III**

- a. All BFP Stations within the AOR were alerted for possible rescue and response operations.
- b. All duty personnel with their Municipal Fire Marshal conducted roving, monitoring, and coordination with MDRRMO, PNP, LGU, and other government agencies within their respective AOR.
- c. Conducted intensive building inspections in all establishments within the Provinces of Region III.
- d. Verified / retrieved victims in Porac and Lubao, Pampanga and currently ongoing retrieval operation.
- e. Verified possible landslide at Brgy. Nabuclod, Floridablanca.
- f. Conducted intensive building inspection throughout Pampanga.
- g. Conducted an Operation at Porac, Pampanga.
- h. Provided monitoring and clearing assistance.

### **DILG III**

- a. Activated the Operations Center.
- b. Submitted Situational Reports to DILG National Office.
- c. Assessed and inspected the DILG Regional Office 3 Building.

### **DTI III**

- a. Chuzon Supermarket, Porac Branch was severely damaged/collapsed of which, current rescue operation is ongoing with the supervision of RD Judith P Angeles.
- b. SM malls in Pampanga and Puregold Supermarkets were reportedly temporarily closed due to structural integrity inspection.
- c. Collected steel and concrete samples of the collapsed building for product standard testing.

### **DPWH III**

- a. Conducted inspection of major roads and bridges in Central Luzon.
- b. Conducted debris clearing operations in Porac, Pampanga.

**AFP (7<sup>th</sup> Infantry Division, PA)**

- a. Deployed 1 squad of 70<sup>th</sup> Infantry Battalion and provided support on the response operations in Porac, Pampanga.
- b. Deployed 48<sup>th</sup> Infantry Battalion to provide support in crowd control within the vicinity of collapsed structure in Porac, Pampanga.
- c. Provided security assistance in connection with the distribution of relief goods at Brgy. Babo Pangulo, Porac, Pampanga on 26 April 2019.
- d. Provided transportation assistance and repacking of assorted relief goods with the Operation Blessings Foundation Philippines at Pulong Santol, Porac, Pampanga on 29 April 2019, 2:30 PM.
- e. Continuous providing route security within vicinity of Landing Zone, Brgy. Cangatba, Porac, Pampanga.

**PRO III**

- a. Assembled all personnel at the evacuation area in front of the Admin Building.
- b. Activated SAR and Standby Teams.
- c. Coordinated with PPOs/CPOs on reported casualties, damages, and incidents.
- d. Coordinated with the Regional DPWH for the needed equipment.
- e. PRO3 Regional Director proceeded to the area to supervise the SRR Operation re Collapsed Building in Chuzon, Porac, Pampanga.
- f. Deployed 3 SAR Teams with 1 medical team at Chuzon, Porac, Pampanga.
- g. Coordinated with BFP Region 3 for standby Rescue Team with Ambulance.
- h. Deployed 1 SAR Team led by PCPT Duran in Porac, Pampanga.
- i. Restored power at Camp Olivas.
- j. BFP Focal person arrived at Command Post and coordinated with FC, RMFB 3 while 5 PNCOs proceeded at Chuzon, Porac, Pampanga.
- k. Philippine Army coordinated with C, RTOC regarding the deployment of personnel.

**NTC III**

- a. Activated the NTC Regional Task Force Bayanihan on 22 April 2019, 10:00 PM and has ongoing radio monitoring activities.
- b. Assigned personnel at the Emergency Operations Center (EOC), Office of Civil Defense Region 3.
- c. The following frequencies were utilized by the NTC:
  - HF Radio 7404 kHz was activated for entire NTC network
  - VHF Radio 147.500 MHz was activated for NTC R3 network only
- d. Affiliated Civic Action Groups of NTC and volunteer radio groups in the region have also been activated and were instructed to report any eventuality.
- e. In coordination with PLOT-Central Luzon through its Manager, Engr. Ernest Mendoza, NTC3 conducted Libreng Tawag and Charging Station activities in the hardest hit areas in Porac, Pampanga, Bataan, and Zambales.
- f. Continues to inquire through SMS any feedback and report from subscribers on the status of mobile signals.

**PDRRMC Aurora**

- a. PDRRMO Operations Center is on Alert and Monitoring Status.

**PDRRMC Pampanga**

- a. PDRRMO Operations Center at PEO Compound, Sindalan City of San Fernando, Pampanga was activated and prepositioned Disaster Response Equipment and Manpower on standby 24/7.
- b. Continuous monitoring and coordination with local DRRMCs on the overall situation of the 21 LGUs.
- c. PDRRMO Pampanga immediately responded with CSSR teams re collapsed Chuzon Supermarket.
- d. Pampanga Governor thru the Provincial Administrator declared the suspension of work both in public and private institutions.

#### **CDRRMC San Fernando**

- a. Conducted actual building and infrastructure inspections through the Office of the City Building Office (OCBO), City Engineering's Office (CEO) and City Disaster Risk Reduction and Management Office (CDRRMO).

#### **CDRRMC Angeles City**

- a. Conducted inspection of all bridges, public/government buildings, and schools around and within the city together with BFP, Angeles City Fire Station, and City Engineers Office for damage assessment.
- b. Supported the rescue operations in Chuzon Supermarket for three (3) days.

#### **PDRRMC Bulacan**

- a. Continuous coordination with Cities/Municipalities, PHIVOLCS-DOST, and OCD III.
- b. Continuously monitoring the situation in the province and updating concerned member-agencies, RDRRMC/OCDRO III, DILG III, media, and other partner agencies thru radio, fax, telephone, SMS, and social media.
- c. Dispatched Bulacan Rescue CSSR Team and Pulilan Rescue to Porac, Pampanga on 22 April 2019.
- d. Coordinated with Provincial General Service Office (PGSO) to conduct inspection at the Provincial Capitol Building.
- e. Coordinated with Provincial Engineering Office (PEO) to conduct inspection on the Provincial Government of Bulacan (PGB) infrastructure projects.
- f. Coordinated with Angat, Ipo, and Bustos Dam operators in assessing immediate effects and structural integrity of the dams after the earthquake.
- g. DTI Bulacan team conducted monitoring of basic and prime commodities in the province of Bulacan.
- h. LGUs conducted inspection to Government Structures and Municipal Halls.

#### **PDRRMC Bataan**

- a. Disseminated earthquake advisories from PHIVOLCS and coordinated with Local DRRMCs and PDRRMC member-agencies thru SMS and social media.
- b. Advised all DRRMOs and concerned agencies to monitor, confirm, and validate information and report on any eventuality on their respective AORs.
- c. LDRRMCs are continuously monitoring critical areas and collapsed structures/landslide within respective AORs.



- d. Coordinated with PEO and Philippine Institute of Civil Engineers (PICE) Bataan Chapter to conduct inspection of buildings particularly Bataan General Hospital, Orani District Hospital, and Mariveles District Hospital.
- e. Coordinated with CDRRMO Balanga Safety Officers to conduct building inspection at St. Joseph Hospital.
- f. Released information to media.
- g. PIA released report re Magnitude 5.7 earthquake that hit several provinces in Luzon including Bataan.
- h. BPSU President, Dr. Greg Rodis suspended classes on 23 April 2019 in all BPSU campuses in order to conduct rapid damage assessment and requiring key officials to report in all campuses.
- i. PDRRMO Bataan released updated information to DZMM interview via phone call on 22 April 2019, 10:30 PM.
- j. Conducted a meeting at PGO Bataan with Rapid Damage Assessment and Needs Analysis (RDANA) Team Bataan re Conduct of Damage Assessment particularly on various infrastructures such as schools, hospitals, dam, roads, and bridges.
- k. DPWH 1 and 2 and PEO conducted assessment on roads and bridges. Likewise, DEPED conducted assessment to schools and AFAB to Mariveles Dam.
- l. CDRRMO Balanga, MDRRMO Limay, and DRRMOs: Morong, Dinalupihan and Pilar, conducted RDANA for damage assessment to infrastructures in their AOR.

#### **PDRRMC Nueva Ecija**

- a. PDRRMO Michael DC Calma coordinated and advised all DRRMOs to be on alert status and to monitor respective AOR for any eventualities and effects of the earthquake.
- b. Disseminated Earthquake Information from DOST-PHIVOLCS to DRRMOs and PDRRMC member agencies and to the public through social media, text, and calls.
- c. Coordinated with Engr Mac Arthur Yap (PEO) on the conduct of inspection of roads and bridges.
- d. Coordinated to all municipal and city engineers to conduct massive inspection of all building structures, roads, and bridges all over Nueva Ecija.

#### **PDRRMC Zambales**

- a. In continuous coordination with the Local DRRMOs.
- b. Conducted inspection on all major roads and bridges connecting the Municipalities of Iba and Castillejos.

#### **MDRRMC Castillejos**

- a. Conducted inspection of landslide prone areas and structural integrity inspection of all public infrastructures within the municipality.

#### **MDRRMC San Antonio**

- a. Advised all the members of the BDRRMCs, BFP, PNP, and all Radio Handlers, Communication Groups to conduct damage assessment.
- b. Conducted meeting/briefing re inspection and assessment of all structures within AOR.

#### **MDRRMC Palauig**

- a. Raised the Operation Center to alert status on April 22, 2019 at 7:00 PM and continuously monitor AOR.
- b. Disseminated EQ Information via SMS, Facebook and other forms of social media for wider dissemination.

- c. Conducted infrastructure damage assessment particularly on school buildings, roads and bridges.
- d. Conducted roving and monitoring and coordination with other LGU and government agencies within AOR.

#### **MDRRMC Iba**

- a. Conducted ocular inspections of major Commercial buildings and facilities within AOR.

#### **MDRRMC BOTOLAN**

- a. Conducted roving and inspection of infrastructures, buildings and facilities for damages.

#### **MDRRMC San Marcelino**

- a. Monitored landslide incident in Mt. Tapungso, Sitio Lomibao, Brgy Buhawen.
- b. Distributed 120 relief packs in Sitio Lomibao of which, approximately 120 evacuated families already returned to their houses on 23 April 2019, 12:00 PM.
- c. Evacuated around 70-100 families from Sitios Cuartel, Cahapa and Ibad, and Brgy. Aglao due to the effect of dust proliferation in the said areas.
- d. Prepared possible evacuation site at the Aeta Market, Brgy Rabanes.
- e. Coordinated with PNP and BPATS/BPSO for provision of security in the evacuation site.

#### **CDRRMC Olongapo**

- a. Disseminated all latest Earthquake Advisory from PHIVOLCS and coordinated with the 17 BDRRMCs and member-agencies thru SMS and social media.
- b. Advised all BDRRMCs and concerned agencies to monitor, confirm, and validate information and report on any eventuality in respective AORs.
- c. Continuous monitoring of critical areas on collapsed structures/landslide within respective AOR.
- d. Coordinated with City Engineering Office to conduct full inspection of critical facilities.
- e. Coordinated with Olongapo Fire Rescue Team (OFRT) of which, 2 squads for CSSR were on standby for deployment on affected areas particularly in Porac, Pampanga.

#### **CDRRMC Tarlac**

- a. On 22 April 2019, alert level status was raised and in close coordination with LDRRMC and partner frontline government and non-government agencies.
- b. Closely monitoring the situation.
- c. Advised LDRRMCs to be on alert status and to closely monitor the situation in respective AORs in anticipation of the effects and possible aftershocks.
- d. Sent SitReps to OCD/PGO and other concerned offices/agencies thru fax, text message, social media (Yahoo mail/ Facebook) and telephone calls.
- e. Coordinated with Tarlac Police Provincial Office, TOG3 PAF, 3rd Mechanized Infantry Battalion, and 522nd Engineering Battalion for possible deployment of assets and personnel.
- f. On 23 April 2019, coordinated with the Provincial Engineering Office (PEO), Provincial General Services Office (PGSO), and Provincial Planning and Development Office (PPDO) to conduct inspection and

assessment of PGT-owned buildings such as the Provincial Capitol and Tarlac Provincial Hospital.

## **RDRRMC CALABARZON**

### **OCD CALABARZON**

- a. OCD-RDRRMC CALABARZON is continuously coordinating with RDRRMC member agencies, PDRRMOs, and LDRRMOs and advised them to monitor its respective AOR.
- b. Disseminated advisories and other information to LDRRMOs and Regional Line Agencies (RLAs).
- c. Operations Center is on Blue Alert Status effective 22 April 2019, 8:00 PM.
- d. Advised RDRRMC CALABARZON RIMT, RETT, RDANA, CSSR Teams, and responders to be on standby alert for possible augmentation to the affected areas.

### **DSWD CALABARZON**

- a. The Regional and Provincial Quick Response Team (QRT) were advised to be on standby alert status and ready to render duty should the need arises.
- b. The Regional and Provincial QRT members trained on the RDANA are on standby and ready for deployment to augment the Local Government Units (LGUs) when necessary.
- c. The QRT of the region trained on Psychosocial Support Processing (PSP) is on standby for possible deployment.

### **DPWH CALABARZON**

- a. Conducted inspection of various infrastructures thru the District Engineering Offices (DEO).
- b. Continuous monitoring/assessment on public school buildings and facilities, and national roads and bridges.

### **PDRRMC Batangas**

- a. 1 drop side rescue truck, 1 rescue boom truck, and 6 personnel are on standby.

### **PDRRMC Laguna**

- a. SRR Team with CSSR capability, 1 rescue vehicle and extrication equipment such as chipping hammer, K12, and BLS equipment are on standby.

### **PDRRMC Quezon**

- a. One service vehicle for personnel and 1 dump truck with operator are on standby.

### **PDRRMC Laguna**

- a. One rescue vehicle with spreader, cutter, and inflatable bags are on standby.

### **PDRRMC Cavite**

- a. One ambulance and 5 EMR personnel are on standby.

### **LDRRMC Biñan**

- a. Conducted inspection of 28 buildings and facilities, including schools on 23 April 2019. No structural damages were found.

## **RDRRMC CAR**

**OCD CAR**

- a. BLUE ALERT status sustained at the Cordillera Regional EOC.
- b. Coordinated and consolidated the status of Cordillera provinces thru coordination with all provincial DRRM offices after the earthquake tremor.
- c. Sent Earthquake Advisory/Information to local DRRM offices immediately following the earthquake.
- d. Continuous coordination with LDRRMCs on weather updates and preparedness measures.
- e. Continuous information dissemination in partnership with the Cordillera RDRRMC members.
- f. Continuous dissemination to the public of advisories and warning alerts to the public thru Text Blast and Social Media.
- g. Logistical support of tents to be provided for requesting agencies.

**DPWH CAR**

- a. All major roads are open to traffic except:
  - Kennon Road
  - Busa Section of Baguio- Bontoc Road

**Philippine Army - 503rd Brigade - CAR**

- a. In-close coordination with LDRRMOs and monitoring of AOR.

**Bureau of Fire Protection (BFP) CAR**

- a. Ready deployment of BFP personnel.
- b. Ambulance and responders are on-standby.

**PDRRMO Abra, Apayao, Benguet, Baguio, Ifugao, Kalinga, and Mt. Province**

- a. Updated the Regional EOC of AOR status following the earthquake.
- b. Close monitoring of AOR.
- c. Dissemination of weather advisories and earthquake information.
- d. Responders on standby.

**Metro Manila Disaster Risk Reduction and Management Council (MMDRRMC)**

- Issued MMDRRMC Memorandum No. 0422-01 re Conduct of Inspection to All Government Buildings and infrastructures within AOR.
- LGU SAR and Medical Responders are on standby for possible deployment/ augmentation to other affected regions.

**OCD NCR**

- a. Raised alert status to Blue effective 23 April 2019, 8:00 AM.
- b. Continuously monitors the situation in NCR.
- c. Continuously consolidates reports from LGUs and member agencies.
- d. Disseminates advisories and updates to MMDRRMC.
- e. Continuous monitoring of the situation in Metro Manila and maintains close coordination with concerned LDRRMCs.
- f. Deactivated the Blue Alert Level effective 8:00 AM, 24 April 2019

**DILG NCR**

- a. Issued a Memorandum for LGUs to convene the Infrastructure Audit Team relative to the MMDRRMC Memorandum issuance on inspection of government buildings and infrastructures.
- b. On 22 April 2019, the following were conducted:
  - Ensured and advised all DILG employees and own families, particularly those living in unengineered buildings or houses to prepare their emergency bags in view of the possible strong aftershocks within the next 24 hours, plan their evacuation routes, and identify the nearest open spaces to evacuate to.
  - Coordinated with the MMDRRMC and DILG-CODIX to secure updates on the actions undertaken particularly by the City/Municipal Governments in response to the effects of earthquake considering the aftershocks which may still occur within the next 24 hours.
  - Tapped the DILG Field Offices to help in the coordination with the concerned LGUs on the actions undertaken by the latter on the effects of earthquake.
- c. On 23 April 2019, the following were undertaken/recorded:
  - The Office of the President suspended work of which, all concerned personnel were instructed to maintain continuous coordination with the LGUs to monitor the situation and submit necessary reports relative to the earthquake.
  - DILG-NCR issued memorandum to DILG Field Offices, requesting them to coordinate with the LGUs and ensure the submission of inspection reports on government buildings and infrastructures within the AOR to the MMDRRMC Secretariat on or before 23 April 2019, 5:00 PM. This is in accordance to the MMDRRMC Memorandum No. 0422-01, s. 2019.
  - Issued advisory to all DILG-NCR personnel, particularly those living in unengineered buildings and houses, on the preparatory measures that shall be undertaken to ensure their and families' safety, including the self-assessment of their places of abode.
  - Requested the SRA Building Administrator and Engineers to conduct damage assessment as regards to the structural integrity of the DILG-NCR Office. Likewise, all personnel of SRA tenant-offices were directed not to enter the building until the completion of inspection/assessment.

#### **DSWD NCR**

- a. Activated the alarm system.
- b. Inspected the building after the shaking by the Engineers and Disaster Response Management Division.
- c. QRT assisted Disaster Response and Management Division in head counting in all Centers and FO-NCR.
- d. Prepared stockpile commodities and standby funds in response to any eventualities

<b>Items</b>	<b>Quantity</b>
Food Packs:	1586 boxes
	368 pieces
Non- Food Items:	
Blanket	13 pieces
Hygiene kit	1,416 boxes
Sleeping kit	885 boxes
Family kit	1,310 boxes
Family Tent	169 tents



Dignity kit	20 bags
malong	29 pieces

- e. Standby funds amounting to P 3,292,543.50.
- f. Continuous monitoring of AOR.

#### **Department of Transportation (DOTr) NCR**

- a. Unloaded passengers of LRT-1, LRT-2, and MRT-3, immediately upon the occurrence of the earthquake and subsequently suspending operations on 22 April 2019.

#### **Department of Health (DOH) NCR**

- a. Augmented manpower at CHD NCR HEMU OpCen.
- b. Coordinated with Local DRRM Officers and DRRM-H Managers regarding casualties and needs of the affected population in their respective LGUs.
- c. Disseminated IEC materials regarding earthquake preparedness.

#### **Metro Manila Center for Health Development**

- a. Continuous monitoring of Health Emergency Management Unit (HEMU)
- b. On 22 April 2019 coordinated with the LGU DRRM Health Managers to report casualties and damages.
- c. No reported casualties from LGUs: Caloocan, Valenzuela, Pasig, Pateros, Pasay, Markina, Taguig, Quezon City, Mandaluyong, Manila, Makati, San Juan, Muntinlupa, Parañaque, Las Piñas and Pasay.
- d. On 23 April 2019, MMCHD Activated to white/ normal alert.
- e. No reported casualties fro LGUs: Navotas, Malabon and Pasig.

#### **PNP NCR**

- a. Directed the PNP Director of Logistics to immediately deploy all available PNP transport vehicles consisting 4 coasters, 1 bus, and 4 trucks to assist in the transportation of stranded passengers from Cubao to Monumento and Cubao to Pasay Taft.

#### **DPWH NCR**

- a. Conducted building and bridge inspection in the cities of Metro Manila.
- b. Submitted summary of inspection report on government infrastructures.
- c. Continuous assessment of government buildings.

#### **MMDA**

- a. Deployed 2 MMDA buses and 1 Military Truck for “Libreng Sakay” to assist stranded passengers.
- b. Temporarily allowed provincial buses to load and unload passengers along EDSA in the evening of 22 April 2019.

#### **Philippine Coast Guard (PCG)**

- a. Conducted Infrastructure / Ocular Inspection on HCGDNCR-CL Bldg.

#### **Philippine Information Agency**

- a. Disseminated updates and announcements of earthquake related information to all stakeholders.
- b. Produced social media cards, press and photo releases and public service announcement to inform the public on the development and the response operations efforts of the MDRRMC.

#### **CDRRMC Manila**

- a. Deployed personnel to assess the affected areas within the City.

- b. Deployed 1<sup>st</sup> Responding Unit at Manila City Hall, SM Manila, Binondo, Sta. Cruz, Mapua, and EAC.
- c. Conducted Search and Rescue Operations at EAC.
- d. Deployed RDANA Team to gather initial report.
- e. Deployed Fire Brigades and Emergency Medical Services (EMS) and activated CDRMMC Incident Management Team (IMT).
- f. Alerted BDRRMCs to take appropriate response actions.

#### **CDRRMC Parañaque**

- a. Conducted RDANA at the City Hall and Ospital ng Parañaque (OSPAR).
- b. Continuous coordination with barangays.
- c. Activated EOC and raised alert status to Blue.
- d. Continuous coordination and monitoring.
- e. PERU SARIEMS on heightened alert.
- f. HEMS Team, Baclaran Fire and rescue volunteer and BFP Parañaque Central Fire Station are on-standby alert.
- g. City Engineering office deployed engineer for structural assessment at OSPAR and City Hall and Legislative Building.

#### **CDRRMC Quezon City**

- a. Established Incident Command Post (ICP) on 22 April 2019, 5:20 PM.
- b. Conducted check-in procedure for the possible activation of the IMT.
- c. Conducted building inspections within QC Hall Compound.
- d. Coordinated with BDRRMCs for situational update relative to the said event.

#### **CDRRMC Mandaluyong**

- a. Instructed BDRRMCs to conduct inspection within respective AORs.
- b. Placed Barangay and City responders on standby for possible deployment.
- c. Conducted inspection at City Hall Complex and other facilities.

#### **CDRRMC Marikina**

- a. Performed Earthquake protocols.
- b. Engineering Department conducted RDANA together with other safety officers in government facilities particularly in Marikina City Hall and other Government Buildings, Schools, Barangays, Health Centers, Police Stations, BFP Stations, Bridges, Hospitals, Malls, Buildings, and Condominiums.
- c. Marikina City Central Communications and Command Center is in 24/7 continuous monitoring.
- d. Raised the Alert Level to YELLOW.
- e. Dispatched all ambulances to patrol respective AORs for any possible casualties.
- f. Coordinated with Barangay, OPSS, City Electrical Engineer, City BFP, and PNP offices to conduct patrols for reconnaissance.
- g. Coordinated with City Engineering Office to conduct inspection on high rise buildings for its structural integrity and to conduct a follow thru inspection on all the facilities and critical infrastructures within the city.
- h. Coordinated with City Social Welfare and Development for child victims of the earthquake for counselling in Marquinton Residences.

#### **CDRRMC San Juan City**

- a. Mobilized SAR team to monitor possible injuries and damages.
- b. Sent SMS to Brgy Chairpersons for injury and infrastructure damage report.

- c. The City Emergency Disaster Operations Center (CEDOC) is on continuous monitoring for further updates.

#### **CDRRMC Las Piñas City**

- a. Activated evacuation protocol.
- b. Building Officials and RDANA Team led by Engineering department conducted assessment within the City.
- c. Barangays initiated evacuation protocol.

#### **CDRRMC Muntinlupa City**

- a. Deployed 11 RDANA Teams to conduct an assessment on the damages of infrastructures in Muntinlupa.
- b. Coordinated with Safety Officers and Building Administrators for the damages and casualties.
- c. Activated Emergency Operations Center.
- d. Continuously gathering information from the stakeholders.
- e. Incident Management Team (IMT) is on standby and ready for deployment.

#### **CDRRMC Malabon City**

- a. Deployed RDANA Team to conduct building inspection in Malabon City Hall.
- b. Continuous monitoring and coordination with Barangays.
- c. Activated 24/7 Emergency Operations Center.
- d. Response Teams are on alert status.

#### **CDRRMC Valenzuela City**

- a. Deployed roving ambulance for immediate transport of injured individuals to nearest hospital.
- b. Assigned medical teams on all first aid stations.
- c. Continuous monitoring of AOR.

### **A. Camp Coordination, Camp Management and IDP Protection Cluster**

#### **1. Department of Social Welfare and Development (DSWD)**

- a. Provided financial assistance for the injured and bereaved families of the dead amounting to ₱140,000.00.
- b. Deployed 27 personnel in the affected areas:
  - Five (5) personnel at the Porac Emergency Operations Center (EOC) for monitoring and coordination of response actions.
  - Five (5) personnel in all evacuation centers to monitor and address protection issues.
  - Seventeen (17) personnel in hardest hit areas to undertake needs assessment, generate data and information on affected population, damaged to shelters, etc.
- c. Prepositioned CCCM and IDP Protection-trained personnel at the DSWD-Central Office and Field Offices for possible deployment.

### **B. Health Cluster**

#### **1. Department of Health (DOH)**

CHD III conducted the following response operations:

- a. Activated Regional DRRM-H Emergency Operations Center.
- b. Close monitoring with Provincial DOH Offices.
- c. Deployed personnel to the Advance Command Post in Porac, Pampanga.
- d. Mobilized ERTs from DOH-retained hospitals to aid in the response operations.
- e. Conducted structural assessment in DOH-retained hospitals.

- f. Augmented 60 Cadaver Bags to the Advance Command Post in Porac, Pampanga.
- g. Jose B. Lingad Memorial Hospital established triage area and prepared necessary logistics and ready to receive patients.
- h. Bataan General Hospital and HEMS unit of City of San Fernando, Pampanga deployed teams to assist in the operations at Chuzon Supermarket, Porac, Pampanga.
- i. Deployed MHPSS Team and processed a total of 53 employees of Chuzon Supermarket in Porac, Pampanga.
- j. Deployed teams from Bataan General Hospital and HEMS Unit of San Fernando to assist in the SRR operations at Chuzon Supermarket, Porac, Pampanga.
- k. Conducted stress debriefing of demobilized responders from BFP, Army and Air Force.

## **2. Philippine Red Cross**

- a. Mobilized an MHPSS Team and processed a total of 13 employees of Chuzon Supermarket in Porac, Pampanga.

## **3. Philippine Disaster Resilience Foundation (PDRF)**

- a. Provided water tanks and potable water through the assistance of Manila Water Company, Inc. and Maynilad Water Services, Inc. in the affected areas.
- b. Provided wheelchairs and prosthetic support through the assistance of Makati Medical Center Foundation, and Kapampangan Development Foundation.

## **C. Emergency Telecommunications Cluster**

### **1. SMART**

- a. Provided communication support like libreng tawag (free calls), charging, and Wi-Fi stations at the Porac Public Market, Pampanga and Clark International Airport.
- b. Distributed refreshments and foldable fans at the Porac Public Market, Pampanga and Clark International Airport.

### **2. GLOBE**

- a. Deployed Communication on Wheels (COW) to further augment services in affected areas.
- b. Established and deployed “Libreng Tawag” and “Libreng Charging” Stations at the Porac Public Market, Pampanga.

## **D. Search, Rescue and Retrieval Cluster**

- a. Deployed National/Regional Government agencies, Local Government Units, PDRRMOs, and Private Sectors SRR Teams in Porac, Pampanga.
- b. Convened meeting with the barangay captains for verification of 7 listed missing persons.
- c. On-going clearing of customer passage way to verify that no civilians were trapped as of 27 April 2019.

### **1. AFP**

- a. Alerted the DRTUs of the NOLCOM, SOLCOM, JTF-NCR to be prepared in case of SRR Operations.
- b. Facilitated availability of AFP trucks and buses to be utilized for the “Libreng Sakay” in coordination with the NDRRMC and DOTr.
- c. Deployed five (5) K-9 Teams from 1BCT (Fort Mag)

- d. Deployed 4/27 PAF personnel from Basa Air Base, two (2) K-9 units from 710 SPOW and 5 personnel from 505SRG 1SRS.

**525<sup>th</sup> Engineer Combat Battalion (Philippine Army Disaster Response Unit), 51<sup>st</sup> Engineer Brigade, PA**

- a. Conducted SAR Operations at Chuzon Supermarket, Porac, Pampanga on 23 April 2019.
- b. Continuous conduct of SAR as of 24 April 2019, 8 PM.

**505<sup>th</sup> Search and Rescue Group, PAF**

- a. Deployed a total of twenty-one (21) personnel to conduct SAR operations on 25 April 2019.

**2. BFP**

- a. Activated OPLAN PAGHALASA to all affected regions, placing them on heightened alert status.
- b. Deployed 194 personnel from ORD-NCR and Region 3 with 4 ambulances, 40 fire trucks, and 1 rescue truck.
- c. A total of fourteen (14) personnel conducted retrieval operations on 25 April 2019 to recover the amputated right leg of the victim trapped at the collapsed supermarket.

**3. PCG**

- a. Deployed 2 CGK9 SAR Team on 23 April 2019 at Porac, Pampanga.

**4. PNP**

- a. PRO 3 established ICP in front of Admin Bldg., Camp Olivas, CSFP and provided 50 SAR personnel from RMFB3.
- b. Deployed 4 SAR Teams with 1 Medical Team.

**5. Leadway Construction**

- a. Conducted clearing operations at the ground zero on 25 April 2019.
-



## Effects of Magnitude 6.1 Earthquake in Castillejos (Zambales)

PERSONNEL AND ASSETS DEPLOYED

As of 01 May 2019, 06:00 AM

## NO. OF PERSONNEL DEPLOYED

(22 April 2019 - 28 April 2019)

TEAMS/AGENCIES	NO. OF PERSONNEL
<b>GRAND TOTAL</b>	<b>1,548</b>
<b>National/Regional Government Agencies</b>	<b>1008</b>
OCD	7
DSWD	28
DPWH	12
DOH	101
DOH HEMS	17
MEDICAL DOCTORS	8
DIOSDADO MEMORIAL HOSPITAL	4
HEMS SAN FERNANDO	5
MAGALANG DIST. HOSPITAL	5
PEMRU/HEMS	11
JBL	5
PHO-CAPITOL	15
DR PJGMRRTC	5
MAGALANG DIST. HOSPITAL	5
DOMINGO DIST HOSP	6
PJG Cabanatuan	10
Mariveles Mental Hospital	5
<b>BFP</b>	<b>267</b>
<b>PNP</b>	<b>157</b>
PNP (Crime Lab/Police)	138
PMFC EDD/K9 PAMPANGA	19
<b>MMDA</b>	<b>24</b>
MMDA K9 UNIT	6
MMDA K9 GROUP	4
MMDA MANILA	14
<b>DOST</b>	<b>4</b>
PHIVOLCS	4
<b>PCG</b>	<b>5</b>
COAST GUARD K9	5
<b>AFP</b>	<b>403</b>
525th ECB, PA	42
70IBC, PA	7
ALPHA UNIT 303 RRBN	17
ARMY 48th IB, 7th ID PA	96
ARMY GEN HOSPITAL, PA	28
ARMY K9. PA	14
505th SEARCH & RESCUE GROUP, PAF	12
AIR FORCE	55
AIR FORCE RESERVE	8
AIR FORCE BASA	41
AIR FORCE SPOW	0
AIR FOFRC (ARTURO ANGELES)	0
PAF BAB SAR TEAM	33
PAF	42
AIRFORCE JASB AFPRESCOM	8

<b>Local Government Units</b>	<b>158</b>
BRGY BALIBAGO KAGAWAD	4
PULILAN MDRRMO	7
BACOLOR MDRRMO	9
SFDO CDRMO	6
PDRRMO	12
PORAC MDRRMO	21
ACDRRMO	8
STA RITA MDRRMO	2
BACOLOR RESCUE	5
BULACAN PDRRMO	6
SFDO RESCUE UNIT	6
PDRRMO ILOCOS SUR	24
PDRRMO PAMP	9
PDRRMO BULACAN	8
MDRRMC-BAYAMBANG	11
OLONGAPO PDRRMO	20
<b>NGOs/Private Groups</b>	<b>382</b>
RG COMMUNITY	12
MAKATI DEVT CORP	9
MERALCO PLARIDEL	22
SCAN INC	48
ST FLORIAN FIRE DEPT	20
CONSTRUCT ENTERPRISE	5
JARTON	21
ERT LAB CARE UNITED	3
JOSE ABAD SANTOS FIRE VOLUNTEER	8
SUBIC RED CROSS	12
NHQ RED CROSS	9
RAHA PURE FORCE	14
LING NAM FIRE & RESCUE	8
SACRED HEART MEDICAL CENTER	1
DEE HWA LIONG	2
RED CROSS PAMPANGA	10
RIZ SPECT	4
MEKENI FOOD PRODUCT	14
LANTING	6
REACT PHILIPPINES	4
PROMPT CARE AMBULANCE	40
PRIVATE RESCUE TEAM	15
MERALCO	19
BACLARAN FIRE VOLUNTEER	3
CAVITE RESCUE	1
WISAR PHILIPPINES	10
SARAG RESCUE UNIT	5
SMART FOUNDATION	6
GLOBE TELECOM	1
LEADWAY CONST	9
MERALCO	8
PHIL EXCEL MINING	15
ASEP	5
CLARK WATER	4
ACCTN	9

# ASSETS DEPLOYED

ASSETS	QTY	AGENCY
Tent	7	
Backhoe	1	
Crane	4	
Tools/Rescue Equipment	1	
Jack Hammer	2	
Loader	2	
Lightings	3	
Hydraulics	2	
Service Vehicles	3	
K12	1	
Wheelchair	1	
USAR Truck	1	
Generator Set	10	
Scanner	1	
Ambulance	16	
	3	BFP
	1	MDRRMC Bacolor
	1	Prompt Care
	1	Diosdado Memorial Hospital
	1	CDRRMC Angeles City
	1	MDRRMC Sta. Rita
	1	HEMS San Fernando
	1	Red Cross Pampanga Chapter
	1	Red Cross Subic Chapter
	1	BDRRMC Balibago
	1	DOH
	1	PNP Health Service
	2	Quick Response Team
Fire Trucks	12	
	10	BFP
	1	Dee Hwa Liong
	1	Lim Nang
Trucks	4	
	1	MMDA
	1	St. Florita Fire Dept
	1	PDRRMC Bulacan
	1	Ling Nam
Rescue Trucks	9	
	1	BFP NCR
	1	MDRRMC Pulilan
	1	MMDA
	2	St. Florita Fire Dept
	1	CDRRMC Angeles City
	1	PDRRMC Bulacan
	1	Bacolor Rescue
	1	MERALCO Plaridel
K9 Units	7	
	2	PCG
	5	MMDA