



REPUBLIC OF THE PHILIPPINES  
**NATIONAL DISASTER RISK REDUCTION AND MANAGEMENT COUNCIL**

National Disaster Risk Reduction and Management Center, Camp Aguinaldo, Quezon City, Philippines

## **NDRRMC UPDATE**

### **Incident Monitored Covering the Period of 8 August 2020, 8:00 AM-08:00 PM**

**Releasing Officer:**

**(SGD.)**

**UNDERSECRETARY RICARDO B JALAD**  
Executive Director, NDRRMC and  
Administrator, OCD

**DATE: 08 August 2020**

*Source: OCD XII*

### **Initial Report on Flooding and Landslide in Alamada, North Cotabato (Region XII)**

#### **A. SITUATION OVERVIEW**

- On 4 August 2020, heavy rainfall resulted to flooding incident in Brgys. Paruayan, Mirasol, and Kitacubong; and landslide incident resulting to blocked road sections in Brgys. Paruayan and Bao all in the Municipality of Alamada, North Cotabato.

#### **B. EFFECTS**

##### **AFFECTED POPULATION**

- A total of **89 households** were affected due to the flooding incident. No evacuation reported.

<b>Location</b>	<b>No. of Households</b>	<b>Status</b>
Sitio Campo Uno, Brgy. Paruayan	10	already subsided
Purok 1 and 2 Brgy. Mirasol	9	already subsided
Purok 3, 4, 6, PNP Village Brgy. Kitacubong	70	already subsided

- A total of **25 persons** were rescued at Sitio Manglicmot and Sitio Bry. Creek, Brgy Camansi.

## STATUS OF ROADS

Location	Road Section Affected	Status
Sitio Tinago, Brgy. Paruayan	Paruayan-Bao Road section (Provincial Road)	Road cleared and passable
Sitio Busay, Brgy. Paruayan	Mahayahay-Paruayan Road	Partially Cleared
Sitio Tumindok, Brgy. Paruayan	Mahayahay – Paruayan Road	Clearing operations ongoing
Sitio Mahayahay, Brgy Paruayan	Mahayahay-Paruayan Road	Clearing operations ongoing
Upper Bao., Brgy Bao	Provincial Road going to Bao, Alamada	Road cleared and passable

### C. ACTIONS TAKEN:

#### OCD XII

Continuously monitoring the situation and in close coordination with concerned LGU.

#### PDRRMO Cotabato

Continuously monitoring the situation and in close coordination with concerned LGU.

#### MDRRMO Alamada

- RDANA Team conducted an ocular inspection/validation in the affected area.
  - Conducted emergency response and clearing operations.
-